

Part 573 Safety Recall Report

17V-830

Manufacturer Name : Newmar Corporation**Submission Date :** DEC 19, 2017**NHTSA Recall No. :** 17V-830**Manufacturer Recall No. :** NR**Manufacturer Information :****Population :**

Manufacturer Name : Newmar Corporation

Number of potentially involved : 2,915

Address : 355 North Delaware Street

Estimated percentage with defect : 100 %

PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

Vehicle Information :

Vehicle 1 : 2016-2018 Newmar Bay Star Sport

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2016-2018 Newmar Bay Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2016-2018 Newmar Canyon Star

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic

Descriptive Information : transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire.
Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 4 : 2016-2018 Newmar Ventana LE

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire.
Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 5 : 2016-2018 Newmar Dutch Star

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire.
Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 6 : 2016-2018 Newmar Essex

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire.
Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 7 : 2018-2018 Newmar New Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 8 : 2016-2018 Newmar Ventana

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 9 : 2016-2018 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 10 : 2016-2018 Newmar London Aire

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Vehicle 11 : 2016-2018 Newmar King Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

Descriptive Information : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

Production Dates : FEB 22, 2016 - OCT 09, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On certain motorhomes, there may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened. A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire. Correction: Dealers will inspect the electrical connections and perform repairs as necessary.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A loose power connection may cause a buildup of heat at the connection, increasing the risk of overheating or a fire.

Description of the Cause : There may be a loose electrical connection to the automatic transfer switch (ATS) that was not properly tightened.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : Newmar Corporation

Address : 355 N. Delaware St.
Nappanee 46550

Country : NR

Chronology :

On 12/07/2017 Newmar was made aware of a possible issue with the transfer switch. On 12/13/2017, Newmar made a decisionn there was a possible safety issue and decided to start a recall. On 12/19/2017, Newmar is giving notice to NHTSA for a recall.

Description of Remedy :

Description of Remedy Program : Dealers will inspect the electrical connections and perform repairs (torque to spec) as necessary at no cost to the customer.

How Remedy Component Differs from Recalled Component : Tightened connections in the transfer switch.

Identify How/When Recall Condition was Corrected in Production : 12/07/2017, Newmar added a 2nd torque check point for this function.

Recall Schedule :

Description of Recall Schedule : Newmar will send out customer and dealer letters on or before

Planned Dealer Notification Date : FEB 17, 2018 - FEB 17, 2018

Planned Owner Notification Date : FEB 17, 2018 - FEB 17, 2018

* NR - Not Reported