

Original Publication Date: July 20, 2017

To: All Toyota Dealer Principals, General Managers, Service Managers, and Parts Managers

Subject: Safety Recall H0M – Remedy Notice

Certain 2016 Avalon HV Certain 2016 Camry HV

Front Drive Shaft Replacement

On July 20, 2017, Toyota filed a Defect Information Report (DIR) with the National Highway Traffic Safety Administration (NHTSA) informing the agency of our intent to conduct a voluntary Safety Recall on certain 2016 model year Avalon HV vehicles and certain 2016 model year Camry HV vehicles.

Condition

The front drive shaft assembly in the involved vehicles may have been misassembled. This could cause vehicle vibration and certain components in the drive shaft assembly to separate, resulting in a loss of propulsion while driving, and the transmission not holding the vehicle when shifted into the "Park" position. A loss of propulsion while driving at higher speeds could increase the risk of a crash. Additionally, if the driver exits the vehicle without applying the parking brake, the vehicle could roll away with the transmission in "Park", increasing the risk of a crash.

<u>Remedy</u>

Any Toyota dealer will inspect the front drive shafts to determine if the vehicle is equipped with an affected part. If so, the affected drive shafts will be replaced at **NO CHARGE** to customers. For additional information on inspection and remedy procedures, refer to the technical instructions on TIS.

Covered Vehicles

There are approximately 700 vehicles covered by this Safety Recall. There are no vehicles which were distributed to Puerto Rico.

Model Name	Model Year	Approximate UIO	Production Period
Avalon HV	2016	300	Mid-January, 2016 – Early February, 2016
Camry HV	2016	400	Mid-January, 2016 – Late January, 2016

Owner Letter Mailing Date

Toyota will begin to notify owners in early August 2017.

Toyota makes significant effort to obtain current customer name and address information from each state through industry resources when mailing owner letters. In the event your dealership receives a notice for a vehicle that was sold prior to the Safety Recall announcement, it is the dealership's responsibility to forward the owner letter to the customer who purchased the vehicle.

Please note that only owners of the covered vehicles will be notified. If you are contacted by an owner who has not yet received a notification, please *verify eligibility by confirming through TIS prior to performing repairs*. Dealers should perform the repair as outlined in the Technical Instructions found on TIS.

New Vehicles in Dealership Inventory

There are approximately 4 vehicles in new dealer inventory as of July 20, 2017.



Under Title 49, Section 30112 of the United States Code, a dealer cannot sell, offer for sale, or introduce or deliver for introduction in interstate commerce a new motor vehicle when it is aware that the vehicle does not comply with an applicable Federal Motor Vehicle Safety Standard or contains a defect related to motor vehicle safety. In addition, 49 Code of Federal Regulations §577.13 requires us to provide the following advisory: It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

Vehicle Safety Recall completion should always be verified through TIS. We request your assistance to ensure involved vehicles are identified and not delivered prior to performing the remedy.

Pre-Owned Vehicles in Dealer Inventory

Toyota requests that dealers do not deliver any pre-owned vehicles in dealer inventory that are covered by a Safety Recall unless the defect has been remedied.

Toyota Certified Used Vehicle (TCUV)

The TCUV policy prohibits the certification of any vehicle with an outstanding Safety Recall, Special Service Campaign, or Limited Service Campaign. Thus, no affected units are to be designated, sold, or delivered as a TCUV until all applicable Safety Recalls, Special Service Campaigns, and Limited Service Campaigns have been completed on that vehicle.

Toyota Rent-A-Car (TRAC) & Service Loaners

Toyota requests that dealers remove all TRAC and Service Loaner vehicles from service that are covered by a Safety Recall unless the defect has been remedied.

Technician Training Requirements

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this repair are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this repair are required to currently hold at least one of the following certification levels:

- Certified Technician (Drivetrain)
- Expert Technician (Drivetrain)
- Master Technician
- Master Diagnostic Technician

Always check which technicians can perform the recall remedy by logging on to https://www.uotdealerreports.com. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

Remedy Procedures

Refer to TIS for Technical Instructions on repair. Conduct all non-completed Safety Recalls and Service Campaigns on the vehicle during the time of appointment.

Repair Quality Confirmation

The repair quality of covered vehicles is extremely important to Toyota. To help ensure that all vehicles have the repair performed correctly, please designate at least one associate (someone other than the individual who performed the repair) to verify the repair quality of every vehicle prior to customer delivery.

Parts Ordering Process - Non SET and GST Parts Ordering Process

Due to potentially limited availability, the parts may have been placed on either Manual Allocation Control (MAC) or Dealer Ordering Solutions (DOS). As the parts inventory changes, the ordering process may change. Please check the Toyota Special Activities MAC/DOS report on Dealer Daily for the most up-to-date parts ordering information.

All Safety Recall, Service Campaign (SSC/LSC) parts are eligible for the Monthly Parts Return Program. Please refer to PANT Bulletin 2011-087 for campaign parts that are currently returnable under the Monthly Parts Return Program and for additional details.

NOTE: Remedy inspection website will provide further parts ordering information, if it is determined part replacement is required.

Campaign Special Service Tools

A 2D Barcode Scanner is required to complete the remedy inspection process. These scanners have been provided to dealers as part of previous recalls. These scanners ARE NOT available through normal Toyota parts or tool channels.

Name	Sample Image
2D Barcode Scanner	

Remedy Procedure

Please refer to TIS for Technical Instructions on the inspection and repair process.


Remedy Inspection Website

The Technical Instructions will direct you to a website as part of the inspection procedure. The Remedy Inspection website will be available starting **July 20**, **2017 at 12PM PST**. For your reference, the website and default password is listed below:

https://toyota-h0m-avalon-camry.imagespm.info

Username: Dealer Code Default Password: xxxxx

Each dealer only has a single account; please ensure that the reset password is communicated to all technicians and dealer associates that will be utilizing this website.



NOTE: Toyota is currently preparing the remedy opcodes and expects to update the dealer letter with these warranty claim filing details within a week.

Claim Filing Accuracy and Correction Requests

It is the dealer's responsibility to file claims correctly for this Safety Recall. This claim filing information is used by Toyota for various government reporting activities; therefore, claim filing accuracy is crucial. If it has been identified that a claim has been filed using an incorrect opcode or a claim has been filed for an incorrect VIN, refer to Warranty Procedure Bulletin PRO17-03 to correct the claim.

Media Contacts


It is imperative that all media contacts (local and national) receive a consistent message. In this regard, all media contacts must be directed to Victor Vanov (469) 292-1318 in Toyota Corporate Communications. Please do not provide this number to customers. Please provide this contact only to media.

Customer Contacts

Customers who receive the owner letter may contact your dealership with questions regarding the letter and/or the Special Service Campaign. Please welcome them to your dealership and answer any questions that they may have. A Q&A is provided to assure a consistent message is communicated.

Customers with additional questions or concerns are asked to please contact the Toyota Customer Experience Center (1-888-270-9371) - Monday through Friday, 7:00 am to 7:00 pm, Saturday 7:00 am to 4:30 pm Central Time.

Campaign Designation Decoder



Please review this entire package with your Service and Parts staff to familiarize them with the proper stepby-step procedures required to implement this Safety Recall.

Thank you for your cooperation. TOYOTA MOTOR SALES, U.S.A., INC.



Safety Recall H0M – Remedy Notice Certain 2016 Avalon HV Certain 2016 Camry HV Front Drive Shaft Replacement

Q1: What is the condition?

A1: The front drive shaft assembly in the involved vehicles may have been misassembled. This could cause vehicle vibration and certain components in the drive shaft assembly to separate, resulting in a loss of propulsion while driving, and the transmission not holding the vehicle when shifted into the "Park" position. A loss of propulsion while driving at higher speeds could increase the risk of a crash. Additionally, if the driver exits the vehicle without applying the parking brake, the vehicle could roll away with the transmission in "Park", increasing the risk of a crash.

Q1a: Are there any warning signs that this condition occurs?

A1a: In some instances, the driver may experience noise and/or vibration while driving.

Q2: What is Toyota going to do?

A2: Toyota will send an owner notification by first class mail starting in early August, 2017, advising owners to make an appointment with their authorized Toyota dealer. The dealer will inspect and, if necessary replace the front drive shaft(s) at **NO CHARGE.**

Q3: Which and how many vehicles are covered by this Safety Recall?

A3: There are approximately 700 vehicles covered by this Safety Recall.

Model Name	Model Year	Approximate UIO	Production Period
Avalon HV	2016	300	Mid-January, 2016 – Early February, 2016
Camry HV	2016	400	Mid-January, 2016 – Late January, 2016

Q3a: Are there any other Lexus/Toyota/Scion vehicles covered by this Safety Recall in the U.S.?

A3a: No, there are no other Lexus/Toyota/Scion vehicles covered by this Safety Recall.

Q4: How long will the repair take?

A4: If the vehicle does not require driveshaft replacement, the repair will take approximately 45 minutes. If the vehicle requires driveshaft replacement, the repair will take approximately 3 hours. However, depending on the dealer's work schedule, it may be necessary to make your vehicle available for a longer period of time.

Q5: How does Toyota obtain my mailing information?

A5: Toyota uses an industry provider who works with each state's Department of Motor Vehicles (DMV) to receive registration or title information, based upon the DMV records. Please make sure your registration or title information is correct.

Q6: What if I have additional questions or concerns?

A6: If you have additional questions or concerns, please contact the Toyota Customer Experience Center at 1-888-270-9371 Monday through Friday, 7:00 am to 7:00 pm, Saturday 7:00 am to 4:30 pm Central Time.