

H009NAS1

TECHNICAL BULLETIN

20 APR 2017



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

205-05: Rear Drive Halfshafts

SUBJECT/CONCERN:

SAFETY RECALL: Rear Halfshaft Incorrectly Labelled

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:
F-PACE (X761)	2017	054429-054568	Solihull

MARKETS:**CONDITION SUMMARY:****SITUATION:**

An issue has been identified on a limited number of vehicles within the listed Affected Vehicle Range may have been fitted with the incorrect specification rear left-hand halfshaft.

ACTION:

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Workshop Procedure detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS INFORMATION **NOTE:**

Order only the expected percentage demand of parts identified.

DESCRIPTION	PART NO. /SUNDRY	QTY. /VALUE	EXPECTED % OF VEHICLES REQUIRING
-------------	---------------------	----------------	-------------------------------------

	CODE		PARTS
Halfshaft	T4A1810	1	29
Hub Nut	C2P12731	1	29
Link to Control Arm Nut	JDE12541	2	29
Link to Control Arm Bolt	C2P11385	2	29
Bolt to Upper Wishbone	T2H5903	1	29
Nut to Upper Wishbone	C2Z2224	1	29
Bolt to Wishbone Arm	T2H3774	1	29
Nut to Lower Wishbone	T2H3176	1	29
Cap Screw to Lower Wishbone	T2H3175	1	29
Oil Filler Plug	T2H13852	1	29
Oil Drain Plug	T2H13851	1	29
Differential Oil	C2P25272	1	29

WARRANTY:



NOTE:

Check DDW to ensure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, ensure that **all** outstanding Recalls and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code together with the relevant Option Code. The SRO and parts

information is included for information only. The Option Code(s) that allows for the drive in / drive out allowance can only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Refer to TOPIx to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS /SUNDRY CODE	QTY. /VALUE
H009	A	Measure rear halfshaft	47.91.20	0.2	-	-
H009	B	Measure rear halfshaft Drive in/drive out	47.91.20 10.10.10	0.2 0.2	-	-
H009	C	Measure rear halfshaft Disengage /reengage transit mode	47.91.20 86.93.93	0.2 0.1	-	-
H009	D	Measure rear halfshaft Disengage /reengage transit mode Drive in/drive out	47.91.20 86.93.93 10.10.10	0.2 0.1 0.2	-	-
H009	E	Measure & replace rear halfshaft	47.91.21	1.0	T4A1810 C2P12731 JDE12541 C2P11385 T2H5903 C2Z2224 T2H3774 T2H3176 T2H3175	1 1 2 2 1 1 1 1 1 1
			51.25.01	0.2	T2H13852	1

		Final Drive Unit - Drain and Refill			T2H13851 C2P25272	1 1
H009	F	Measure & replace rear halfshaft	47.91.21	1.0	T4A1810 C2P12731 JDE12541 C2P11385 T2H5903 C2Z2224 T2H3774 T2H3176 T2H3175	1 1 2 2 1 1 1 1 1
		Final Drive Unit - Drain and Refill	51.25.01	0.2	T2H13852 T2H13851 C2P25272	1 1 1
		Drive in/drive out	10.10.10	0.2	-	-
H009	G	Measure & replace rear halfshaft	47.91.21	1.0	T4A1810 C2P12731 JDE12541 C2P11385 T2H5903 C2Z2224 T2H3774 T2H3176 T2H3175	1 1 2 2 1 1 1 1 1
		Final Drive Unit - Drain and Refill	51.25.01	0.2	T2H13852 T2H13851 C2P25272	1 1 1
		Disengage and reengage transit mode	86.93.93	0.1	-	-
H009	H	Measure & replace rear halfshaft	47.91.21	1.0	T4A1810 C2P12731 JDE12541 C2P11385 T2H5903 C2Z2224	1 1 2 2 1 1


					T2H3774	1
					T2H3176	1
					T2H3175	1
			51.25.01	0.2	T2H13852	1
		Final Drive Unit - Drain and Refill			T2H13851	1
			86.93.93	0.1	C2P25272	1
			10.10.10	0.2	-	-
		Disengage and reengage transit mode			-	-
		Drive in/drive out				

WORKSHOP PROCEDURE:

- 1 Raise the vehicle on a ramp (see TOPIx Workshop Manual section 100-02: Jacking and Lifting).

2 NOTES:

- The measurement has a tolerance of $\pm 2\text{mm}$.
- Measure from the inner constant velocity joint boot clip to the outer constant velocity joint boot clip.



Measure the length of the rear left halfshaft as shown.

If the rear left halfshaft length is **405mm ± 2mm (")** , go to Step 5.

If the rear left halfshaft length is **375mm ± 2mm (")** , go to Step 3.

3 Replace the rear left halfshaft (see TOPIx Workshop Manual section 205-05: Rear Drive Halfshafts - Rear Halfshaft).

4 Drain and refill the rear differential (see TOPIx Workshop Manual section 205-02: Rear Drive Axle/Differential - Differential Draining and Filling).

5 Lower and release the vehicle.

