TECHNICAL INSTRUCTIONS

FOR

SAFETY (NONCOMPLIANCE) RECALL H0Z

LOAD CARRYING CAPACITY MODIFICATION LABEL


CERTAIN 2017 SIENNA AND TACOMA CERTAIN 2018 HIGHLANDER AND RAV4 CERTAIN 2017-2018 4RUNNER AND TUNDRA

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently hold <u>at least one</u> of the following certification levels:

- Certified Technician (any classification)
- Expert Technician (any classification)
- Master Technician
- Master Diagnostic Technician

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety (Noncompliance) Recall, and that it has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were completed by another dealer.

III. PREPARATION

A. PARTS

The replacement AWR labels are specific to each vehicle. For in stock units, the labels will be mailed directly to the attention of the Service Manager at the dealership. Each label will have the VIN numbers printed on them for identification. It is critical that the label be applied to the correct vehicle.

However, in some cases a replacement label will need to be ordered to accommodate the changes to the vehicle weight for dealer installed accessories. The instruction below will determine if dealer installed accessories were applied. If required a blank label can be ordered from the Material Distribution Center (MDC).

| Part Number | Part Description | Quantity |
|-------------|---|----------|
| 00107-FMVSS | Load Carrying Capacity Modification Label | 1 |

Note: Labels are sold in packs of 25 from the MDC.

IV. BACKGROUND

Due to a software programming error, the involved vehicles received load carrying capacity modification labels with incorrect information. As a result, the involved vehicles do not meet the Federal Motor Vehicle Safety Standard (FMVSS) requirements for these labels. A vehicle which is loaded beyond its load carrying capacity may have an increased risk of a crash.



V. WORK PROCEDURE



1. LOCATE THE LOAD CARRYING CAPACITY LABEL

a. The yellow load carrying capacity label will be located on the B-Pillar, inside the driver's door.



Note: The location picture on the left is an example only. The exact location will vary slightly by model.




2. IDENTIFY TYPE OF LABEL

a. Determine if the weight reduction amount on the label is <u>PRINTED</u> or <u>HANDWRITTEN</u>

<u>Handwritten:</u> Dealer installed accessories were installed, proceed to step 4.

<u>Printed:</u> Vehicle is only equipped with factory accessories, proceed to step 3.



| Division: TOYOTA | Model: Tundra | Grade: SR3 | Model Year: 2018 | | |
|---------------------------------------|---|---|---|--|--|
| Drive Type: 4WD Date of first Use: | Body Type: Crow Max Production Date: 11/30/2017 | Engine Family: Large V8 - 3UR-FE Plant Code: T - SAN ANTONIO - TMMTX | Engine No: 3UR 6323962 Transmission: 6AT | | |
| VIN: STF-DYSF1-! Dest: USA | Electronic Parts Catalog Fluids | Flat.Rate Manual Standard Equipment [+] | | | |
| Exterior Color: 01H5, CEMENT | Interior Celor: FB20, BLACK Interior Trim Celor: FB, FAB | | Interior Fabric: ", " | | |

C. Identify the dealer installed accessories and lookup the change weight in the accessories sales guide (ASG) website.

Accessory Sales Guide: https://www.toyotaasg.com/

Note:

- Login info is your dealer code and region code.
- Not all accessories installed at the dealer maybe Toyota, in these cases the ASG guide will not have the weight change value.

| O All ● Toyota ● Scion | | Products Sales M | A CONTRACTOR OF | | 20 BACK | eyword or Pa | tNo. S | serch |
|--|---|---|-----------------|------------|--------------|-----------------|---------------|-------|
| ▼ VIN Search | | s Carry-Over Report 1580-34070-58 : Bed Mat - | COLUMN TO A | Change | Inacker | | | |
| Enter VIN | | | | | | | | |
| Search | | (() T. () | Attribute | Va | lue | Parts Re | quired | |
| | 1 12 | | Bed Type | 5h | | + i Mascella | | |
| Find a Product | | | Logo | Tu | ndra | Substitu | te Parts | |
| Brand Toyota Scion | S.Com | | | | | <u>.</u> * | | |
| Model Year All Years V Select Year Range | | | | | | | | |
| Series All Toyota | | - | | | | | | |
| Model Codes | ۱ کی 😸 | | | | | | | |
| All Model Codes III | 1 | | | | | | | |
| Category Al Categores | Vehicle Applicabil | Details Specs Dis | claimers Inst | all Instr. | Inventory | | | |
| Search Reset | Showing 197 record | s for Part PT580-34070-58 | | | | | | ^ |
| | All Series V All | Years V All Model Codes | | ~ | | | | 1 |
| View Recent Searches | - | | Change | | | Labor Time | PPO Codel PP | |
| STFDYSF15JX709653 3TMD25874EM038054 2T18URHE3JC010871 | Series * Tear 0 | Model Code # | Weight | Conflicts | Requirements | PPO Water | Make | |
| | Tundox 2007 | 8270-LTD-CREWV8:2WD | 37.5 km | - 14 | - | 0.15 0.1 | CJ / \$137.00 | |
| | Tundra 2000 | \$270-L10-CREWV92WD | 37.5.8% | 24 | 4 | 0.15 0.1 | CJ / \$127.00 | |
| | Tantis 2000 | 1275-LTD-CREWVI/2WD | 37.5 Rs | 3 | 8 | · 0.1 | 9 B | ~ |
| ota Provided Label | Va | alculate the NE alues from the T ccessory chang | oyota pro | ovided | label ar | | | |
| Modifications to this encle have reduced the original load | Toyota Accessories + Dealer Accessories = New Value | | | | | | | |
| carrying capacity by | E | kample: Bed M | at and S | tep wa | as Insta | lled at | Dealers | hip |
| | | oyota Provided ealer Installed | | | | | | |
| NEW LABEL | | ealer Installed | | | | g | | |

Venicle have reduced the original load carrying capacity by

80

kg o

e. Handwrite the NEW calculated weight reduction values onto a blank label.



- f. Clean the surface of the original label with a dry cloth.
- g. Apply the new revised label for your VIN directly over the top of the original label and ensure only new label value can be read.
- h. Confirm the label is properly adhered.
- i. Dispose of the Toyota provided printed label.

◄ VERIFY REPAIR QUALITY ►

- Confirm the reduced weight value was calculated correctly for Dealer Installed Acessory vehicles.
- Confirm that the label is properly applied and covers the orignal label value
- Confirm that the label is fully adhered to the vehicle

If you have any questions regarding this update, please contact your regional representative.

10. APPENDIX

A. PARTS DISPOSAL

As required by Federal Regulations, please make sure all recalled parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, *unless requested for parts recovery return*.

B. CAMPAIGN DESIGNATION DECORDER

