17085 Electric Power Steering Connector Cable Seal Not Seated



Reference Number: N162075010 Release Date: February 2017

Revision: 00

Attention:

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

All involved vehicles that are in dealer inventory must be held and not delivered to customers, dealer traded, or used for demonstration purposes until the repair contained in this bulletin has been performed on the vehicle.

		Model Year		Model Year			
Make	Model	From	То	RPO	Description		
Buick	LaCrosse	2017	2017				

Involved vehicles are marked "open" on the Investigate Vehicle History screen in GM Global Warranty Management system. This site should always be checked to confirm vehicle involvement prior to beginning any required inspections and/or repairs.

Condition	General Motors has decided that a defect, which relates to motor vehicle safety, exists in certain 2017				
	model year Buick LaCrosse vehicles. Some of these vehicles have a condition in which the cable seal				
	on one or both of the electric power steering (EPS) connectors may not be properly seated. If the seal				
	is not properly seated on a connector, water could enter and corrode the connector, or create a high				
	resistance condition capable of melting the connector, potentially resulting in a loss of EPS. If power				
	steering assist is lost, manual steering functionality is retained but would require an increased steering				
	effort, particularly at lower speeds, increasing the risk of a crash.				
Correction	Verify the seals are fully seated and secure the seal to the affected connectors.				

Parts

Quantity	Part Name	Part No.
1	Tie Strap	Obtain Locally
As	Vinyl Electrical Tape	Obtain Locally
Required		

Warranty Information

Labor		Labor	Trans.	Net
Operation	Description	Time	Type	Item
9103007	Seat Electronic Power Steering Connector Wire Seals	0.3	ZFAT	N/A

Service Procedure

1. Open the hood and install fender covers.




4725030


17085 Electric Power Steering Connector Cable Seal Not Seated



2. Locate the electronic power steering connector (1).




- 3. Verify the wire seal is fully seated (1).
 - If the wire seal is fully seated, proceed to the next step.
 - If the wire seal is NOT fully seated (2), re-seat the wire seal with a trim tool and proceed to the next step.



- 4. Install a tie strap (1) around the wire at the base of the connector to hold the seal in the connector.
- 5. Wrap the wire and tie strap in vinyl electrical tape (2).
- 6. Remove fender covers and close hood.
- 7. Raise and support the vehicle. Refer to Lifting and Jacking the Vehicle in SI.

17085 Electric Power Steering Connector Cable Seal Not Seated





4725056

FWD



4725063

AWD

8. Locate the K43 power steering control module X1 connector.


17085 Electric Power Steering Connector Cable Seal Not Seated





4725069

- 9. Verify the yellow wire seal is fully seated (1).
 - If the yellow wire seal is fully seated, proceed to the next step.



4725079

Note: A tie strap is NOT required for this connector.

- If the yellow wire seal is NOT fully seated (2), re-seat the yellow wire seal using a long trim tool (3) and proceed to the next step.
- 10. Lower the vehicle. Refer to Lifting and Jacking the Vehicle in SI.

17085 Electric Power Steering Connector Cable Seal Not Seated



Dealer Responsibility - For USA & Export (USA States, Territories, and Possessions)

It is a violation of Federal law for a dealer to deliver a new motor vehicle or any new or used item of motor vehicle equipment (including a tire) covered by this notification under a sale or lease until the defect or noncompliance is remedied.

The US National Traffic and Motor Vehicle Safety Act provides that each vehicle that is subject to a recall of this type must be adequately repaired within a reasonable time after the customer has tendered it for repair. A failure to repair within sixty days after tender of a vehicle is prima facie evidence of failure to repair within a reasonable time. If the condition is not adequately repaired within a reasonable time, the customer may be entitled to an identical or reasonably equivalent vehicle at no charge or to a refund of the purchase price less a reasonable allowance for depreciation. To avoid having to provide these burdensome remedies, every effort must be made to promptly schedule an appointment with each customer and to repair their vehicle as soon as possible. In the recall notification letters, customers are told how to contact the US National Highway Traffic Safety Administration if the recall is not completed within a reasonable time.

Dealer Responsibility – All

All new, used, GM Certified Used, courtesy transportation vehicles, dealer shuttle vehicles, etc. in dealers' possession and subject to this recall <u>must</u> be held and inspected/repaired per the service procedure of this bulletin <u>before</u> customers take possession of these vehicles. Involved vehicles must be held and not delivered to customers, dealer-traded, released to auction, used for demonstration, or any other purpose.

All GM Certified Used vehicles currently in the dealers' inventory within the Certified Pre-Owned Inventory System (CPOIS) will be de-certified and must be held and remedied per the service procedure in this bulletin. Upon submitting an accepted/paid warranty transaction in the Global Warranty Management (GWM) system, the vehicle can be re-certified for sale within the CPOIS system, or once again be used in the CTP program.

Dealers are to service all vehicles subject to this recall at no charge to customers, regardless of mileage, age of vehicle, or ownership, from this time forward.

Customers who have recently purchased vehicles sold from your vehicle inventory, and for which there is no customer information indicated on the dealer listing, are to be contacted by the dealer. Arrangements are to be made to make the required correction according to the instructions contained in this bulletin. Recall follow-up cards should not be used for this purpose, since the customer may not as yet have received the notification letter.

In summary, whenever a vehicle subject to this recall enters your vehicle inventory, or is in your dealership for service in the future, you must take the steps necessary to be sure the recall correction has been made before selling or releasing the vehicle.

Dealer Reports

For dealers with involved vehicles, a listing with involved vehicles has been prepared and will be provided to U.S. and Canadian dealers through the GM GlobalConnect Recall Reports, or sent directly to export dealers. The listing may contain customer names and addresses obtained from Motor Vehicle Registration Records. The use of such motor vehicle registration data for any purpose other than follow-up necessary to complete this recall is a violation of law in several states/provinces/countries. Accordingly, you are urged to limit the use of this report to the follow-up necessary to complete this recall.

Courtesy Transportation - For USA & Canada

Courtesy transportation is available for customers whose vehicles are involved in a product program and still within the warranty coverage period. See General Motors Service Policies and Procedures Manual, Sections 1.4 and 6.1.10, for courtesy transportation program details.

Customer Notification

USA & Canada - General Motors will notify customers of this recall on their vehicle.

