

Part 573 Safety Recall Report

18V-039

Manufacturer Name : Mazda North American Operations**Submission Date :** MAR 16, 2023**NHTSA Recall No. :** 18V-039**Manufacturer Recall No. :** 2318A**Manufacturer Information :****Population :**

Manufacturer Name : Mazda North American Operations

Number of potentially involved : 2,205

Address : 1025 Connecticut Avenue, NW
Suite 910 Washington DC 20036

Estimated percentage with defect : 1 %

Company phone : 800-222-5500

Vehicle Information :

Vehicle 1 : 2006-2006 Mazda B-Series

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : [Updated February 9, 2018]: Due to new information from Takata laboratory testing, the affected population under the "Do Not Drive" notification increased from 160 units to 2,205 units. Consequently, the recall population for 1817L (17V-806) was reduced from 19,621 units to 17,576 units.

[Initial submission January 16, 2018]:

- The recall population includes all vehicles produced with a Takata single stage driver, PSAN based, non-desiccated driver frontal air bag inflator produced by Takata on either 9/3/2005 or 9/5/2005. No inflators were produced by Takata on 9/4/2005.

- Vehicles not included in this recall are included in 1817L (NHTSA no. 17V806).

Production Dates : AUG 05, 2005 - NOV 04, 2005

VIN Range 1 : Begin : 4F4YR46U36PM00006 End : 4F4YR46U56PM03103

☐ Not sequential

VIN Range 2 : Begin : 4F4ZR47E76PM00005 End : 4F4ZR47E96PM03083

☐ Not sequential**Description of Defect :**

Description of the Defect : The passenger frontal air bag inflator could rupture if the vehicle is involved in a crash where the supplemental frontal air bags are designed to deploy. The vehicles included in this recall were removed from recall 1817L (NHTSA no. 17V806). An elevated risk of rupture which only affects the driver side air bag inflators applies to these vehicles.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Activation of a non-desiccated phase-stabilized ammonium nitrate ("PSAN") inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Involved Components :

Component Name 1 : NR

Component Description : NR

Component Part Number : NR

Supplier Identification :

Component Manufacturer

Name : Takata / T K Holding INC.

Address : 888 16th street, NW,
Suite 800 District of Columbia 20006

Country : United States

Chronology :

(See the attached Chronology.pdf for preceding chronological events.)

Updated July 27 2020 – This amendment is to inform of Mazda's intent to implement the "other" reporting category for removed vehicles in Quarterly Reporting as permitted in the Third Amendment to the Coordinated Remedy Order ("ACRO"), Paragraphs 45 through 49. As a condition of the ACRO, all affected vehicles will remain active, or "live", across Mazda's data systems such that any search of "other" removed VINs will return an open recall status. For this reason, the Number of potentially involved vehicles in this report will remain the same. However, for reference, initial counts of vehicles in the "other" reporting category are indicated in attached supplement. Note that these counts are current as of the second calendar quarter 2020. Future changes to overall Total Removed counts, including "Other," will be reflected in quarterly reporting as well as monthly dashboard reporting until otherwise directed by the agency.

March 16, 2023 - Amending P573 to include NHTSA approved counts for accountability completions. Refer to

Miscellaneous document and corresponding table of applicable models and counts.

Description of Remedy :

Description of Remedy Program : Owners of record will be notified of this issue and instructed to not drive their vehicles until repairs are completed. Owners will be instructed to contact their Mazda dealer to have their driver and passenger frontal air bag inflators replaced with permanent remedy parts. The repair will be performed free of charge to vehicle owners.

How Remedy Component Differs from Recalled Component : Recalled Parts name: Air bag inflator manufactured by Takata. Part number: 1FTT-57K50.
The remedy part is an air bag inflator manufactured by a different parts supplier and confirmed to be free from phase-stabilized ammonium nitrate.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : [Update on February 9, 2018]: Mazda plans to notify dealers on February 12, 2018 and begin contacting owners by telephone and alternative methods beginning the week of February 12, 2018. Mailing of owner notifications is planned to be completed as soon as possible, but no later than February 16, 2018.

[Initial submission January 16, 2018]: Mazda plans to notify dealers on January 16, 2018 and begin contacting owners by telephone and alternative methods on January 16, 2018. Mailing of owner notifications is planned to be completed as soon as possible, but no later than January 19, 2018.

Planned Dealer Notification Date : FEB 12, 2018 - FEB 12, 2018

Planned Owner Notification Date : FEB 16, 2018 - FEB 16, 2018

* NR - Not Reported