OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Ferrari North America, Inc.Submission Date :MAY 30, 2018NHTSA Recall No. :18V-040Manufacturer Recall No. :63

Manufacturer Information :

Manufacturer Name : Ferrari North America, Inc. Address : 250 Sylvan Avenue Englewood Cliffs NJ 07632-2500 Company phone : 1800-999-9999

Population :

Number of potentially involved : 1,899 Estimated percentage with defect : 100~%

Vehicle Information :

Vehicle 1: 2013-2013 Ferrari California			
Vehicle Type : LIGHT VEHICLES			
Body Style : 2-DOOR			
Power Train : GAS			
Descriptive Information : All MY 2013 vehicles in the production range, nationwide. Note: All MY 2012 and older affected Ferrari vehicles were already included in Ferrari North America's protocol 573 Safety Defect Information Reports dated January 10, 2017 and May 23, 2016, respectively, and are therefore not included in this filing	ior		
Production Dates : MAY 21, 2012 - APR 02, 2013			
VIN Range 1: Begin: ZFF65TJA7D0189063 End: ZFF65TJA2D0195708 Not sequent	al		
	_		
Vehicle 2: 2013-2013 Ferrari 458 Italia			
Vehicle Type : LIGHT VEHICLES			
Body Style : 2-DOOR			
Power Train : GAS			
Descriptive Information : All MY 2013 vehicles in the production range, nationwide. Note: All MY 2012 and older affected Ferrari vehicles were already included in Ferrari North America's prospectively. The second	ior		
Production Dates : MAY 18, 2012 - APR 17, 2013			
VIN Range 1 : Begin : ZFF67NFA2D0189101 End : ZFF67NFA0D0196046			
	_		
Vehicle 3: 2013-2013 Ferrari F12 berlinetta			
Vehicle Type : LIGHT VEHICLES			
Body Style : 2-DOOR			
Power Train : GAS			
Descriptive Information : All MY 2013 vehicles in the production range located in Zone A ONLY (States: Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, Texas, and Son Carolina, Puerto Rico, and American Samoa). Note: All MY 2012 affected Ferrari	ıth		
	The information contained in this report was submitted pursuant to 49 CFR §573		



18V-040

	vehicles in Zone A, and MY 2011 and older C were already included in Ferrari North A Information Reports dated January 10, 20 therefore not included in this filing.	America's prior 573 Safety Def	ect
	DEC 10, 2012 - APR 26, 2013 Begin : ZFF74UFA0D0193090 End : ZF	FF74UFA2D0196279	ot sequential
Descriptive Information :	All MY 2013 vehicles in the production rat older affected Ferrari vehicles were alread 573 Safety Defect Information Reports dat respectively, and are therefore not include	dy included in Ferrari North A ted January 10, 2017 and May	merica's prio
	MAY 30, 2012 - APR 22, 2013 Begin : ZFF73SKA0D0189019 End : ZF		ot sequential
Descriptive Information :	All MY 2013 vehicles in the production ratio older affected Ferrari vehicles were alread 573 Safety Defect Information Reports dat respectively, and are therefore not include	dy included in Ferrari North A ted January 10, 2017 and May	merica's prio
	MAY 22, 2012 - APR 23, 2013 Begin : ZFF68NHA1D0189231 End : ZF	FF68NHA2D0196124	ot sequential

The information contained in this report was submitted pursuant to 49 CFR \$573

18V-040

Description of Defect :

 begins the properties of the properties of the study of the properties of the study of the properties of the propert of the properties of the properies of the properties of the properties of the pr	Description of the Defect :	On January 2, 2018, Takata submitted a 573 Safety Defect Information Report to NHTSA, stating as follows: "Takata has determined that a defect related to motor vehicle safety may arise in some of the subject non-desiccated PSAN inflators due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures and high temperature cycling. Testing and analyses conducted by Takata and by independent entities have found that there are wide differences in the time periods in which propellant degradation takes place. The propellant degradation varies in different climate
 complaints involving the subject Takata passenger air bag non-desiccated ammonium nitrate inflators mounted on its vehicles. Ferrari is filing this report in compliance with 49 CFR 573.3. FMVSS 1: NR FMVSS 2: NR Description of the Safety Risk : Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in nijury or death to vehicle occupants." Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability." 		zones, in different vehicle makes and models, and in different inflator and propellant configurations. Takata believes that the subject inflators perform as originally designed and manufactured and do not pose an unreasonable risk to safety until they reach a certain level of propellant degradation." Per the Defect Information Report filed by Takata with NHTSA on January 2, 2018, Takata stated not to be aware of any test ruptures in ballistic testing of returned inflators or confirmed field incidents of the designated categories and model years of the subject non-desiccated PSAN inflators other than those already under recall as detailed in prior Takata Defect Information Reports (DIR). Defect Information Reports of Takata prior to the Defect Information Report of Takata dated May 16, 2016 did not involve Ferrari vehicles. Ferrari is not
FMVSS 2 :NRDescription of the Safety Risk :Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants."Description of the Cause :Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability."		complaints involving the subject Takata passenger air bag non-desiccated ammonium nitrate inflators mounted on its vehicles. Ferrari is filing this report
 Description of the Safety Risk : Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants." Description of the Cause : Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability." 		
2018, "the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability."		Per the Defect Information report filed with NHTSA by Takata on January 2, 2018, "Activation of a non-desiccated PSAN inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants."
	Description of the Cause :	2018, "the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based upon Takata's investigation to date, the potential for such ruptures occurs in some of the subject inflators after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant
	· · ·	None.

The information contained in this report was submitted pursuant to 49 CFR \$573

Supplier Identification :

Component Manufacturer

Name : TK Global LLC Address : 111 Peyerk Court Romeo MICHIGAN 48065 Country : United States

Chronology :

Takata filed a Defect Information Report with NHTSA on January 2, 2018 and Ferrari is filing this Defect Information Report in compliance with 49 CFR 573.3. With regard to remedy launch, Ferrari will comply with the schedule outlined in the Third Amendment to the Coordinated Remedy Order dated December 9, 2016 ("CRO3") issued by NHTSA.

In May, 2018 Ferrari expanded this campaign from Zone A only, to include all MY 2013 vehicles, nationwide.

Description of Remedy :

How Remedy Component Differs from Recalled Component :Ferrari will replace the current front passenger airbag assembly which includes a PSPI-2 inflator, with an airbag assembly including a new non- ammonium nitrate inflator ("new PAB").Identify How/When Recall Condition was Corrected in Production :Ferrari began installing 'Final' non-ammonium nitrate airbag inflators ("new PAB") in new production vehicles, beginning in MY 2018.		Description of Remedy Program :	Ferrari will conduct a voluntary safety recall on all affected vehicles to replace the front passenger airbag assembly subject to the availability of replacement assemblies in accordance with prioritization of risk, determined by the age of the inflator and exposure to high humidity and fluctuating high temperatures, and in accordance with the Coordinated Remedy Program. Customers may be eligible to receive reimbursement for the cost associated with this defect provided that the customer sends the original receipt and/or other adequate proof of payment to the company for confirmation of the expenses incurred by the customers. As stated in Annex A of CRO3, the vehicles involved in this filing have been assigned by NHTSA to Priority Groups # 9 and 10, with June 30, 2018 and March 31, 2019, as remedy launch deadlines for starting the implementation of the recall.
			includes a PSPI-2 inflator, with an airbag assembly including a new non-
	[d		

Recall Schedule :

Description of Recall Schedule : Ferrari will conduct a voluntary safety recall on all affected vehicles to replace the front passenger airbag assembly subject to the availability of

Part 573 Safety Recall Report

Page 5

	replacement assemblies in accordance with prioritization of risk, determined by the age of the inflator and exposure to high humidity and fluctuating high temperatures, and in accordance with the Coordinated
	Remedy Program.
Planned Dealer Notification Date :	JUN 08, 2018 - NR
Planned Owner Notification Date :	JUN 22, 2018 - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573