

Part 573 Safety Recall Report

18V-108

Manufacturer Name : Toyota Motor Engineering & Manufacturing**Submission Date :** FEB 14, 2018**NHTSA Recall No. :** 18V-108**Manufacturer Recall No. :** JOG**Manufacturer Information :**

Manufacturer Name : Toyota Motor Engineering & Manufacturing
Address : 6565 Headquarters Drive
 Plano TX 75024
Company phone : 1-800-331-4331

Population :

Number of potentially involved : 11,807
Estimated percentage with defect : NR

Vehicle Information :**Vehicle 1 :** 2018-2018 Toyota Camry**Vehicle Type :****Body Style :****Power Train :** NR

Descriptive Information : (1) Although the involved vehicles are within the above production period, not all vehicles in this range were sold in the U.S.

(2) The involved vehicles are equipped with a V6 gasoline engine, which contains two fuel delivery pipes that connect to two fuel supply hoses. Other Toyota or Lexus vehicles either use a different fuel line structure or use a different assembly process to connect the fuel pipes to the fuel supply hoses.

Note: Toyota is unable to provide an estimate of the percentage of vehicles to actually contain the defect. Whether the manufacturing issue will lead to the partial engagement of the fuel delivery pipes with the fuel hoses, creating an unreasonable risk to safety, depends on each vehicle's actual installation and inspection at the time of manufacturing.

Production Dates : JUN 22, 2017 - NOV 29, 2017**VIN Range 1 : Begin :**

NR

End : NR Not sequential**Description of Defect :**

Description of the Defect : The subject vehicles are equipped with a V6 engine. For these vehicles, the engine design uses two fuel delivery pipes connected to two fuel hoses in the engine compartment. During the assembly process, there is a possibility that one or both fuel delivery pipes may not have been properly connected with its fuel hoses. In this condition, the fuel delivery pipe(s) could be partially engaged, resulting in a fuel odor or fuel leak. In the presence of an ignition source, a fuel leak could increase the risk of a fire.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In this condition, the fuel delivery pipe(s) could be partially engaged, resulting in a fuel odor or fuel leak. In the presence of an ignition source, a fuel leak could increase the risk of a fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

Chronology :

Please see the attached Part 573 Defect Information Report for the full chronology

Description of Remedy :

Description of Remedy Program : All known owners of the involved vehicles will be notified via first class mail to return their vehicles to a Toyota dealer. Toyota dealers will inspect the fuel delivery pipes for proper installation and connect them, as necessary, at no charge to the owner. As the owner notification letters will be mailed out well within the active period of the Toyota New Vehicle Limited Warranty ("Warranty"), all involved vehicle owners for this recall would have been provided a repair at no cost under Toyota's Warranty.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Notifications to owners of the affected vehicles will occur by late-March, 2018. A copy of the draft owner notification letter will be submitted as

soon as available. Notifications to distributors/dealers will be sent on February 14, 2018. Copies of dealer communications will be submitted as they are issued.

Planned Dealer Notification Date : FEB 14, 2018 - FEB 14, 2018

Planned Owner Notification Date : MAR 30, 2018 - APR 15, 2018

* NR - Not Reported