

Part 573 Safety Recall Report

18V-156

Manufacturer Name : Nissan North America, Inc.

Submission Date : MAR 07, 2018

NHTSA Recall No. : 18V-156

Manufacturer Recall No. : NR



Manufacturer Information :

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : 800-647-7261

Population :

Number of potentially involved : 49,385

Estimated percentage with defect : 2 %

Vehicle Information :

Vehicle 1 : 2011-2012 Nissan Juke

Vehicle Type : LIGHT VEHICLES

Body Style : HATCHBACK

Power Train : GAS

Descriptive Information : This issue only affects the subject Nissan Juke vehicles that were previously remedied under recall 12V-069. Additional 2011-2014 Nissan Juke vehicles are subject to recall 14V-683. The remedy for this group of vehicles is unchanged.

Production Dates : APR 09, 2010 - DEC 27, 2011

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : On a small number of affected vehicles, the fuel pressure sensor may not have been tightened properly when the remedy for recall 12V-069 was performed. As a result, the fuel pressure sensor may loosen gradually due to heat and vibration. If this occurs, over time, a small amount of fuel may leak from the fuel pressure sensor.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If this condition occurs, over time, a small amount of fuel may leak from the fuel pressure sensor connection which could increase the risk of a fire in the presence of an ignition source.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : NR
Address : NR
NR
Country : NR

Chronology :

See chronology in attached electronic copy of the Part 573 report.

Description of Remedy :

Description of Remedy Program : Dealers will retighten the fuel pressure sensor to the proper torque specification using the new (recall 14V-683) remedy procedure. Part 577 owner notifications will include information concerning reimbursement for the cost of obtaining a pre-notification remedy as the subject vehicles are no longer covered under warranty.

How Remedy Component Differs from Recalled Component : Nissan is revising the remedy procedure for vehicles that were repaired under recall 12V-069. These vehicles will received the updated remedy procedure that reduces complexity by requiring a special tool that allows access to the fuel pressure sensor without engine disassembly. The tightening torque is also changed from a calculated value for each dealer (based on torque wrench measurements) to a fixed value for all dealers to avoid remedy variation.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owners of all potentially affected vehicles will be notified within 60 days. Nissan plans to notify dealers by March 8, 2018.
Planned Dealer Notification Date : MAR 09, 2018 - NR
Planned Owner Notification Date : MAY 07, 2018 - NR

* NR - Not Reported