OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

## 18V-209

Manufacturer Name: Van Hool N.V.

Submission Date: MAY 02, 2018

NHTSA Recall No.: 18V-209

Manufacturer Recall No.: P941-SB1480



#### **Manufacturer Information:**

Manufacturer Name: Van Hool N.V.

Address: BERNARD VAN HOOLSTRAAT 58

LIER-KONINGSHOOIKT (BELGIUM) 00

B2500

Company phone: 999

### **Population:**

Number of potentially involved: 1,528 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2015-2018 VAN HOOL CX45

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

**Descriptive Information: 56 PASSENGERS** 

Production Dates: AUG 22, 2014 - NOV 22, 2017

Vehicle 2: 2016-2018 VAN HOOL CX35

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER Power Train: DIESEL

**Descriptive Information: 42 PASSENGERS** 

Production Dates: JUL 24, 2015 - DEC 22, 2017

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3: 2015-2018 VAN HOOL TX45

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : OTHER Power Train : DIESEL

**Descriptive Information: 56 PASSENGERS** 

Production Dates: MAY 16, 2014 - MAR 09, 2018

Vehicle 4: 2015-2018 VAN HOOL TDX25

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style: OTHER

	Power Train: DI	ESEL					
	Descriptive Information: 81	criptive Information: 81 PASSENGERS					
	Production Dates: MAY 29, 2015 - FEB 06, 2018						
	VIN Range 1: Beg	gin:	NR	End:	NR	☐ Not sequential	
	Vehicle 5: 2015-2018 VAN HOOL TX40 Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES Body Style: OTHER Power Train: DIESEL						
	Descriptive Information: 48 PASSENGERS						
	Production Dates: OCT 02, 2014 - OCT 12, 2017						
	VIN Range 1: Beg	gin:	NR	End:	NR	☐ Not sequential	
	Vehicle 6: 2015-2018 VAN HOOL TD925  Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES  Body Style: OTHER  Power Train: DIESEL  Descriptive Information: 81 PASSENGERS  Production Dates: JUL 10, 2015 - NOV 08, 2017  VIN Range 1: Begin: NR End: NR Not sequential						
Description of Defect :							
	Description of the Defect :	Subject vehicles have passenger seats equipped with buckles of which the outer casing may fail. These casings are held in place by one plastic notch only. When subjected to great pressure (e.g. by standing on the buckle or tampering the buckle) these casings may fail and consequently slide down thereby uncovering the buckle mechanism.					
	FMVSS 1: FMVSS 2:						
Ι	Description of the Safety Risk: These buckles, as and when the covers have/are slid down, may give passengers the impression that the buckle mechanism is defect and as such inhibit passengers from buckling up.						
	Description of the Cause :	NR					
	Identification of Any Warning that can Occur :	NR					

### **Supplier Identification:**

### **Component Manufacturer**

Name: Fasching Salzburg

Address: Hellbrunner Strasse 11

Salzburg FOREIGN STATES 5020

Country: Austria

### **Chronology:**

The first claim on the seat belt buckle was traced back to a failure reported early March 2016. By February 2017, our distributor ABC Companies informed Van Hool on how the seats are being used by passengers and why many seat belt buckles are being damaged. Van Hool Quality Department assessed the problem as "The buckles are rigidly mounted and extend above the seat cushions. The solution proposed is a buckle on a flexible stem.'

On March 30th 2017, the National Transportation Safety Board requested information on the seat belt buckle design after the incident at Biloxi involving a Van Hool motorcoach where several belt buckles were found with the cover out of place, but with all buckles remaining operational except one.

At the end of August 2017 two fixes were proposed and investigated. As a first solution the adding of a metal support on the anchorage to stop the casing from moving down, was proposed. The buckle on a flexible stem was as the second proposal after investigation retained and 2000 samples were sent into the field for a try-out. On October 11th 2017 the Office of Defect Investigation of NHTSA opened a Preliminary Evaluation (PE17-006) to investigate allegations of seat belt latch casing failures, which request for information was answered by November 30th.

On March 30th 2018 Van Hool decided that the failure rate for the rigid buckles was too high for modelyear 2016 vehicles (17%), and decided to recall all affected motorcoaches, in order to have the rigid seat belt buckles on the aisle side changed by buckles on a flexible stem.

### **Description of Remedy:**

Description of Remedy Program: Van Hool is recalling the 2015-2018 affected motorcoaches, in order to

have the rigid seat belt buckles of the aisle side passenger seats changed

by flexible buckles: see service bulletin SB1480.

Our designated agent ABC Bus, Inc. will notify Van Hool motorcoach owners of the above mentioned vehicles by mail sent to their addresses

and conduct the recall free of charge.

How Remedy Component Differs The recalled component is a rigid seat belt buckle with Fasching PN

from Recalled Component: X-4315-2-009.

The remedy component is a fixed seat betl buckle with Fasching PN

4309-2-002.

Identify How/When Recall Condition The rigid passenger seat belt buckles on the aisle side were replaced with

was Corrected in Production: flexible buckles.

### **Recall Schedule:**

Description of Recall Schedule: The notified owner should contact ABC Bus Inc. our designated agent in

the United States to schedule to have the recall performed and to ensure

that parts are available.

The replacement will take approximately 10 minutes per buckle replaced

and will be performed at no charge to the owner.

Planned Dealer Notification Date: APR 17, 2018 - APR 17, 2018 Planned Owner Notification Date: MAY 15, 2018 - MAY 29, 2018

\* NR - Not Reported