

# Part 573 Safety Recall Report

# 18V-240

**Manufacturer Name :** Nissan North America, Inc.**Submission Date :** APR 16, 2018**NHTSA Recall No. :** 18V-240**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Nissan North America, Inc.

Address : P. O. BOX 685001

Franklin TN 37068-5009

Company phone : 800-647-7261

**Population :**

Number of potentially involved : 483

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2016-2018 Nissan Titan

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : GAS

Descriptive Information : -No other vehicles are affected because the issue is unique to this model and dates of manufacture.  
 -The recalled vehicles are not equipped with the requisite load carrying capacity modification label.

Production Dates : APR 14, 2016 - FEB 27, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2016-2016 Nissan Titan XD

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : DIESEL

Descriptive Information : -No other vehicles are affected because the issue is unique to this model and dates of manufacture.  
 -The recalled vehicles are not equipped with the requisite load carrying capacity modification label.

Production Dates : NOV 18, 2015 - SEP 17, 2016

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2018-2018 Nissan Titan XD

Vehicle Type : LIGHT VEHICLES

Body Style : PICKUP TRUCK

Power Train : DIESEL

Descriptive Information : -No other vehicles are affected because the issue is unique to this model and dates of manufacture.

-The recalled vehicles are not equipped with the requisite load carrying capacity modification label.

Production Dates : DEC 07, 2017 - FEB 13, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Noncompliance :

Description of the Noncompliance : S10.1 of Federal Motor Vehicle Safety Standard (FMVSS) No. 110 requires the addition of a load carrying capacity modification label if weight exceeding the lesser of 1.5 percent of GVWR or 45.4 kg (100 pounds) is added to a vehicle between final vehicle certification and first retail sale of the vehicle. The subject vehicles are not equipped with the requisite load carrying capacity modification label.

FMVSS 1 : 110 - Tire selection and rims

FMVSS 2 : NR

Description of the Safety Risk : If the load carrying capacity modification label is missing, the customer is at risk of overloading the vehicle, which can create an unsafe condition.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

During a vehicle inspection at a Nissan Vehicle Preparation Center (VPC), Nissan identified the reduced capacity label was missing on a Nissan Titan vehicle equipped with accessories over the S10.1 threshold. Subsequent investigation identified additional Titan vehicles were not equipped with the reduced capacity label. Upon determining that the subject vehicles had left Nissan's control, and were either delivered to dealers or retailed, Nissan decided that the subject vehicles did not comply with S10.1 of FMVSS No. 110; and to conduct a recall to replace the missing label.

## Description of Remedy :

Description of Remedy Program : Nissan will mail affected customers a new label and installation instructions on how to affix the label in order to remedy the issue. Each label will be generated specifically for each customer's vehicle, based on the accessories actually installed. These customers will also have the option of taking their vehicle to a Nissan dealer to have the new label affixed if they are uncomfortable performing this action.

Nissan will not include a statement in the Part 577 owner notification concerning reimbursement for the cost of obtaining a pre-notification remedy as the subject vehicles are under warranty.

How Remedy Component Differs from Recalled Component : The recalled vehicles do not contain the requisite load carrying capacity modification label. A label with the correct reduced load carrying modification information will be mailed to the affected customers.

Identify How/When Recall Condition was Corrected in Production : NR

## Recall Schedule :

Description of Recall Schedule : Owners of all potentially affected vehicles will be notified within 60 days.

Planned Dealer Notification Date : APR 17, 2018 - NR

Planned Owner Notification Date : JUN 16, 2018 - NR

\* NR - Not Reported