The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :	Ford Motor Company
Submission Date :	APR 30, 2018
NHTSA Recall No. :	18V-275
Manufacturer Recall No. :	17S34-s #1

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Vehicle Information :

	2015-2017 Ford Transit		
• •	LIGHT VEHICLES		
Body Style :	ALL		
Power Train :	GAS		
Descriptive Information :	The recalled vehicles were introduced into production on $02/03/14$. Ongoing robustness actions were introduced into vehicles by $08/02/17$.		
	This supplement recognize included in Ford's prior act	s an additional 25,658 affe ion due to an inadvertent i	l 17S34 (NHTSA # 17V668). cted vehicles, which were not dentification error. The affected bed in Ford's 17S34 action have
	this action to specific vehic line (1-866-436-7332) or b	les can best be obtained by y contacting a local Ford o ing the vehicles from the F	aation as to the applicability of either calling Ford's toll-free r Lincoln dealer who can obtain ford On-line Automotive Service
Production Dates :	FEB 03, 2014 - AUG 02, 201		
VIN Range 1:1	Begin : NR	End: NR	☐ Not sequential

Population :

Number of potentially involved : 25,658 Estimated percentage with defect : 1 %



18V-275

Description of Defect :

FMVSS 1 :	
FININGS 2.	N R
cription of the Safety Risk :	An electrical short to ground in the module can overload the ground wire
	circuit, increasing the risk of overheated or melted wiring and fire.
Description of the Cause :	Water and snow can migrate into the driver's door stepwell area of the vehicle where the trailer tow module is packaged. There is limited drain capability for water in this area, which can allow water to pool and splash, potentially causing corrosion to the module or wiring. Prolonged corrosion of the module or wiring can cause an electrical short to ground in the module and overload the ground wire circuit.
	This is a supplement to Ford's October 23, 2017 recall 17S34 (NHTSA # 17V668). This supplement recognizes an additional 25,658 affected vehicles, which were not included in Ford's prior action due to an inadvertent identification error. The affected vehicle production beginning and ending dates described in Ford's 17S34 action have not changed.
	The customer may notice rapid flashing of the turn signals, loss of the instrument cluster display, loss of heater and air conditioning controls, loss of multimedia (radio, screens, SYNC), or odor of overheated or melted electrical wiring.
	FMVSS 1 : FMVSS 2 : cription of the Safety Risk : Description of the Cause : ntification of Any Warning

Supplier Identification :

Component Manufacturer

Name: Delphi Deutschland GmbH

- Address : Albert-Einstein-Straße 5
 - Wiehl FOREIGN STATES D-51674
- Country: Germany

The information contained in this report was submitted pursuant to 49 CFR §573

Chronology :

This is a supplement to Ford's October 23, 2017 recall 17S34 (NHTSA # 17V668). This supplement recognizes an additional 25,658 affected vehicles, which were not included in Ford's prior action due to an inadvertent error.

April 2018: Ford identified an error that resulted in the inadvertent exclusion of certain vehicle configurations from the 17S34 program. Ford contacted NHTSA's Recall Management activity to inform the agency of this error, and that plans for supplemental dealer and customer contact were underway. The agency subsequently requested a separate Part 573 defect notification from Ford for these vehicles.

On April 30, 2018, Ford's Field Review Committee reviewed the matter and approved the submission of this separate defect notice.

Ford will manage these additional vehicles as part of the original 17S34 field service action, with separate reporting to the agency in accordance with the requirements of 49 CFR Part 573.7 (Quarterly Reporting).

Description of Remedy :

	Description of Remedy Program :	Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to drill a drainage hole in the driver's side stepwell, and install an inline fuse for trailer tow modules that were produced without a fuse. There will be no charge for this service.
		Until repairs are performed, owners will be instructed to park their vehicle outside.
		Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in February 2017. The ending date for reimbursement eligibility is May 25, 2018.
		Ford will forward a copy of the notification letters to dealers to the agency when available.
	How Remedy Component Differs from Recalled Component :	Ford is installing an incremental fuse and a drain hole on affected vehicles.
de		The recall condition was corrected in production by the addition of a fuse for the module ground wire in the auxillary fuse box, and the addition of a drain hole in the stepwell area effective August 2, 2017.

Recall Schedule :

I

The information contained in this report was submitted pursuant to 49 CFR §573

Description of Recall Schedule :	Notification was sent to dealers on April 19, 2018. Mailing of owner
	notification letters is expected to begin May 7, 2018 and is expected to be
	completed by May 11, 2018.
Planned Dealer Notification Date :	NR - NR
Planned Owner Notification Date :	MAY 07, 2018 - MAY 11, 2018

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573