

Part 573 Safety Recall Report

18V-288

Manufacturer Name : Daimler Vans USA, LLC**Submission Date :** JUN 27, 2019**NHTSA Recall No. :** 18V-288**Manufacturer Recall No. :** NR**Manufacturer Information :**

Manufacturer Name : Daimler Vans USA, LLC

Address : One Mercedes-Benz Drive
Sandy Springs GA 30328

Company phone : 854-888-3214

Population :

Number of potentially involved : 153

Estimated percentage with defect : 5 %

Vehicle Information :

Vehicle 1 : 2017-2017 Mercedes-Benz Sprinter

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN

Power Train : DIESEL

Descriptive Information : The recall population refers to the NAFTA Sprinter vehicles (Platform 906) from the Ludwigsfelde plant, produced between September 11, 2017 (restart after block break) and October 11, 2017 (discovery in plant).

A further filtering of the potentially affected vehicles based on the programming of the welding robot could not be made, neither by Daimler nor by the supplier of the welding robots.

Other NAFTA Sprinter vehicles (Platform 906) have already been equipped correctly with the necessary spot welds and have been produced outside the affected production period September 11, 2017 and October 11, 2017.

Production Dates : SEP 11, 2017 - OCT 11, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2017-2017 Feightliner Sprinter

Vehicle Type :

Body Style :

Power Train : NR

Descriptive Information : The recall population refers to the NAFTA Sprinter vehicles (Platform 906) from the Ludwigsfelde plant, produced between September 11, 2017 (restart after block break) and October 11, 2017 (discovery in plant).

A further filtering of the potentially affected vehicles based on the programming of the welding robot could not be made, neither by Daimler nor by the supplier of the welding robots.

Other NAFTA Sprinter vehicles (Platform 906) have already been equipped correctly with the necessary spot welds and have been produced outside the affected production period September 11, 2017 and October 11, 2017.

Production Dates : SEP 11, 2017 - OCT 11, 2017

VIN Range 1 : Begin :

NR

End : NR

Not sequential

Description of Defect :

Description of the Defect : Daimler AG (DAG), the manufacturer of Mercedes-Benz Vans, has determined that on certain Mercedes-Benz and Freightliner Sprinter vehicles for the NAFTA market, spot welds might be missing on the front side wall on the driver and the passenger side. The affected spot welds connect the door portal with the underlying hinge reinforcements behind.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash, it cannot be ruled out that there may be a negative impact on vehicle safety due to the missing welding spots. Further, the durability of the vehicle over its lifecycle may be affected.

Description of the Cause : During the preparatory work on the production systems for the subsequent model series, a programming error occurred with two welding robots. Spot welds on the front side wall paneling may not have been set as a result of the programming error. As a consequence, the integrity of the weld, which connects the door portal with the underlying hinge reinforcements in the area of the A-pillar and the reinforcement of the closing eyelet in the area of the B-pillar, is not ensured.

Identification of Any Warning that can Occur : NR

Supplier Identification :

Component Manufacturer

Name : KUKA Aktiengesellschaft

Address : Zugspitzstraße 140
Augsburg 86165

Country : NR

Chronology :

Chronology exceeds the number of characters allowed. Please find the chronology attached as a miscellaneous

document.

Description of Remedy :

Description of Remedy Program : An authorized Mercedes-Benz or Freightliner Sprinter dealer will perform a visual inspection and check if any of the welds on the A-pillar are missing. If necessary, the affected vehicles will be reworked by setting the missing weld spots at the front side wall panelling.

Pursuant to 49 C.F.R. § 577.11(e), Daimler Vans does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs from Recalled Component : Mercedes-Benz and Freightliner Sprinter vehicles (Platform 906) will be equipped with the necessary spot welds on the front side wall on the driver and the passenger side.

Identify How/When Recall Condition was Corrected in Production : A 100% visual inspection as well as the inspection of the factory inventory at the Ludwigsfelde plant were carried out immediately after the facts had been identified.
Furthermore, a correction of the robot programming was implemented immediately after detection of the issue.

Recall Schedule :

Description of Recall Schedule : Owners will be notified approximately one week after the recall launch to the dealers.

Planned Dealer Notification Date : JUN 28, 2018 - JUN 28, 2018

Planned Owner Notification Date : JUN 29, 2018 - JUN 29, 2018

* NR - Not Reported