Part 573 Safety Recall Report

Manufacturer Name :Volkswagen Group of America, Inc.Submission Date :JUN 25, 2018NHTSA Recall No. :18V-430Manufacturer Recall No. :20AV



18V-430

Manufacturer Information :

Manufacturer Name :Volkswagen Group of America, Inc.Address :3800 Hamlin RoadAuburn Hills MI 48326Auburn Hills MI 48326Company phone :1-800-893-5298

Population :

Number of potentially involved : 6,633 Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1 : Vehicle Type : Body Style :	2013-2014 Audi S8	
Power Train :	NR	
Descriptive Information :	The recall population was determined based upon the fact that the affected fuel line was only used in vehicles produced between June 2012 and July 2014. Before that period a different engine was installed and after that period a different fuel line was used.	
Production Dates :	JUN 27, 2012 - MAR 28, 2014	
VIN Range 1 : Begin : WAUD2AFD2DN004908 End : WAUD2AFDXEN014930 🔽 Not sequentia		
Vehicle 2 : Vehicle Type : Body Style :	2015-2015 Audi S8	
Power Train :	NR	
Descriptive Information :	The recall population was determined based upon the fact that the affected fuel line was only used in vehicles produced between June 2012 and July 2014. Before that period a different engine was installed and after that period a different fuel line was used.	
Production Dates .	MAR 10 2014 - OCT 21 2014	
	Production Dates :MAR 19, 2014 - OCT 21, 2014VIN Range 1 : Begin :WAUK2AFD1FN000584End :WAUK2AFD4FN022756Image: Image:	
Vehicle 3 : Vehicle Type : Body Style :	2015-2015 Audi A8	
Power Train :	NR	
Descriptive Information :	The recall population was determined based upon the fact that the affected fuel line	
The information contained in this report was submitted pursuant to 49 CFR §573		

art 573 Safet	ty Recall Report	18V-430	Page
Descriptive Information :	was only used in vehicles produced betw period a different engine was installed an used.	5	
	MAR 18, 2014 - AUG 01, 2014 Begin : WAU32AFD8FN000571 End : V	VAU32AFD4FN014239 ☑ Not seq	uentia
Vehicle Type : Body Style :	2015-2015 Audi A8		
Power Train : Descriptive Information :	NR The recall population was determined ba was only used in vehicles produced betw period a different engine was installed an used.	veen June 2012 and July 2014. Before	that
	APR 16, 2014 - JUL 31, 2014 Begin : WAUJ2AFDXFN003687 End : V	NAUJ2AFD1FN014139 ☑ Not seq	uentia
Vehicle 5 : Vehicle Type : Body Style :	2013-2014 Audi A8		
Power Train : Descriptive Information :	NR The recall population was determined ba was only used in vehicles produced betw period a different engine was installed an used.	veen June 2012 and July 2014. Before	that
	JUN 27, 2012 - MAR 26, 2014 Begin : WAUR2AFD2DN004929 End : V	VAUR2AFD5EN014968 🔽 Not seq	uentia
Vehicle Type : Body Style :	2013-2014 Audi A8		
Power Train : Descriptive Information :	NR The recall population was determined ba was only used in vehicles produced betw period a different engine was installed an used.	veen June 2012 and July 2014. Before	that
	JUL 11, 2012 - MAR 21, 2014 Begin : WAUA2AFD8DN006973 End : V	VAUA2AFD2EN014780 ☑ Not seq	uentia

The information contained in this report was submitted pursuant to 49 CFR \$573

Description of Defect :

Description of the Defect :	Over time, the fuel supply line for the high pressure fuel pump may become porous, resulting in a fuel smell or a fuel leak.
FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	Leaking fuel, in the presence of an ignition source, may potentially result in a fire.
Description of the Cause :	The fuel supply line for the high pressure fuel pump may become porous/ damaged from the inside. The exact root cause and possible contributing factors are not yet fully known. Audi continues to investigate the root cause and all outside factors to fully understand the issue.
Identification of Any Warning that can Occur :	Fuel smell may be noticeable to vehicle occupants.

Supplier Identification :

Component Manufacturer

Name : Veritas AG Address : Stettiner Str. 1-9 Gelnhausen FOREIGN STATES 63571 Country : Germany

Chronology :

"4th quarter of 2016: Single cases with fuel leaks due to a damaged fuel line were reported to Audi AG. First quarter of 2017: Increase in reports of fuel leaks due to a damaged fuel line.

May 2017: Issue was presented in the Audi AG Product Safety Committee pre-clarification. It was decided to collect field parts for further investigation.

June 2017 - September 2017: Parts collection and analysis conducted.

October 2017: Results were presented at the Audi AG Product Safety Committee pre-clarification. It was determined that the fuel lines became porous from the inside. Further tests and investigations were tasked in order to identify the cause.

November 2017 - May 2018: Collection and analysis of additional field parts, comparison to other markets and other fuel lines, investigation of possible contributing factors and root cause. Updates were provided to the Audi Product Safety Committee. Reported failures only occurred in the United States and Canada.

June 18, 2018: Although the root cause and influential factors still have not been fully understood, the Audi Product Safety Committee made the defect determination and decided on safety recall for United States and Canadian markets. Audi continues to investigate the root cause and all outside factors to fully understand the issue.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Date of determination: June 18, 2018				
Description of Remedy :				
Description of Remedy Program :	The fuel line will be replaced at no cost to owners. Audi will offer a reimbursement program under this recall.			
How Remedy Component Differs from Recalled Component :	"Part number of recalled part: 079.133.986.AB The replacement fuel line is the part that has been used in production since July 2014. This part has a higher stiffness and is therefore less susceptible to porosity.			
Identify How/When Recall Condition was Corrected in Production :	In July 2014 a new fuel line with part number 079.133.986.AF was introduced in production.			
Recall Schedule :				
	Anticipated to begin in August 2018.			
Planned Dealer Notification Date : Planned Owner Notification Date :				

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573