The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Manufacturer Name :Nissan North America, Inc.Submission Date :SEP 18, 2018NHTSA Recall No. :18V-601Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : Nissan North America, Inc. Address : P. O. BOX 685001 Franklin TN 37068-5009 Company phone : 800-647-7261

Vehicle Information :

	2016-2017 Niss				
• •	LIGHT VEHICLE	S			
Body Style :					
Power Train :	GAS				
Descriptive Information :					and models that were san or INFINTI vehicles are
Production Dates :	FEB 10, 2015 - JA	AN 05, 201	7		
VIN Range 1:	Begin :	NR	End :	NR	□ Not sequential
Vahiela 2 ·	2015-2017 Niss	an Murano			
	LIGHT VEHICLE				
Body Style :		5			
Power Train :					
		Costuctors		to the melves.	and models that were
Descriptive Information :			-		and models that were san or INFINTI vehicles are
Production Dates :	AUG 22, 2014 - F	EB 24, 201	7		
VIN Range 1:		NR	End :	NR	☐ Not sequential
Vahiala 2.	2017-2018 Niss	on Dothfin d	lan		
			ler		
• •	LIGHT VEHICLE	3			
Body Style : Power Train :					
Descriptive Information :			-		and models that were san or INFINTI vehicles are
Production Dates :	APR 20, 2016 - J.	AN 09, 201	7		
	APR 20, 2016 - J			ttod purcupat t	- 40 CED SE 72



Number of potentially involved : 215,124 Estimated percentage with defect : 56 %

Population :

18V-601

Part 573 Safety Recall Report

1	8	V-	6	0	1
_	\mathbf{v}	-		v	_

VIN Range 1:Beg	in: NR	End: NR	□ Not sequential
Vehicle 4: 20	17-2017 INFINITI QX	60	
Vehicle Type : LI			
Body Style: SU Power Train: GA			
Descriptive Information : Th	e affected ABS actuat	ors are unique to the makes an e above dates. No other Nissa	
Production Dates : MA	AY 18, 2016 - JAN 09,	2017	
VIN Range 1 : Beg	in: NR	End: NR	□ Not sequential
Description of Defect : Description of the Defect :	an oil seal that may specifically, die temp Coupled with insuffi prematurely. If this	are equipped with ADVICS AB nave been manufactured out of perature variation may have af cient lubrication, this could cau occurs, the ABS warning lamp anel to warn the driver. Howey	f specification. More fected oil seal hardness. use the oil seal to wear will continuously illuminate
	and the vehicle cont	inues to be operated in this con te an electrical short in the act	ndition, the brake fluid leak
FMVSS 1 :			
FMVSS 2 :			
Description of the Safety Risk :	If a fire occurs in cer vehicles occupants.	tain rare instances, in can incr	ease the risk of injury to
Description of the Cause :	-		
Identification of Any Warning that can Occur :	If this occurs, an AB instrument panel to		usly illuminate on the
Supplier Identification : Component Manufacturer Name : ADVICS North Ame Address : 1650 Kingsview D Lebanon OHIO 450	rive		

The information contained in this report was submitted pursuant to 49 CFR §573

Chronology :

January 2018 – Nissan received a report of an illuminated ABS warning lamp on a vehicle previously remedied under 16V-636 recall.

February 2018 to March 2018 – Nissan began an investigation into the issue together with the supplier (ADVICS), and Nissan began active field monitoring. The returned part exhibited a tear in the oil seal, however, the cause of this was undetermined and the condition could not be duplicated on new production parts.

April 2018 to May 2018 – Nissan began a parts collection activity, and began comparing oil seals from returned actuators to the seal from the actuator that malfunctioned.

June 2018 to July 2018 – Nissan performed a number of durability performance tests on returned parts to help determine the scope of parts that may have been affected.

July 2018 to August 2018 – Durability performance testing identified two potential factors affecting the subject ABS actuator performance. More specifically, the hardness of the seal coupled with lack of lubrication around the seal was affecting seal durability.

Nissan then investigated which production specifications of the oil seal could have affected seal hardness and lack of lubrication. Nissan found that the actuator oil seal die temperature was affecting oil seal hardness wear resistance.

August 30, 2018 - Based on the foregoing, Nissan decided to conduct a safety recall campaign to remedy the vehicles outlined above.

Description of Remedy :

Description of Remedy Program :	1	rial number of the ABS actuator on affected affected range, the dealer will replace the at no cost to the owner.
	concerning reimbursement fo remedy for the subject vehicle statement will be excluded for	nt in the Part 577 owner notification r the cost of obtaining a pre-notification es that are no longer under warranty. The r the subject vehicles that are still under provided with a copy of the Part 577 owner
	See attached Part 573 report f vehicles with corresponding p	for Make, Model and Model Year of the part numbers.
	Part Description ABS ACTUATOR ASSY ABS ACTUATOR ASSY - AWD	Part Number 47660-4RB1C 47660-9UD6D

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report	
-------------------------------	--

Page 4

	ABS ACTUATOR ASSY - FWD 47660-9UD6C
	ABS ACTUATOR ASSY 47660-9PP1B
	ABS ACTUATOR ASSY 47660-9PP1D
	ABS ACTUATOR ASSY 47660-9PP1B
	ABS ACTUATOR ASSY 47660-9PP1D
	Brake Fluid (DOT 3 Type 12oz) 999MP-AA410P
dentify How/When Recall Condition	NR
dentify How/When Recall Condition was Corrected in Production :	
was Corrected in Production :	
ecall Schedule :	
was Corrected in Production :	Owners of the subject vehicles will be notified beginning on October 15,
was Corrected in Production :	Owners of the subject vehicles will be notified beginning on October 15, 2018. Dealers will be notified on September 25, 2018.

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573