OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Mercedes-Benz USA, LLC.Submission Date :SEP 11, 2018NHTSA Recall No. :18V-609Manufacturer Recall No. :NR



Manufacturer Name : Mercedes-Benz USA, LLC. Address : 13470 International Parkway

Jacksonville FL 32218 Company phone : 1-877-496-3691

Population :

Number of potentially involved :22Estimated percentage with defect :100 %

云 🔨 🗛 🖈

NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION

18V-609

Vehicle Information :

| Vahiela 1 : | 2018-2018 Mercedes-Benz AM | $C F63 S AMATIC_{\pm}$ | |
|--------------------|--|------------------------|----------------|
| | LIGHT VEHICLES | | |
| Body Style : | | | |
| Power Train : | | | |
| | 213.089 ZF8K 22 vehicles. | | |
| | The recall population was determined through production records. Vehicles not affected by this recall will have seats with sufficient mechanical limitation and correct seat software calibration. | | |
| Production Dates : | JUN 02, 2017 - AUG 03, 2017 | | |
| VIN Range 1: | Begin : NR | End: NR | Not sequential |
| | | | _ |

Description of Defect :

| Description of the Defect : | Daimler AG, ("DAG") the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2017 E-Class AMG (213 platform) vehicles, the adjustment range of the passenger seat might not be limited correctly. |
|----------------------------------|--|
| FMVSS 1 : | NR |
| FMVSS 2 : | NR |
| Description of the Safety Risk : | In this case, the occupant load for certain seating positions on the front passenger seat might be increased. Thus an increased risk of injury for the front passenger during a crash cannot be ruled out. |
| Description of the Cause : | Due to an insufficient design of the front passenger seat mechanical limits and seating software calibration, the adjustment range might not be limited to meet current production specifications. |
| | |

Identification of Any Warning The customer will not receive an advance warning due to the nature of the that can Occur : failure mechanism.

Supplier Identification :

Component Manufacturer

Name : NR

Address : NR NR

Country: NR

Chronology :

In December 2016, DAG performed initial investigations based on failed internal certification crash tests in the development phase. These investigations indicated an incorrect limitation of the front passenger seat adjustment range as the root cause. Further analysis was initiated to define the necessary front passenger seat updates and changes in the seat control unit software to correctly limit the seat travel.

In February 2017, an updated seat control unit software was introduced.

In March 2017, a mechanical adjustment range limitation was added to the passenger seat design. Vehicles produced before installation of mechanical adjustment range limitation were reworked in the vehicle production or the vehicle preparation center prior to sale.

In July 2018, it was determined through routine monitoring that not all vehicles were reworked in the vehicle preparation center. The range of potentially affected vehicles in the field was determined in August, 2018 In the beginning of September 2018, DAG determined that a potential safety risk cannot be ruled out.

Description of Remedy :

| Description of Remedy Program : | As a precautionary measure an authorized Mercedes-Benz dealer will check the adjustment range of the passenger seat on the affected vehicles and install the mechanical adjustment range limitation or update the seat control unit software respectively. |
|---|---|
| | Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty. |
| How Remedy Component Differs from Recalled Component : | Vehicles equipped with passenger seats with correct adjustment range limitation. |

Part 573 Safety Recall Report

| | A change of the passenger seat design and an update of the seat control unit software ensures that this issue can no longer occur from September 27, 2017 onwards. |
|---|--|
| Recall Schedule : | |
| Description of Recall Schedule : | Dealers will be notified of the pending campaign in September 2018. A copy of all communications will be provided when available. |
| | Owners will be notified with a letter in late October 2018, approximately one week after recall launch to dealers. |
| Planned Dealer Notification Date : Planned Owner Notification Date : | |

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573