OMB Control No.: 2127-0004

Not sequential

Part 573 Safety Recall Report

18V-610

Manufacturer Name: Mercedes-Benz USA, LLC.

Submission Date: OCT 31, 2018 **NHTSA Recall No.:** 18V-610 **Manufacturer Recall No.:** 2018090014



Manufacturer Information:

Manufacturer Name: Mercedes-Benz USA, LLC.

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

Population:

Number of potentially involved : 4,702 Estimated percentage with defect : 10%

Vehicle Information:

Vehicle 1: 2018-2018 Mercedes-Benz GLC300 4MATIC Coupe

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: 253.349 0J4K 61 vehicles.

The recall population was determined through production records. Vehicles not affected by the recall have turn-signal lamps that display the correct color specified in

FMVSS 108 §6.1.2.

Production Dates: JAN 08, 2018 - MAR 12, 2018

VIN Range 1: Begin: NR End: NR

Vehicle 2: 2018-2018 Mercedes-Benz GLC300

Vehicle Type: LIGHT VEHICLES

Body Style : SUV Power Train : GAS

Descriptive Information: 253.948 0G4J 1808 vehicles.

The recall population was determined through production records. Vehicles not affected by the recall will have turn-signal lamps that display the correct color

specified in FMVSS 108 §6.1.2.

Production Dates: JAN 08, 2018 - MAR 18, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 3: 2018-2018 Mercedes-Benz GLC300 4MATIC

Vehicle Type: LIGHT VEHICLES

Body Style: SUV Power Train: GAS

Descriptive Information: 253.949 0G4K 2793 vehicles.

Descriptive Information :	The recall population was determined through production records. Vehicles not affected by the recall will have turn-signal lamps that display the correct color specified in FMVSS 108 §6.1.2.				
Production Dates :	IAN 08 2018 - N	MAR 12 2018			
VIN Range 1:		NR	End:	NR	☐ Not sequential
	208		2114 (
Vehicle 4:	2018-2018 Mercedes-Benz GLC350e 4MATIC				
Vehicle Type :	LIGHT VEHICLES				
Body Style :	SUV				
Power Train :	HYBRID ELECTRIC				
Descriptive Information :	253.954 0G5E 7 vehicles.				
	The recall population was determined through production records. Vehicles not affected by the recall will have turn-signal lamps that display the correct color specified in FMVSS 108 §6.1.2.				
Production Dates :					
VIN Range 1:	Begin:	NR	End:	NR	■ Not sequential
Vehicle Type : Body Style : Power Train : Descriptive Information :	GAS 253.364 0J6E 3 vehicles. The recall population was determined through production records. Vehicles not affected by the recall will have turn-signal lamps that display the correct color specified in FMVSS 108 §6.1.2. JAN 08, 2018 - MAR 12, 2018				
viiv kange 1.	begin.	NR	EIIU .	INK	☐ Not sequential
	GAS 253.964 0G6E 3	ES 80 vehicles.			ds Vahiclas not
	The recall population was determined through production records. Vehicles not affected by the recall will have turn-signal lamps that display the correct color specified in FMVSS 108 §6.1.2.				
Production Dates :					_
VIN Range 1:	Begin:	NR	End:	NR	☐ Not sequential

Description of Noncompliance:

Description of the Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has

Noncompliance: determined that on certain Model Year ("MY") 2018 GLC-Class (253 platform)

vehicles, equipped with LED headlamps, the front turn signal lights may be

pink/violet in color.

FMVSS 1: 108 - Lamps, reflective devices, and assoc. Equipment

FMVSS 2: NR

Description of the Safety Risk: Though the function of the turn indicators is not affected, the legal

requirements of FMVSS108 §6.1.2 may not be met.

Description of the Cause: Due to an error during manufacturing at the headlamp supplier, the visible

color spectrum of the turn signal LED may deviate from current production

specification.

Identification of Any Warning The customer may notice incorrect color of the turn signal LED lights when

that can Occur: locking or unlocking the vehicle.

Supplier Identification:

Component Manufacturer

Name: ZKW Lichtsysteme GmbH

Address: Scheibbser Straße 17

Wieselburg FOREIGN STATES 3250

Country: Austria

Chronology:

In March 2018, DAG initiated initial investigations based on a single vehicle detected in the production plant.

In April 2018, DAG, along with the headlamp supplier, analyzed the exemplar headlamp.

In May 2018, it was determined that a production deviation at the supplier resulted in damaged LED phosphor layers.

In June 2018, the supplier determined potentially affected batches of headlamps.

In July and August 2018, DAG determined the potentially affected vehicles equipped with the suspect headlamps.

In early September 2018, DAG determined that a potential non-compliance of subject vehicles regarding FMVSS 108 §6.1.2 cannot be excluded.

Description of Remedy:

Description of Remedy Program : As a precautionary measure, an authorized Mercedes-Benz dealer will

check the color of the turn signal on the affected LED headlamps, and

replace the LED module, if necessary.

Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles

remain covered under the new vehicle warranty.

How Remedy Component Differs Correct LED module according to specification.

from Recalled Component :

Identify How/When Recall Condition A change in the production procedure of our supplier ensures that this

was Corrected in Production: issue can no longer occur from April 6, 2018 onwards.

Recall Schedule:

Description of Recall Schedule: Dealers were notified of the pending recall on October 1, 2018, and again

when parts were available on October 26, 2018. A copy of all

communications will be provided when available.

Owners will be notified on November 2, 2018, one week after the recall

launch to dealers.

Planned Dealer Notification Date : OCT 01, 2018 - OCT 26, 2018 Planned Owner Notification Date : NOV 02, 2018 - NOV 02, 2018

^{*} NR - Not Reported