OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Subaru of America, Inc.Submission Date :SEP 13, 2018NHTSA Recall No. :18V-626Manufacturer Recall No. :WTV-81

Manufacturer Information :

Manufacturer Name : Subaru of America, Inc. Address : One Subaru Drive

Camden NJ 08103 Company phone : 856-488-8500

Vehicle Information :

Vehicle 1:	2010-2014 Subaru Legacy		
Vehicle Type :	LIGHT VEHICLES		
Body Style :	4-DOOR		
Power Train :	GAS		
Descriptive Information :	Description of the issue: A capacitor on the circuit board and/or the actuator stroke sensor magnetic ring, located in the control unit of electronic parking brake (EPB), may crack with vehicle use over time. If either component develops a crack, the brake telltale warning lamp illuminates, and the EPB may not apply as intended.		
	The basis for how the recall population was determined: All manual transmission vehicles.		
	How the recalled products differ from products that were not included in the recall: Products that were not included in the recall are equipped with an automatic transmission.		
	7,994 2010-14MY Subaru Legacy vehicles are affected.		
Production Dates .	DEC 10, 2008 - MAY 19, 2014		
VIN Range 1:			
viivitange 1.			
Vehicle Type : Body Style :			
Power Train :			
Descriptive Information :	Description of the issue: A capacitor on the circuit board and/or the actuator stroke sensor magnetic ring, located in the control unit of electronic parking brake (EPB), may crack with vehicle use over time. If either component develops a crack, the brake telltale warning lamp illuminates, and the EPB may not apply as intended.		
	The basis for how the recall population was determined: All manual transmission		
The information contained in this report was submitted pursuant to 49 CFR §573			



Number of potentially involved : 27,175 Estimated percentage with defect : 100 %

Population :

18V-626

Part 573 Safety Recall Report

v	ehicles.		
P	-	cts differ from products that w included in the recall are equip	
1	9,181 2010-14MY Sub	aru Outback vehicles are affect	ed.
Production Dates : M	IAR 16, 2009 - JUN 02,	2014	
VIN Range 1 : Be	egin : NR	End: NR	Not sequential
-	ring, located in the c	rcuit board and/or the actuato ontrol unit of electronic parkin r time. If either component de	g brake (EPB), may crack
Description of Defect : Description of the Defect	ring, located in the c	ontrol unit of electronic parkin	g brake (EPB), may crack
Description of the Defect	ring, located in the c with vehicle use ove telltale warning lam		g brake (EPB), may crack velops a crack, the brake
Description of the Defect FMVSS 1 FMVSS 2	ring, located in the c with vehicle use ove telltale warning lam NR NR	ontrol unit of electronic parkin r time. If either component de p illuminates, and the EPB may	ng brake (EPB), may crack velops a crack, the brake v not apply as intended.
Description of the Defect FMVSS 1 FMVSS 2	ring, located in the c with vehicle use ove telltale warning lam NR NR If the transmission s	ontrol unit of electronic parkin r time. If either component de p illuminates, and the EPB may hift lever is not in the recomme d the EPB does not engage, the	ng brake (EPB), may crack velops a crack, the brake not apply as intended. ended gear when the
Description of the Defect FMVSS 1 FMVSS 2	 ring, located in the c with vehicle use ove telltale warning lamp NR NR If the transmission s vehicle is parked and increasing the risk o Due to improper ma 	ontrol unit of electronic parkin r time. If either component de p illuminates, and the EPB may hift lever is not in the recomme d the EPB does not engage, the f a crash. nufacturing processes, a capac stroke sensor magnetic ring lo	ng brake (EPB), may crack velops a crack, the brake r not apply as intended. ended gear when the vehicle may roll away, itor on the circuit board

Supplier Identification :

Component Manufacturer

Name : Continental Automotive Corp.

Address :New Stage Yokohama 1-1-32
Shin-Urashimacho Kanagawa-Ku Yokoyama, Kanagawa FOREIGN STATES 221-0031Country :Japan

Chronology :

June 2018: Subaru Corporation notified Subaru of America, Inc of the dialog between Subaru Corporation and Japan's Ministry of Land, Infrastructure, and Transportation.

June 2018: Continental presented material related to the overseas investigation into the defects.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

18V-626

Page 3

June 2018-August 2018: Subaru assessed the United States product data related to this defect.

September 6, 2018: Subaru determined that a safety recall will be performed.

Description of Remedy :

Description of Remedy Program :	For all affected vehicles, replace the EPB actuator assembly with a remedied one.
	Regarding the remedy component, (1) the capacitor's material was changed to a more durable one, (2) the manufacturing process of the circuit board and actuator stroke sensor magnetic ring was improved, and (3) implemented tighter control of moisture content of the resin hub during production. Recalled Component Name: PARKING BRAKE ACTUATOR Recalled Component Description: PARKING BRAKE ACTUATOR Recalled Component Part numbers: 26002AJ01D, 26002AJ02C
Identify How/When Recall Condition was Corrected in Production :	•

Recall Schedule :

Description of Recall Schedule :	Owner notification will occur within 60 days. If parts are not available by that time, owners will be notified that parts are not available yet and they
	will be re-notified once parts are available.
Planned Dealer Notification Date :	SEP 14, 2018 - SEP 14, 2018
Planned Owner Notification Date :	NR - NR

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR \$573