

Part 573 Safety Recall Report

18V-667

Manufacturer Name : Suzuki Motor of America, Inc.**Submission Date :** NOV 07, 2018**NHTSA Recall No. :** 18V-667**Manufacturer Recall No. :** 4009**Manufacturer Information :****Population :**

Manufacturer Name : Suzuki Motor of America, Inc.

Number of potentially involved : 1,107

Address : 3251 East Imperial Highway
Brea CA 92821-6795

Estimated percentage with defect : 100 %

Company phone : 714-996-7040

Vehicle Information :

Vehicle 1 : 2006-2006 Suzuki Grand Vitara

Vehicle Type : LIGHT VEHICLES

Body Style : SUV

Power Train : GAS

Descriptive Information : A total of 1,107 vehicles produced during this production period were not previously included in the population of affected vehicles identified for recall 10V-250.

Production Dates : MAY 23, 2006 - JUN 16, 2006

VIN Range 1 : Begin :

NR

End : NR

☐ Not sequential**Description of Defect :**

Description of the Defect : The tension adjuster pulley for the drive belt that operates the power steering pump and air conditioner compressor (if equipped) has an outer portion that is made of plastic. Repeated heat stress can cause the plastic material to deteriorate and pieces of the pulley can break off. In the worst case, broken pieces of the pulley can get caught between the pulley and the drive belt, causing the drive belt to come off.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : If the drive belt that operates the power steering pump comes off, the driver will need increased effort to steer the vehicle, increasing the risk of a crash.

Description of the Cause : NR

Identification of Any Warning NR
that can Occur :

Supplier Identification :

Component Manufacturer

Name : NSK, Ltd.

Address : 1-6-3 Osaki Shinagawa-ku
Tokyo, Japan 141-8560 FOREIGN STATES

Country : Japan

Chronology :

The chronology of principal events is attached as a separate document.

Description of Remedy :

Description of Remedy Program : Suzuki distributors will conduct a safety recall campaign to replace the power steering pump drive belt tension adjuster pulley of affected vehicles with an improved part, if an improved part has not already been installed. SMAI's plan for reimbursing owners who may have paid for repairs to remedy the reported condition in advance of recall notification is attached as a separate document.

How Remedy Component Differs from Recalled Component : The outer portion of the remedy power steering pump drive belt tension adjuster pulley is made of metal rather than plastic. The part number of the recalled power steering pump drive belt tension adjuster pulley is 49160-66J00.

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : The recall will be conducted by the following U.S. distributors: Suzuki Motor of America, Inc., Suzuki Del Caribe, Inc. (Puerto Rico). Notification end dates were amended to accommodate a delay in notification for vehicles sold in Puerto Rico and U.S. territories. The delay is due to an oversight that resulted in U.S. territory VINs not being included in SMAI's original request for motor vehicle registration data.

Planned Dealer Notification Date : NOV 02, 2018 - NOV 23, 2018

Planned Owner Notification Date : NOV 09, 2018 - NOV 30, 2018

* NR - Not Reported