

# Part 573 Safety Recall Report

# 18V-694

**Manufacturer Name :** Suzuki Motor of America, Inc.**Submission Date :** OCT 04, 2018**NHTSA Recall No. :** 18V-694**Manufacturer Recall No. :** 2A86 - 2A88**Manufacturer Information :**

Manufacturer Name : Suzuki Motor of America, Inc.

Address : 3251 East Imperial Highway

Brea CA 92821-6795

Company phone : 714-996-7040

**Population :**

Number of potentially involved : 6,928

Estimated percentage with defect : 100 %

**Vehicle Information :**

Vehicle 1 : 2018-2018 Suzuki DL650A

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycle were determined based on vehicle production records. There are 236 motorcycles in this production date range.

Production Dates : DEC 05, 2017 - MAR 01, 2018

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 2 : 2017-2017 Suzuki DL650A

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 649 affected motorcycles in this production date range.

Production Dates : DEC 13, 2016 - FEB 28, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 3 : 2017-2017 Suzuki DL650XA

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 362 motorcycles in this production date range.

Production Dates : JAN 16, 2017 - MAY 10, 2017

VIN Range 1 : Begin :

NR

End : NR

 Not sequential

Vehicle 4 : 2018-2018 Suzuki GSX-S750

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on vehicle production records. There are 1,150 motorcycles in this production date range.

Production Dates : JAN 10, 2017 - MAR 02, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 5 : 2018-2018 Suzuki DL650XA

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 404 motorcycles in this production date range.

Production Dates : DEC 04, 2017 - MAR 19, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 6 : 2017-2017 Suzuki GSX-R1000

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on vehicle production records. There are 1,704 motorcycles in this production date range.

Production Dates : FEB 02, 2017 - SEP 13, 2017

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 7 : 2017-2017 Suzuki GSX-R1000R

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 762 affected motorcycles in this production date range.

Production Dates : MAR 10, 2017 - SEP 13, 2017

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 8 : 2018-2018 Suzuki GSX-R1000

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 622 affected motorcycles in this production date range.

Production Dates : SEP 14, 2017 - JAN 19, 2018

VIN Range 1 : Begin : NR End : NR  Not sequential

Vehicle 9 : 2018-2018 Suzuki GSX-R1000R

Vehicle Type : MOTORCYCLES

Body Style :

Power Train : GAS

Descriptive Information : Affected motorcycles were determined based on production records. There are 1,039 affected motorcycles in this production date range.

Production Dates : SEP 14, 2017 - MAY 30, 2018

VIN Range 1 : Begin :

NR

End : NR

Not sequential

## Description of Defect :

Description of the Defect : The design of the fuel pump O-ring and fuel tank inner vessel in affected vehicles can allow the fuel pump O-ring to be twisted during the fuel pump installation process.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : A twisted fuel pump O-ring can have reduced sealing performance, and in the worst case can cause a fuel leak. In the presence of an ignition source, leaked fuel can cause a fire.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

## Supplier Identification :

### Component Manufacturer

Name : NR

Address : NR

NR

Country : NR

## Chronology :

The chronology is attached as a separate document.

**Description of Remedy :**

Description of Remedy Program : Suzuki dealers will replace the fuel pump O-ring and fuel tank inner vessel with improved parts. A copy of Suzuki Motor of America Inc.'s plan for reimbursing owners who incurred costs for remedies of the reported defect in advance of recall notification is provided as a separate document.

How Remedy Component Differs from Recalled Component : The recalled fuel pump O-ring has a D-shaped cross-section and the remedy O-ring has a round cross-section. Ribs have been added to the remedy fuel tank inner vessel. The recalled fuel tank inner vessel does not have ribs. Following are the part numbers of the recalled components.

DL650, GSX-S750, GSX-R1000 fuel pump O-ring part number:  
15201-17K01

DL650, GSX-S750, GSX-R1000 fuel tank inner vessel part number:  
44121-28K00

Identify How/When Recall Condition was Corrected in Production : Use of the countermeasure fuel pump O-ring in production began on June 1, 2018. Use of the countermeasure fuel tank inner vessel in production began on June 21, 2018.

**Recall Schedule :**

Description of Recall Schedule : The recall will be conducted by the following authorized Suzuki motorcycle distributors in the U.S.: Suzuki Motor of America, Inc. - continental U.S.; Montgomery Motors, Ltd. - Hawaii; Suzuki Del Caribe, Inc. - Puerto Rico

Planned Dealer Notification Date : OCT 15, 2018 - OCT 15, 2018

Planned Owner Notification Date : OCT 19, 2018 - OCT 19, 2018

\* NR - Not Reported