OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-717

Manufacturer Name: Mazda North American Operations

Submission Date: AUG 24, 2020 NHTSA Recall No.: 18V-717 Manufacturer Recall No.: 1317F



Manufacturer Information:

Manufacturer Name: Mazda North American Operations

Address: 1025 Connecticut Avenue, NW

Suite 910 Washington DC 20036

Company phone: 800-222-5500

Population:

Number of potentially involved: 155,436

Estimated percentage with defect: 1 %

Vehicle Information:

Vehicle 1: 2010-2013 Mazda Mazda6

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: These vehicles are MY2011-2013 Mazda6 registered in zone B and MY2010-2013

Mazda6 registered in Zone C. The recall population was determined based on vehicle manufacturing records at Mazda Motor Corporation. Plant information; Auto Alliance International plant in Flat Rock, Michigan, USA. Each population by model year is as follows; MY2010 Mazda6: 6,793 units. MY2011 Mazda6: 12,192 units. MY 2012

Mazda6: 17,001 units. MY2013 Mazda6: 5,902 units.

Production Dates: JUN 22, 2009 - AUG 24, 2012

 VIN Range 1: Begin: 1YVHZ8CB6A5M00020 End: 1YVHZ8CH1A5M58864

 VIN Range 2: Begin: 1YVHZ8CB5B5M00012 End: 1YVHZ8BH2B5M30736

 VIN Range 3: Begin: 1YVHZ8CB9C5M00001 End: 1YVHZ8EH7C5M44239

VIN Range 4: Begin: 1YVHZ8CH4D5M00008 End: 1YVHZ8EH1D5M17345

☐ Not sequential☐ Not sequential

☐ Not sequential

■ Not sequential

Vehicle 2: 2010-2015 Mazda CX-9				
Vehicle Type: LIGHT VEHICLES				
Body Style: SUV				
Power Train: GAS				
Descriptive Information: These vehicles are MY2014-2015 CX-9 registered in Zone A and MY2011-2015 CX-9 registered in zone B and MY2010-2015 CX-9 registered in Zone C. The recall population was determined based on vehicle manufacturing records at Mazda Motor Corporation. Plant information; Hiroshima plant of Mazda Motor Corporation in Japan. Each population by model year is as follows; MY2010 CX-9: 5,935 units. MY2011 CX-9: 14,755 units. MY 2012 CX-9: 16,326 units. MY2013 CX-9: 9,660 units. MY2014 CX-9: 19,543 units. MY 2015 CX-9: 18,813 units.				
Production Dates: JUL 28, 2009 - AUG 26, 2015				
VIN Range 1: Begin: JM3TB3MA2A0200009 End: JM3TB3MV5A0238708				
VIN Range 2: Begin: JM3TB2CA7B0300006 End: JM3TB2CA9B0333119				
VIN Range 3: Begin: JM3TB3CA1C0333123 End: JM3TB3DV9C0369269 Not sequential				
VIN Range 4: Begin: JM3TB3DV7D0400004 End: JM3TB2CV4D0425227				
VIN Range 5 : Begin : JM3TB2CAXE0425229 End : JM3TB3DV9E0447150 ☐ Not sequential				
VIN Range 6: Begin: JM3TB3DA2F0447151 End: JM3TB2CA5F0469768				
Vehicle 3: 2010-2012 Mazda CX-7				
Vehicle Type: LIGHT VEHICLES				
Body Style: SUV				
Power Train: GAS				
Descriptive Information : These vehicles are MY2011-2012 CX-7 registered in Zone B and MY2010-2012 CX-7 registered in zone C. The recall population was determined based on vehicle manufacturing records at Mazda Motor Corporation. Plant information; Hiroshima plant of Mazda Motor Corporation in Japan. Each population by model year is as follows; MY2010 CX-7: 5,530 units. MY2011 CX-7: 18,868 units. MY 2012 CX-7: 4,118 units.				
Production Dates: APR 06, 2009 - DEC 16, 2011				
VIN Range 1: Begin: JM3ER4WLXA0300044 End: JM3ER2WM8A0352947 Not sequential				
VIN Range 2: Begin: JM3ER4D32B0353048 End: JM3ER4DLXB0410354				
VIN Range 3: Begin: JM3ER2B5XC0410395 End: JM3ER2CMXC0422049				

Description of Defect:

Description of the Defect: Under terms of the Amendment to November 3, 2015 Consent Order issued May 3, 2016, Takata is scheduled to submit Defect Information Report (DIR) #4 on non-desiccated frontal PSAN inflators at the end of 2018. Mazda has decided to submit DIR#4 at this time because permanent remedy replacement parts have become available earlier than anticipated. This submission adds affected vehicles under DIR#4 to the existing recall population covered by Mazda recalls 17V429 (DIR#1) and 17V457 (DIR#2) and 18V018 (DIR#3). For Zone A: MY2014 and MY2015 vehicles are added. For Zone B: MY2011 through 2015 vehicles are added. For Zone C: MY2010 through MY2015 vehicles are added. The PSPI6 air bag inflator, equipped in these subject Mazda vehicles, may potentially rupture during passenger side air bag deployment due to propellant degradation occurring after prolonged exposure to high absolute humidity, high temperatures, and high temperature cycling.

> FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Activation of a non-desiccated ammonium nitrate inflator with degraded propellant may result in an inflator rupture. An inflator rupture may cause metal fragments to pass through the air bag and into the vehicle interior at high speed, which may result in injury or death to vehicle occupants.

Description of the Cause: The propellant wafers in the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the air bag is activated. Overly aggressive combustion creates excessive internal pressure when the inflator is activated, which may cause the inflator body to rupture. Based on Takata's investigation to date, the potential for such ruptures occur after several years of exposure to persistent conditions of high absolute humidity, high temperatures, and high temperature cycling. The potential for rupture may also be influenced by other factors, including the specific vehicle environment, the inflator and propellant configuration, and manufacturing variability.

Identification of Any Warning NR

that can Occur:

Involved Components:

Component Name 1: NR Component Description: NR

Component Part Number: NR

Supplier Identification:

Component Manufacturer

Name: Takata / T K Holding INC.

Address: 888 16th street, NW

Suite 800 DISTRICT OF COLUMBIA 20006

Country: United States

Chronology:

(See the attached Chronology.pdf for preceding chronological events.)

Updated July 27 2020 – This amendment is to inform of Mazda's intent to implement the "other" reporting category for removed vehicles in Quarterly Reporting as permitted in the Third Amendment to the Coordinated Remedy Order ("ACRO"), Paragraphs 45 through 49. As a condition of the ACRO, all affected vehicles will remain active, or "live", across Mazda's data systems such that any search of "other" removed VINs will return an open recall status. For this reason, the Number of potentially involved vehicles in this report will remain the same. However, for reference, initial counts of vehicles in the "other" reporting category are indicated in attached supplement. Note that these counts are current as of the second calendar quarter 2020. Future changes to overall Total Removed counts, including "Other," will be reflected in quarterly reporting as well as monthly dashboard reporting until otherwise directed by the agency.

Description of Remedy:

Description of Remedy Program: Owners of record will be notified of this issue and instructed to take their

vehicles to a Mazda dealer for repair. The dealer will replace the frontal passenger side air bag inflator with modified one. The repair will be

performed free of charge to the vehicle owners.

How Remedy Component Differs Recalled Parts Name: Air bag inflator manufactured by Takata. Part

from Recalled Component: number: EGZ1-57K80, TDY1-57K80, GSYL-57K80.

The remedy parts are the air bag inflator manufactured by other-than-Takata parts supplier and confirmed to be free from phase-stabilized

ammonium nitrate.

Identify How/When Recall Condition NR

was Corrected in Production:

Recall Schedule:

Description of Recall Schedule: The draft owner notification letter is attached.

Planned Dealer Notification Date : OCT 12, 2018 - OCT 12, 2018 Planned Owner Notification Date : NOV 12, 2018 - NOV 12, 2018

Part 573 Safety Recall Report	18V-717	Page 5
* NR - Not Reported		
The information contained in this report was submitted		