OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-723

Manufacturer Name: Keystone RV Company

Submission Date: OCT 15, 2018 NHTSA Recall No.: 18V-723 Manufacturer Recall No.: 18-334



Manufacturer Information:

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN

46527

Company phone: 574-535-2100

Population:

Number of potentially involved: 1,276 Estimated percentage with defect: 100 %

Vehicle Information:

Vehicle 1: 2019-2019 Dutchmen Aerolite 2513RLF,2573BH,2733RB,2843BH,2923BH,3153ML

Vehicle Type: TRAILERS

Body Style: Power Train: NR

Descriptive Information: Models with 4400 pound axles

Model Aerolite 48 units.

Production Dates: JUL 09. 2018 - AUG 15, 2018

VIN Range 1: Begin: 4YDT28426KP910390 End: 4YDT28424KP910498 ✓ Not sequential

Vehicle 2: 2019-2019 Dutchmen Atlas 2922BH,2952RLF,3112BHF,3132ML

Vehicle Type: TRAILERS

Body Style: Power Train: NR

Descriptive Information: Models with 4400 pound axles

Model Atlas 68 units.

Production Dates: JUL 09, 2018 - AUG 02, 2018

VIN Range 1: Begin: 4YDT31322KP960127 End: 4YDF31123KP960203 **✓** Not sequential

Vehicle 3: 2019-2019 Keystone Bullet 1750RK,1900RD,30RIPR,330BHS,34BIPR,34RIPR

Vehicle Type: TRAILERS

Body Style: Power Train: NR

Descriptive Information: Models with 4400 pound axles

Model Bullet 120 units.

Production Dates: JUL 11. 2018 - AUG 01. 2018

VIN Range 1: Begin: 4YDT34B27KD432233 End: 4YDT33026KT432145 **✓** Not sequential Vehicle 4: 2019-2019 Keystone Laredo 255SRL,290SRL,291SMK,292BH,296SBH,298SRL,330RL

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with 4400 pound axles

Model Laredo 60 units

Production Dates: JUL 10, 2018 - AUG 07, 2018

VIN Range 1: Begin: 4YDF29628KE600591 End: 4YDF29129KE600690 ✓ Not sequential

Vehicle 5: 2019-2019 Keystone Cougar

22RBS,25RES,26RBS,26RKS,27RES,27RLS,27SAB,27SGS,28SGS,29BHS,29RDB,29RKS,

29RLD

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with 4400 pound axles

Model Cougar 405 units.

Production Dates: JUN 26, 2018 - AUG 07, 2018

VIN Range 1: Begin: 4YDF29R24K1502372 End: 4YDF25R22KV504736 ✓ Not sequential

Vehicle 6: 2019-2019 Keystone Hideout

28BHS,28RKS,30RLDS,318LHS,31FBDS,31RBDS,32RDDS,338LHS,33BHDS,38BHDS,3

8FDDS

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with 4400 pound axles

Model Hideout 106 units

Production Dates: JUL 12, 2018 - AUG 10, 2018

VIN Range 1 : Begin : 4YDT30R24K7243293 End : 4YDT31829K7245290
✓ Not sequential

Vehicle 7: 2019-2019 Keystone Passport 175BH,2950BH,3290BH,3320BH,3350BH

Vehicle Type: TRAILERS

Body Style :

Power Train: NR

Descriptive Information: Models with 4400 pound axles

Model Passport 63 units.

Production Dates: JUL 09, 2018 - AUG 01, 2018

VIN Range 1 : Begin : 4YDT17513KK412020 End : 4YDT33228KK412370 ✓ Not sequential

Vehicle 8: 2019-2019 Keystone Springdale

240BH,253FWRE,274RB,27TH,280BH,298BH,300FWBH,302FWRK,303BH,311RE

Vehicle Type: TRAILERS

Body Style:

Power Train: NR

Descriptive Information: Models with 4400 pound axles

Model Springdale units 299

Production Dates: JUL 23, 2018 - AUG 14, 2018

Vehicle 9: 2019-2019 Crossroads Sunset 250RK,330SI,331BH,336BH,33SI

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with 4400 pound axles

Model Sunset 107 units.

Production Dates: JUL 09, 2018 - AUG 07, 2018

VIN Range 1: Begin: 4YDT25026K5350791 End: 4YDT25024K5351079 ✓ Not sequential

Description of Defect:

Description of the Defect: It has been decided that the vehicles in the recall population may not have a

bearing cup installed in the bearing assembly.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Under certain conditions during travel, if the bearing cup is not installed it

could lead to a bearing failure, leading to an increased risk of property

damage and poor vehicle handling.

Description of the Cause: The bearing cup was not installed in the hub during the manufacturing process.

Identification of Any Warning If the bearing cup is missing the hub may initially heat up. If this were to occur,

that can Occur: the hub may start to smoke from burning grease. The wheel may become

wobbly if the bearing starts to fail.

Supplier Identification:

Component Manufacturer

Name: Dexter Axle Address: PO Box 250

Elkhart INDIANA 46515

Country: United States

Chronology:

8/20/2018 – Dexter Axle contacted Keystone and started an inspection of units that had not yet been shipped. Dexter Axle stated that an investigation was being conducted on missing bearing cups. Units with D-44 axles were put on hold until inspected and defect contained going forward by Dexter Axle.

10/5/2018 – Keystone received an official letter stating that D-44 axles were being recalled. A request was made to Dexter Axle to provide specific part shipments to determine scope and conclude investigation of affected vehicles.

10/10/2018 - Proper documentation was given by Dexter Axle to determine affected unit range.

10/11/2018 - Investigation concluded and scope completed.

Description of Remedy:

Description of Remedy Program: The remedy is to inspect axles for hub clearance. If hub clearance is not

sufficient, appropriate parts will be provide to correct the defect.

How Remedy Component Differs The remedy part has the appropriate bearing assembly installed.

from Recalled Component:

Identify How/When Recall Condition Units were quarantined, inspected then repaired as indicated by

was Corrected in Production: inspection.

Recall Schedule:

Description of Recall Schedule: Keystone will notify the dealers and owners of the recreational vehicles

by letter. A final copy of the owner letter will be provided to NHTSA,

along with the dealer repair procedures.

Planned Dealer Notification Date : DEC 11, 2018 - DEC 11, 2018 Planned Owner Notification Date : DEC 11, 2018 - DEC 11, 2018

* NR - Not Reported