OMB Control No.: 2127-0004

Part 573 Safety Recall Report

18V-743

Manufacturer Name: Daimler Vans USA, LLC

Submission Date: MAR 15, 2019 **NHTSA Recall No.:** 18V-743

Manufacturer Recall No.: NR



Manufacturer Information:

Manufacturer Name: Daimler Vans USA, LLC

Address: One Mercedes-Benz Drive

Sandy Springs GA 30328

Company phone: 854-888-3214

Population:

Number of potentially involved: 76 Estimated percentage with defect: 30 %

Vehicle Information:

Vehicle 1: 2018-2018 Freightliner Sprinter

Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN
Power Train : DIESEL

Descriptive Information: Daimler AG became aware of this issue in July 2018 by a notification from the

assembly plant Düsseldorf. The affected population was determined as being produced in the period of time between the relevant dates mentioned above. The

vehicles concerned can be identified based on production information.

The recall population refers to the NAFTA Sprinter vehicles (Platform 906) that might have been equipped with an incorrect operating lever as a subcomponent of the door

locks on the right side of the vehicle.

Other NAFTA Sprinter vehicles (Platform 906) have already been equipped with the correct door looks and have been produced outside the affected production period

July 04, 2018 and July 19, 2018.

Mercedes-Benz and Freightliner Sprinter vehicles (Platform 906) will be equipped

with the correct door looks on the right side of the vehicle.

Production Dates: JUL 04, 2018 - JUL 19, 2018

VIN Range 1 : Begin : NR End : NR Not sequential

Vehicle 2: 2018-2018 Mercedes-Benz Sprinter Vehicle Type: BUSES, MEDIUM & HEAVY VEHICLES

Body Style : VAN
Power Train : DIESEL

Descriptive Information: Daimler AG became aware of this issue in July 2018 by a notification from the

assembly plant Düsseldorf. The affected population was determined as being produced in the period of time between the relevant dates mentioned above. The

vehicles concerned can be identified based on production information.

Not sequential

The recall population refers to the NAFTA Sprinter vehicles (Platform 906) that might have been equipped with an incorrect operating lever as a subcomponent of the door locks on the right side of the vehicle.

Other NAFTA Sprinter vehicles (Platform 906) have already been equipped with the correct door looks and have been produced outside the affected production period July 04, 2018 and July 19, 2018.

Mercedes-Benz and Freightliner Sprinter vehicles (Platform 906) will be equipped with the correct door looks on the right side of the vehicle.

Production Dates: JUL 04, 2018 - JUL 19, 2018

VIN Range 1 : Begin : NR End : NR

Description of Defect:

Description of the Defect: Daimler AG (DAG), the manufacturer of Mercedes-Benz Vans, has determined

that in certain Mercedes-Benz and Freightliner Sprinter vehicles for the NAFTA market, for the door locks on the right side of the vehicle, an incorrect

operating lever might have been installed as a subcomponent.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: When the driver's door, cargo door and rear door are electronically unlocked,

the corresponding doors on the right side of the vehicle cannot always be opened from inside and outside the vehicle. Exiting the vehicle on the left side of the vehicle is possible during normal driving operation. This could increase

the risk of injury in the event of a crash.

Description of the Cause: Due to a fault in the production of a sub-supplier, an incorrect operating lever

as a subcomponent of the lock has been installed in the lock for the right side of the vehicle. All main locks (passenger hinged door, load compartment sliding door, hinged rear door) only on the right side of the vehicle may be affected. Due to geometric variations on the operating lever, the clutch lever may not be able to fall behind the designated driving hook on the operating lever after locking and unlocking. In this case, the door lock would remain locked. The door would then be electronically unlocked, but might not be opened from the

inside and outside.

Dynamic movement of the door handle allows the door lock function to be restored temporarily and consequently the door can be unlocked and opened.

Identification of Any Warning A customer does not receive any advance warning.

that can Occur:

Supplier Identification:

Component Manufacturer

Name : Kiekert AG Address : Hoseler Platz 2

Heiligenhaus FOREIGN STATES 42579

Country: Germany

Chronology:

Daimler AG became aware of this issue in July 2018 by a notification from the assembly plant Düsseldorf.

Upon identification, analysis and evaluation as to the root cause and impact of this issue were commenced.

On October 12, 2018, Daimler AG decided to initiate a recall campaign based on the results of the preceding analysis and evaluation.

To date Daimler AG is aware of 13 complaints concerning this matter from the field.

Description of Remedy:

Description of Remedy Program : An authorized Mercedes-Benz or Freightliner Sprinter dealer will check

and replace the locks if necessary.

Pursuant to 49 C.F.R. § 577.11(e), Daimler Vans does not plan to provide

notice about pre-notice reimbursement to owners since all involved

vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs Mercedes-Benz and Freightliner Sprinter vehicles (Platform 906) will be

from Recalled Component: equipped with the correct door looks on the right side of the vehicle.

Identify How/When Recall Condition Immediately after recognizing the issue, a function test was set up by the

was Corrected in Production: supplier for the affected lock types.

Recall Schedule:

Description of Recall Schedule: Owners will be notified approximately one week after the recall launch to

the dealers.

Dealers will be notified of the pending voluntary recall campaign in

December 2018. A copy of all communications will be provided when

available.

Planned Dealer Notification Date: DEC 03, 2018 - DEC 03, 2018

Planned Owner Notification Date: DEC 11, 2018 - DEC 11, 2018

18V-743	Page 4
	18V-743 pursuant to 49 CFR §573