#### OMB Control No.: 2127-0004

# Part 573 Safety Recall Report

# 18V-843

**Manufacturer Name:** Keystone RV Company

**Submission Date:** JAN 16, 2019 NHTSA Recall No.: 18V-843 Manufacturer Recall No.: 19-340



### **Manufacturer Information:**

Manufacturer Name: Keystone RV Company

Address: PO Box 2000

2642 Hackberry Drive Goshen IN

46527

Company phone: 574-535-2100

# **Population:**

Number of potentially involved: 982 Estimated percentage with defect: 100 %

#### **Vehicle Information:**

Vehicle 1: 2019-2019 Dutchmen Aerolite 2513RLF, 2683RK, 2733RB

Vehicle Type: TRAILERS

**Body Style:** Power Train: NR

Descriptive Information: Models with D44 axles.

Model Aerolite 39 units.

Production Dates: SEP 19, 2018 - OCT 16, 2018

VIN Range 1: Begin: 4YDT27326KP910594 End: 4YDT27321KP910650 ✓ Not sequential

Vehicle 2: 2019-2019 Dutchmen Atlas 2922BH, 2952RLF, 3112BHF, 3132ML

Vehicle Type: TRAILERS

**Body Style:** Power Train: NR

Descriptive Information: Models with D44 axles.

Model Atlas 64 units.

Production Dates: SEP 12, 2018 - OCT 16, 2018

VIN Range 1: Begin: 4YDF29521KP960275 End: 4YDF3112XKP960375 **✓** Not sequential

Vehicle 3: 2019-2019 Keystone Bullet 243BHS, 248RKS, 257RSS, 261RBS, 269RLS, 273BHS,

287QBS, 290BHS, 308BHS

Vehicle Type: TRAILERS

**Body Style:** Power Train: NR

Descriptive Information: Models with D35 axles.

Model Bullet 86 units.

Production Dates: SEP 14, 2018 - SEP 26, 2018

VIN Range 1: Begin: 4YDT29023KT433534 End: 4YDT30821KT433819 **✓** Not sequential Vehicle 4: 2019-2019 Keystone Cougar 22RBS, 25RES, 26RBS, 26RKS, 27RES, 27SAB, 27SGS,

29BHS, 29RDB, 29RKS, 29RLD

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with D44 axles.

Model Cougar 228 units.

Production Dates: SEP 10, 2018 - SEP 27, 2018

VIN Range 1: Begin: 4YDT29B24KV506072 End: 4YDT26R2XKV506940 ✓ Not sequential

Vehicle 5: 2019-2019 Keystone Hideout 272LHS, 274LHS

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with D35 axles.

Model Hideout 35 units.

Production Dates: SEP 13, 2018 - SEP 19, 2018

VIN Range 1 : Begin : 4YDT27427K7245283 End : 4YDT27227K7245478 ✓ Not sequential

Vehicle 6: 2019-2019 Keystone Outback 210URS, 221UMD, 240URS, 260UML, 280URB, 299URL

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with D35 axles.

Model Outback 149 units.

Production Dates: SEP 13, 2018 - OCT 16, 2018

Vehicle 7: 2019-2019 Keystone Passport 175BH, 197RB, 199ML, 216RD, 2210RB, 239ML,

240BH, 2521RL, 2710RB, 2820BH, 2950BH

Vehicle Type: TRAILERS

Body Style : Power Train : NR

Descriptive Information: Models with D35 axles.

Model Passport 228 units.

Production Dates: SEP 11, 2018 - OCT 12, 2018

VIN Range 1: Begin: 4YDT23921KD413518 End: 4YDT2162XKK413408 ✓ Not sequential

Vehicle 8: 2019-2019 Keystone Springdale 280BH, 282BH, 293RK, 296BH, 298BH, 303BH,

311RE

Vehicle Type: TRAILERS

Body Style : Power Train : NR Descriptive Information: Models with D44 axles.

Model Springdale 153 units.

Production Dates: SEP 11, 2018 - OCT 09, 2018

VIN Range 1: Begin: 4YDT29327K3103228 End: 4YDT29321K3103905 ✓ Not sequential

# **Description of Defect:**

Description of the Defect: It has been decided that the vehicles in the recall population may have an axle

built with bearings that have insufficient grease.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: Under certain conditions during travel, the bearing can heat up and fail

leading to an increased risk of property damage and poor vehicle handling.

Description of the Cause: During the manufacturing process of the axle, the bearings may have been

installed with insufficient grease.

Identification of Any Warning Wheel hubs heating up or visible discoloration of the hub.

that can Occur:

# **Supplier Identification:**

# **Component Manufacturer**

Name: Dexter Axle Address: PO Box 250

Elkhart INDIANA 46515

**Country: United States** 

### **Chronology:**

11/6/2018 – Report was made by Dexter that a run of axles produced on 9/10/2018 was produced with insufficient bearing grease.

11/7/2018 - Investigation opened. All affected units were put on hold and axles were inspected.

11/14/2018 – Keystone received the defect notice from Dexter Axle with POs to determine shipping dates.

11/20/2018 – Investigation concluded and scope completed.

## **Description of Remedy:**

Description of Remedy Program: The remedy is inspect the axle tag to determine if the axle is affected

according to the manufacturing date. If the affected manufacturing date is

9/10/2018, the bearing will need to be removed and inspected.

How Remedy Component Differs Bearings will be repacked with sufficient amount of grease as described in

from Recalled Component: the field repair from Dexter.

Identify How/When Recall Condition Units were quarantined, inspected then repaired as indicated by

was Corrected in Production: inspection.

#### **Recall Schedule:**

Description of Recall Schedule: Keystone will notify the dealers and owners of the recreational vehicles

by letter. A final copy of the owner letter will be provided to NHTSA,

along with the dealer repair procedures.

Planned Dealer Notification Date : JAN 20, 2019 - JAN 20, 2019 Planned Owner Notification Date : JAN 20, 2019 - JAN 20, 2019

<sup>\*</sup> NR - Not Reported