### OMB Control No.: 2127-0004

# **Part 573 Safety Recall Report**

Manufacturer Name: Blue Bird Body Company Submission Date : DEC 11, 2018 NHTSA Recall No.: 18V-880 Manufacturer Recall No.: R19ZU-SB

# **Manufacturer Information :**

Manufacturer Name : Blue Bird Body Company Address: P.O. Box 937 **402 Blue Bird Boulevard Fort Valley** GA 31030 Company phone : 478-822-2242

# **Vehicle Information :**

Vehicle 1:	2019-2019 Blue Bird All American				
Vehicle Type :	BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :					
Power Train :	CNG/LPG				
Descriptive Information :	On certain 2019 All Americans, there is the potential of an unintended disengagement of the parking brake cable that sets the hydraulic parking brake from the retention clevis on the foot pedal assembly.				
Production Dates :	APR 10, 2018 - JU	N 13, 2018			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential
Vehicle 2:	2019-2019 Blue I	Bird Vision			
Vehicle Type :	Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES				
Body Style :	OTHER				
Power Train :	CNG/LPG				
Descriptive Information :	On certain 2019 Visions, there is the potential of an unintended disengagement of the parking brake cable that sets the hydraulic parking brake from the retention clevis on the foot pedal assembly.				
Production Dates :	MAR 08, 2018 - JI	JN 23, 2018			
VIN Range 1:	Begin :	NR	End :	NR	Not sequential

### **Description of Noncompliance :**

Description of the There is the potential of an unintended disengagement of the parking brake Noncompliance : cable that sets the hydraulic parking brake from the retention clevis on the foot pedal assembly. In the event that the parking brake cable becomes dislodged, there is an increase possibility of unintended movement when the vehicle is parked.

The information contained in this report was submitted pursuant to 49 CFR §573



Number of potentially involved : 469 Estimated percentage with defect : 100%

**Population**:

# 18V-880

FMVSS 1 :	105 - Hydraulic and electric brake systems
FMVSS 2 :	NR
Description of the Safety Risk :	In the event that the parking brake cable becomes dislodged, there is an increase possibility of unintended movement when the vehicle is parked.
Description of the Cause :	A root cause investigation was conducted and determined the issue was due to the shape of the slot in the retention clevis of the new pedal assembly, as well as, slack in the cable. The slack is caused due to friction between the cable and the cable sheathing at the bends in the cable routing.
Identification of Any Warning that can Occur :	There is no audible or visual warning, which would precede an event

#### **Supplier Identification :**

#### **Component Manufacturer**

Name : NR Address : NR NR Country : NR

#### **Chronology** :

On May 17, 2018, a Vision chassis rolled off the BBCV Chassis Assembly line due to an unintended disengagement of the cable that sets the hydraulic parking brake from the retention clevis in the new foot pedal assembly.

On May 21, 2018, Blue Bird issued a stop ship to inspect and address this issue as required on all hydraulic brake buses on property. An interim corrective action was implemented the same date to retain the cable in the parking brake pedal clevis with a clip.

In October 2018, Blue Bird determined that this condition could potentially exist on 473 buses. The corrective action proposed for units in the field is to install the clevis cable retention clip and a cable-end return spring to prevent the cable from disengaging from pedal retention clevis and to remove slack in the cable to return the cable to the completely released position.

The information contained in this report was submitted pursuant to 49 CFR \$573

# Part 573 Safety Recall Report

# **Description of Remedy** :

Description of Remedy Program :	The corrective action is to install the clevis cable retention clip and a cable- end return spring to prevent the cable from disengaging from pedal retention clevis and to remove slack in the cable to return the cable to the completely released position.	
How Remedy Component Differs from Recalled Component :	NR	
Identify How/When Recall Condition was Corrected in Production :	NR	

# **Recall Schedule :**

Description of Recall Schedule :	Parts should be available February, 2019
Planned Dealer Notification Date :	FEB 11, 2019 - FEB 11, 2019
Planned Owner Notification Date :	FEB 11, 2019 - FEB 11, 2019

\* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR  $\S573$