OMB Control No.: 2127-0004

Not sequential

# Part 573 Safety Recall Report

# 18V-909

Manufacturer Name: Mercedes-Benz USA, LLC.

**Submission Date:** FEB 01, 2019 **NHTSA Recall No.:** 18V-909 **Manufacturer Recall No.:** 2018120025



#### **Manufacturer Information:**

Manufacturer Name: Mercedes-Benz USA, LLC.

Address: 13470 International Parkway

Jacksonville FL 32218

Company phone: 1-877-496-3691

# **Population:**

Number of potentially involved : 675 Estimated percentage with defect : 100 %

#### **Vehicle Information:**

Vehicle 1: 2019-2019 Mercedes Benz C43 AMG

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: 205.064 WF6E 99 Vehicles

The recall population was determined through production records. Unaffected

vehicles have correct software installed.

Production Dates: JUL 05, 2017 - NOV 26, 2018

VIN Range 1: Begin: NR End: NR

Vehicle 2: 2019-2019 Mercedes Benz C300

Vehicle Type: LIGHT VEHICLES

Body Style: 4-DOOR Power Train: GAS

Tower Hum. und

Descriptive Information: 205.083 WF8D 26 Vehicles

The recall population was determined through production records. Unaffected

vehicles have correct software installed.

Production Dates: JUL 05, 2017 - NOV 26, 2018

Vehicle 3: 2019-2019 Mercedes Benz C300 4MATIC

Vehicle Type: LIGHT VEHICLES

Body Style : 4-DOOR Power Train : GAS

Descriptive Information: 205.084 WF8E 38 Vehicles

The recall population was determined through production records. Unaffected

vehicles have correct software installed.

Production Dates :	JUL 05. 2017 - N	OV 26. 2018						
VIN Range 1:		NR	End:	NR	☐ Not sequential			
Vehicle Type : Body Style : Power Train :								
Production Dates : VIN Range 1 :		OV 26, 2018 NR	End:	NR				
Vehicle Type : Body Style : Power Train :								
Production Dates : VIN Range 1 :		OV 26, 2018 NR	End:	NR	☐ Not sequential			
Vehicle Type : Body Style : Power Train :	Vehicle 6: 2019-2019 Mercedes Benz C300 4MATIC Coupe Vehicle Type: LIGHT VEHICLES Body Style: 2-DOOR Power Train: GAS criptive Information: 205.384 WJ8E 72 Vehicles The recall population was determined through production records. Unaffected vehicles have correct software installed.							
Production Dates : VIN Range 1 :		OV 26, 2018 NR	End:	NR	☐ Not sequential			
	GAS 205.464 WK6E 4 The recall popul vehicles have co	S 46 Vehicles ation was deter rrect software i	rmined	through production record	ls. Unaffected			

# **Part 573 Safety Recall Report**

18V-909

Page 3

VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential			
Vehicle 8: 2019-2019 Mercedes Benz C300 Cabrio								
Vehicle Type :	LIGHT VEHICLE	S						
Body Style :	2-DOOR							
Power Train:	GAS							
Descriptive Information :	205.483 WK8D	134 Vehicles						
	The recall population was determined through production records. Unaffected vehicles have correct software installed.							
Production Dates:	JUL 05, 2017 - NOV 26, 2018							
VIN Range 1:	Begin :	NR	End:	NR	☐ Not sequential			
Vehicle 9: 2019-2019 Mercedes Benz C300 4MATIC Cabrio								
Vehicle Type :	LIGHT VEHICLE	S						
Body Style :								
Power Train :								
Descriptive Information :	205.484 WK8E 64 Vehicles The recall population was determined through production records. Unaffected vehicles have correct software installed.							
Production Dates: JUL 05, 2017 - NOV 26, 2018								
VIN Range 1:	Begin :	NR	End:	NR				

#### **Description of Defect:**

Description of the Defect: Daimler AG, ("DAG"), the manufacturer of Mercedes-Benz vehicles, has

determined that on certain Model Year ("MY") 2019 C-Class facelift vehicles (205 platform) the sleep mode functionality within the ESP-Software might not

meet current production specification.

FMVSS 1: NR FMVSS 2: NR

Description of the Safety Risk: In case the customer removes the ignition key and leaves the vehicle, the

sleep mode functionality of the ESP is initiated according to specification. Should this process be interrupted by a signal, the ESP control unit would not be reinitialized as intended. In this case the brake light would be permanently activated and a corresponding warning message would be displayed in the instrument cluster. Furthermore the ESP-function would be deactivated and

the current status of the park brake could not be changed.

The park brake is automatically activated after parking upon opening of the driver door. Therefore, in most cases of an incomplete re-initialization of the

ESP control unit, the vehicle could no longer be driven.

Should - in contrary to the security measure instructions against unintended rolling - the parking brake be deactivated by the customer, the vehicle could

still be driven without ESP-functionality being available. In this case the risk

of a crash would be increased.

However, DAG is only aware of customer complaints describing a

permanently activated park brake.

Description of the Cause: Due to an incorrect coding of the ESP-Software by a supplier the sleep mode

functionality within the ESP-Software might not meet current specification.

Identification of Any Warning NR

that can Occur:

### **Supplier Identification:**

### **Component Manufacturer**

Name: ZF Group

Address: Carl-Spaeter-Straße 8

**Koblenz FOREIGN STATES 56070** 

Country: Germany

## **Chronology:**

In the end of June 2018, DAG launched initial investigations based on internal findings in a production plant where the park brake of a vehicle could not be deactivated.

In July 2018, first results of these investigations indicated an incorrect coding of the ESP-Software as the root cause. Further analyses were performed including the determination of potential impacts of the incorrect coding of the ESP-Software. It was found that the incorrect coding resulted in an impaired sleep mode functionality of the ESP-system.

The analysis was extended to examine field complaints that could be associated with the issue.

In October 2018, these investigations showed that an interruption of the sleep mode functionality of the ESPsystem after vehicle parking might in certain cases lead to a disabled control of the park brake and a deactivation of the ESP-function.

In November 2018, the range of potentially affected vehicles was determined.

In the beginning of December 2018, DAG determined that a potential safety risk cannot be ruled out, as a scenario where the customer leaves the vehicle with deactivated park brake could not completely be ruled out.

#### **Description of Remedy:**

Description of Remedy Program: As a precautionary measure, an authorized Mercedes-Benz dealerwill update the ESP-Software. Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.

How Remedy Component Differs Vehicles equipped with updated ESP-Software.

from Recalled Component:

Identify How/When Recall Condition A change in the ESP-Software ensures that this issue can no longer occur

was Corrected in Production: from November 29, 2018 onwards.

#### **Recall Schedule:**

Description of Recall Schedule: Dealers will be notified of the pending voluntary recall campaign in

Janaury 2019. Owners will be notified approximately one week after

recall launch to the dealers in February 2019. A copy of all

communications will be provided when available.

Planned Dealer Notification Date : JAN 04, 2019 - NR Planned Owner Notification Date : JAN 29, 2019 - NR

<sup>\*</sup> NR - Not Reported