



MERCEDES-BENZ USA, LLC One Mercedes-Benz Dr. Sandy Springs, GA, 30328 Phone: (770) 705-0600 Fax: (770) 705-0117 MBUSA.com

newschannel update

To: Mercedes-Benz Dealer Principals, General	FROM: Gregory Gunther, Department Manager,
Managers, Sales Managers, Service Managers, Parts	Vehicle Compliance and Analysis, Engineering
Managers	Services
RE: Recall Campaign Launch Notification Rear Window Bonding MY18 205 (C-Class)	DATE: October 26, 2018

IMPORTANT RECALL CAMPAIGN INFORMATION



Campaign No.:

Customer Notification Timeline

AOMS/SOMS

Rental Fleet Partners

RECALL CAMPAIGN LAUNCH NOTIFICATION

Campaign Desc. :

campaign no	campaign beser.	Rework Rear Window Bonding		
2018100003	1808P67C52	Nework Near William Bollaing		
	III be visible on the <u>www.safer</u>	car window bonding on 387 Model Year ("MY") 2018 C-Class (205 platform) car.gov website and may generate questions from customers. Affected VINs II as "OPEN" on October 26, 2018.		
	В	ackground		
Issue	certain MY 2018 C- current production decreased long-ter			
What We're Doing		MBUSA will conduct a voluntary recall. An authorized Mercedes-Benz dealer will rework the rear window bonding on your vehicle.		
Parts	Parts are available	Parts are available and can be ordered as necessary.		
	Vehi	icles Affected		
Vehicle Model Year(s)	2018	2018		
Vehicle Model	C-Class	C-Class		
	Vehic	le Populations		
Total Recall Population	387	387		
Total Vehicles in Dealer Inve	entory 61			
this notification until the vehice Instructions will b Loaner and den	cle has been repaired. Once te available in Star TekInfo On monstrator vehicles may conti	sell or lease any new MY18 C-Class vehicles in dealer inventory covered by he remedy is available, the vehicles will be flagged as "OPEN" and Work ce the repair is complete, the vehicle may be sold or leased. nue to be driven, but must not be retailed until repaired. for car rental companies to rent new MY18 C-Class vehicles covered by this the vehicle has been repaired.		
Next Steps/Notes				

While we regret any inconvenience this may cause, MBUSA is determined to maintain a high level of vehicle quality and customer satisfaction. Please refer all customer inquiries to the Customer Assistance Center at 1-800-FOR-MERCEDES.

available.

your dealers ASAP.

preferred MBUSA dealer.

Customer letters will be mailed approximately one week after the remedy becomes

AOMs – This recall may generate questions from your dealers. Please forward this notice to

This recall may affect vehicles in your fleet. Please contact your respective MBUSA fleet

representative for further information and next steps. For repairs, please contact your

Recall Campaign Bulletin



Campaign No. 2018100003, October 2018

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model C-Class (205 platform) Model Year 2018

Replace rear window bonding

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2018 C-Class (205 platform) vehicles, the rear window bonding might not meet current production specification. Incorrect bonding of the rear window could lead to decreased long-term adhesion of the rear window. This could lead to the rear window detaching from the vehicle, creating a road hazard and increasing the risk of a crash for following traffic. An authorized Mercedes-Benz dealer will rework the rear window bonding on the affected vehicles.

Prior to performing this Recall Campaign:

- Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns **do not expire** and may also be performed on a vehicle with a vehicle status indicator.

Approximately 387 vehicles are involved.

Order No. P-RC-2018100003

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Procedure

1. Replace rear window bonding.

i For basic data, see AR67.20-P-2000LW.

Replace rear window if it is damaged during removal.

Primary Parts Information

Qty.	Part Name	Part Number	Estimated Replacement Rate
1	RS windshield installation 1-component adhesive	A 000 670 01 00	100%
3	Lower rear window sealing strip	A 000 987 45 66 08	100%
As required (3)	Upper rear window support for code 413	A 222 678 00 79	
As required (1)	Rear window	A 205 670 61 00	

Warranty Information

Operation: Replace rear window bonding Includes: Remove/install rear window (02-2605)

Replace rear window (rear window removed)(02-2606)

OR: Submit as SUBLET utilizing sublet code of SUB with required amount.*

Damage Code	Operation Number	Labor Time (hrs.)
67 900 47 7	02-2605	1.7
	02-2606	0.1

i Note:

Operation Number labor times are subject to change.

^{*}Sublet amount may not exceed equivalent labor cost.

^{*}If sublet billed for repair, repair cannot be billed for op-codes and vice versa.