

David J. Johnson
Director
Service Engineering Operations
Ford Customer Service Division

Ford Motor Company P. O. Box 1904 Dearborn, Michigan 48121

November 2, 2018

TO: All U.S. Ford and Lincoln Dealers

SUBJECT: Safety Recall 18S34

Certain 2010 Fusion and 2010-2012 MKZ Vehicles

Passenger Airbag Module Replacement

AFFECTED VEHICLES

| Vehicle | Model Year | Assembly Plant | Build Dates | |
|---------|------------|----------------|---|--|
| MKZ | 2010-2012 | Hermosillo | March 10, 2009 through July 16, 2012 | |
| Fusion | 2010 | Hermosillo | February 26, 2010 through June 21, 2010 | |

This safety recall affects less than 250 vehicles listed above. Affected vehicles are identified in OASIS and FSA VIN Lists. Additional VINs may be added as vehicles are identified as having affected passenger airbag modules installed.

REASON FOR THIS SAFETY RECALL

In all of the affected vehicles, a passenger airbag module with a part number of AE5Z-54044A74-C or AH6Z-54044A74-C was previously installed while completing FSA 16S26, 17S01, or 18S01. The inflator in the passenger airbag module may not remain fully supported during airbag deployment in the event of a crash. This could result in incomplete airbag inflation and may increase the risk of an injury.

SERVICE ACTION

Dealers are to replace the passenger airbag module. This service must be performed on all affected vehicles at no charge to the vehicle owner.

NOTE: All replaced passenger airbag modules must be returned for analysis.

In addition, dealers are to identify any vehicles serviced at your dealership that had affected part number AE5Z-54044A74-C or AH6Z-54044A74-C installed as part of FSA 16S26, 17S01, or 18S01. It is important that all affected vehicles are identified and receive this service action. If dealership records indicate that an affected part was installed, and the vehicle is not identified in OASIS as being affected under this FSA, dealers should:

- Submit a VIN-specific web contact to the Special Service Support Center (SSSC) under 18S34
 using contact type 'Non-Involved'. Please provide repair order documentation showing the use
 of the part on the vehicle.
- Contact the owner and arrange a service date.

OWNER NOTIFICATION MAILING SCHEDULE

Owner letters are expected to be mailed the week of November 12, 2018. Dealers should repair any affected vehicles that arrive at their dealerships, whether or not the customer has received a letter.

PLEASE NOTE:

Federal law requires dealers to complete this recall service before a new vehicle is delivered to the buyer or lessee. Violation of this requirement by a dealer could result in a civil penalty of up to \$21,000 per vehicle. Correct all vehicles in your new vehicle inventory before delivery.

ATTACHMENTS

Attachment I: Administrative Information

Attachment II: Labor Allowances and Parts Ordering Information

Attachment III: 2010 Fusion Technical Information
Attachment IV: 2010-2012 MKZ Technical Information
Attachment V: Airbag Module Core Return Process

QUESTIONS & ASSISTANCE

For questions and assistance, contact the Special Service Support Center (SSSC) via the SSSC Web Contact Site. The SSSC Web Contact Site can be accessed through the Professional Technician Society (PTS) website using the SSSC link listed at the bottom of the OASIS VIN report screen or listed under the SSSC tab.

Sincerely,

David J. Johnson

Safety Recall 18S34

Certain 2010 Fusion and 2010-2012 MKZ Vehicles Passenger Airbag Module Replacement

OASIS ACTIVATION

OASIS will be activated on November 1, 2018.

FSA VIN LISTS ACTIVATION

FSA VIN Lists will be available through https://web.fsavinlists.dealerconnection.com by November 1, 2018. Owner names and addresses will be available by November 23, 2018.

NOTE: Your FSA VIN Lists may contain owner names and addresses obtained from motor vehicle registration records. The use of such motor vehicle registration data for any purpose other than in connection with this recall is a violation of law in several states, provinces, and countries. Accordingly, you must limit the use of this listing to the follow-up necessary to complete this recall.

SOLD VEHICLES

- Ford has not issued instructions to stop selling/delivering or driving used vehicles under this safety recall. Owners should contact their dealer for an appointment to have their vehicles remedied as soon as practicable. Owners can continue to safely drive their vehicles if they follow all instructions and warnings contained in the recall notice.
- Owners of affected vehicles will be directed to dealers for repairs.
- Immediately contact any of your affected customers whose vehicles are not on your VIN list but are identified in OASIS. Give the customer a copy of the Owner Notification Letter (when available) and schedule a service date.
- Correct other affected vehicles identified in OASIS which are brought to your dealership.
- Dealers are to prioritize repairs of customer vehicles over repairs of new and used vehicle inventory.

STOCK VEHICLES

Use OASIS to identify any affected vehicles in your used vehicle inventory.

DEALER-OPERATED RENTAL VEHICLES

The Fixing America's Surface Transportation (FAST) Act law effective June 2016 prohibits a rental company from selling, renting or leasing vehicles subject to a safety or compliance recall. Please consult your legal counsel for legal advice.

TITLE BRANDED / SALVAGED VEHICLES

Affected title branded and salvaged vehicles are eligible for this recall.

OWNER REFUNDS

Refunds are not approved for this program.

RENTAL VEHICLES

With proper dealer parts ordering and service appointment scheduling, rental vehicles should not be required. If a customer <u>requests</u> a rental vehicle while their vehicle is being repaired, dealers are preapproved for up to 4 days for a comparable rental vehicle. Rentals will be reimbursed at a dollar rate of up to \$44 per day for Ford owners and \$55 per day for Lincoln owners.

Approval for more than 4 rental days is required from the SSSC via the SSSC Web Contact Site. The SSSC must be provided total rental and repair costs, including parts and labor, to approve the full RO line amount.

Safety Recall 18S34

Certain 2010 Fusion and 2010-2012 MKZ Vehicles
Passenger Airbag Module Replacement

ADDITIONAL REPAIR (LABOR TIME AND/OR PARTS)

Additional repairs identified as necessary to complete the FSA should be managed as follows:

- For related damage and access time requirements, refer to the Warranty and Policy Manual / Section 6 – Ford & Lincoln Program Policies / General Information & Special Circumstances for FSA's / Related Damage.
- Submit an Approval Request to the SSSC Web Contact Site prior to completing the repair.

CLAIMS PREPARATION AND SUBMISSION

- Claim Entry: Enter claims using Dealer Management System (DMS) or One Warranty Solution (OWS) online.
 - When entering claims, select claim type 31: Field Service Action. The FSA number (18S34) is the sub code.
 - o For additional claims preparation and submission information, refer to the Recall and Customer Satisfaction Program (CSP) Repairs in the OWS User Guide.

NOTE: The serial number of the <u>new</u> passenger airbag module must be provided to Ford for the claim to be processed. The Technical Information in this bulletin advises technicians to document the serial number from the new airbag Module on the repair order. The passenger airbag module serial number is 13 characters. Enter the serial number of the new airbag Module or module in the claim as follows:

- For claims submitted using DMS or OWS on-line, enter the serial numbers in the Test Results Section.
 - Select DTC REQUIRED MEASUREMENT OR RESULTS from the drop down list.
 - Enter serial number in the CODE field without spaces or dashes.
- Related Damage/Additional labor and/or parts: Must be claimed as Related Damage on a separate repair line from the FSA with same claim type and sub code as described in Claim Entry above. IMPORTANT: Click the Related Damage Indicator radio button.
- Rental Vehicle Reimbursement
 - o If the customer is already in a rental vehicle as part of FSA 16S26, 17S01, or 18S01, follow the rental claiming guidelines in that respective FSA Dealer Bulletin.
 - o If the customer is not already in a rental vehicle under another FSA, dealers are preapproved for up to 4 days of rental vehicle reimbursement. Approval for more than 4 rental days under FSA 18S34 is required from the Special Service Support Center (SSSC) and can be requested after repairs are completed. The SSSC must be provided total rental and repair costs, including parts and labor, to approve the full line amount.
 - Rental expenses must be claimed on the same claim, and the same line as the repair.
 Enter the total amount of the rental expense under Misc. Expense Code "RENTAL".

Safety Recall 18S34

Certain 2010 Fusion and 2010-2012 MKZ Vehicles Passenger Airbag Module Replacement

LABOR ALLOWANCES

| Description | Labor Operation | Labor Time | |
|---|-----------------|------------|--|
| Replace Passenger Airbag Module – Fusion vehicles | 18S34B | 2.8 Hours | |
| Replace Passenger Airbag Module – MKZ vehicles | 18S34C | 3.0 Hours | |

PARTS REQUIREMENTS / ORDERING INFORMATION

This safety recall affects less than 250 vehicles. To ensure an equitable distribution of service parts, the SSSC will proactively place part orders for affected vehicles to dealers that previously installed the affected passenger airbag module. These part orders will include all required parts and can be viewed in DOES II. These orders are expected to start shipping by November 12, 2018.

If your dealer is not included in the proactive part orders or additional parts are needed, submit a VINspecific Part Order contact via the SSSC Web Contact Site.

| Part Number | Description | Order Quantity | Claim Quantity |
|-----------------|--|-------------------|-------------------|
| AE5Z-54044A74-D | Passenger Airbag Module – Fusion vehicles only | 1 | 1 |
| AH6Z-54044A74-D | Passenger Airbag Module – MKZ vehicles only | 1 | 1 |
| W711044-S403 or | A Dillor Trim Clin | 4 | 2 |
| W711044-S439 | A-Pillar Trim Clip | I | 2 |
| W712961-S439 | Steering Column Shaft-to-Steering Gear Bolt | 1 | 1 |

NOTE: Passenger airbag module part number AE5Z-54044A74-D includes a white airbag cushion sheet in the packaging. This sheet is not used during this service procedure and can be discarded. Dealers will be notified via a DOES II communication if circumstances warrant a change in part supply strategy and when open ordering resumes.

DEALER PRICE

For latest prices, refer to DOES II.

PARTS RETENTION AND RETURN

It is critical that all original passenger airbag inflators removed from vehicles are not allowed back into the market. Therefore, all passenger airbag inflators under this safety recall have been assigned a \$100 core charge to ensure they will be properly returned.

The Regional Core Recover Center (RCRC), **including dealers in Alaska and Hawaii**, will pick up these airbag inflators along with all other core returns during your normal core retrieval visit.

For additional information, refer to the attachment: Airbag Module Core Return Process.

IMPORTANT: Any <u>new</u> stock of part numbers AE5Z-54044A74-C or AH6Z-54044A74-C previously utilized under FSA 16S26, 17S01, and 18S01 must no longer be installed in vehicles, and can be returned following the instructions in EFC06992, published October 18, 2018 on FMCDealer.

EXCESS STOCK RETURN

Excess stock returned for credit must have been purchased from Ford Customer Service Division in accordance with Policy Procedure Bulletin 4000.

CERTAIN 2010 FUSION VEHICLES — PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

In all of the affected vehicles, a passenger airbag module was previously installed while completing FSA 16S26, 17S01, or 18S01. The inflator in the passenger airbag module may not remain fully supported during airbag deployment in the event of a crash. This could result in incomplete airbag inflation and may increase the risk of an injury. Dealers are to replace the passenger airbag module.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2010 Fusion vehicles. Repair instructions are published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



MARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.

1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.




FIGURE 1

- 2. Remove the left hand and right hand A-Pillar trim panels. Reuse the LH and RH trim panels for this repair. See Figure 2.
 - To prevent damage to the trim panel, grasp the trim panel approximately 5 inches from the top and pull downward toward the door, then rotate the panel inward toward the windshield to slide it off of the a-pillar clip.

NOTE: Do not bend or flex the trim panels during removal to avoid stress marks from occurring.

NOTE: To view a video demonstration of this repair procedure, click the video icon.



FIGURE 2

3. Remove and discard the top A-Pillar clip from the body. Retain the screw for re-use. See Figure 3.





FIGURE 3

- 4. Remove the passenger airbag module. Please refer to Workshop Manual (WSM) procedures in section 501-20B.
 - Remove the instrument panel crossmember-to-airbag module bracket. See Figure 4.
 - Torque to 80 lb. in.

MARNING: Do not allow any debris on or around the instrument panel once the airbag is removed.



1801D

FIGURE 4

- 5. Install the new airbag module and instrument panel. Please follow WSM procedures in section 501-20B.
 - Install the instrument panel crossmember-to-airbag module bracket. See Figure 4.

6. Install the new A-Pillar trim panel clip onto the trim panel. See Figure 5.

NOTE: If the new A-Pillar trim panel clips are not equipped with a screw installed, re-use the screw from the original clip from step 3. Install the screw into the new clip by hand.

• Torque to 9 lb.in.




FIGURE 5

- 7. Install the LH and RH A-Pillar trim panels by aligning the attachment clips to the holes and snapping the new trim panel in place.
- 8. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.

NOTE: The new passenger airbag module includes a white airbag cushion sheet in the packaging. This sheet is not used during this service procedure and can be discarded.

CERTAIN 2010 — 2012 MKZ VEHICLES — PASSENGER AIRBAG MODULE REPLACEMENT

OVERVIEW

In all of the affected vehicles, a passenger airbag module was previously installed while completing FSA 16S26, 17S01, or 18S01. The inflator in the passenger airbag module may not remain fully supported during airbag deployment in the event of a crash. This could result in incomplete airbag inflation and may increase the risk of an injury. Dealers are to replace the passenger airbag module.

SERVICE PROCEDURE

NOTE: The following repair instructions only apply to 2010 – 2012 MKZ vehicles. Repair instructions are published in separate attachments for other vehicle lines included in this recall as parts become available for those vehicles.

NOTE: The parts used in this safety recall may physically appear to be identical, but they have differing operating characteristics. It is crucial that parts are not interchanged or substituted.



MARNING: Failure to follow the instructions and warnings in the Workshop Manual (WSM) may result in injury.

NOTE: If the Airbag Readiness light indicates no Supplemental Restraint System (SRS) faults are present, it is not necessary to follow the WSM SRS Depowering and Repowering steps. Turn the ignition to OFF and wait 1 minute, then it is safe to proceed with airbag inflator replacement.

NOTE: The ignition must remain OFF until this service procedure is completed.

1. Record the 13 character serial number of the new airbag module on the repair order. See Figure 1.




FIGURE 1

- 2. Remove the left hand and right hand A-Pillar trim panels. Reuse the LH and RH trim panels for this repair. See Figure 2.
 - To prevent damage to the trim panel, grasp the trim panel approximately 5 inches from the top and pull downward toward the door, then rotate the panel inward toward the windshield to slide it off of the a-pillar clip.

NOTE: Do not bend or flex the trim panels during removal to avoid stress marks from occurring.

NOTE: MKZ A-Pillar trim is wrapped in fabric, be sure to protect the fabric from stains when removing.

NOTE: To view a video demonstration of this repair procedure, click the video icon.



FIGURE 2

3. Remove and discard the top A-Pillar clip from the body. Retain the screw for re-use. See Figure 3.




FIGURE 3

- 4. Remove the passenger airbag module. Please refer to Workshop Manual (WSM) procedures in section 501-20B.
 - Remove the instrument panel crossmember-to-airbag module bracket. See Figure 4.
 - Torque to 80 lb. in.




FIGURE 4

- 5. If a white airbag cushion sheet has been installed previously, remove the bracket from the instrument panel and discard the sheet. See Figure 5.
 - Torque to 80 lb.in.




FIGURE 5

- 6. Reinstall the airbag module bracket onto the instrument panel. See Figure 5.
- 7. Install the new airbag module and instrument panel. Please follow WSM procedures in section 501-20B.
 - Install the instrument panel crossmember-to-airbag module bracket. See Figure 4.

8. Install the new A-Pillar trim panel clip onto the trim panel. See Figure 7.

NOTE: If the new A-Pillar trim panel clips are not equipped with a screw installed, re-use the screw from the original clip from step 3. Install the screw into the new clip by hand.

• Torque to 9 lb.in.




FIGURE 7

- 9. Install the LH and RH A-Pillar trim panels by aligning the attachment clips to the holes and snapping the new trim panel in place.
- 10. Package the replaced airbag module in the new part box and provide to the appropriate dealership personnel for part returns.

AIRBAG MODULE CORE RETURN PROCESS

DEALER PART RETURN INSTRUCTIONS AND SHIPPING DOCUMENTATION

Parts used under safety recall 18S34 have a core charge and will be identified as such with the yellow core label on the packaging. The Regional Core Recover Center (RCRC), including dealers in Alaska and Hawaii, will pick up these airbag inflators along with all other core returns during your normal core retrieval visit.

THE AIRBAG INFLATOR REMOVED FROM THE VEHICLE MUST BE RETURNED IN THE NEW REPLACEMENT INFLATOR PACKAGING.

- Ensure that you have processes in place to safeguard the packaging.
- The Dealer provided Haz-Mat Materials must also be returned in the packaging.
- RCRCs will not accept any airbag inflators without correct packaging or Haz-Mat documentation.
- The new replacement service part packaging is certified with the appropriate DOT marks and labels.
- Ensure that all marks and labels are present prior to tendering to the RCRC for core credit.

Airbag Inflator Haz-Mat Return Instructions

Print and provide both of the following completed documents to the RCRC driver:

- 1. Hazardous Materials Shipping Document (Page 2)
 - a. In the box titled Shipper, enter your dealership name and address.
 - b. In the box titled Receiver, enter the address of your Regional Core Recovery Center.
 NOTE: Page 4 contains a list of RCRC locations. If you are unsure of which RCRC location serves your dealership, please consult the RCRC driver.
 - c. In the box titled **Number/Type of Package**, enter the number of boxed airbag inflators.
 - d. In the box titled **Weight**, enter the total shipment weight of all boxed airbag inflators.
 - e. At the bottom of the Hazardous Materials Shipping Document, complete the Shipper's Certification.
- 2. North American Emergency Response Guide 171 (Page 3)

HAZARDOUS MATERIALS SHIPPING DOCUMENT - GROUND TRANSPORTATION

| | SHIPPER | RECEIVER | | |
|---|---|---|---|--|
| Dealership Name | :: | Ford Motor Company | | |
| | | Regional Core Recovery Cer | iter | |
| Address: | | Address: | | |
| | | | | |
| | | | | |
| Phone: | | Phone: | | |
| 24-HOUR EMER | GENCY CONTACT: INFOTRAC 1-8 | 300-535-5053 (Domestic) 1-352-323-3500 (Inter | national) | |
| hazmat packaging shipping documer CFR (10) Sign ship (12) Segregate ha it holds hazardous Also, pursuant to | g (4) Properly close hazmat packaging (5) at (8) Provide and maintain emergency resping document to certify shipment is in cozardous material from incompatible cargos materials. 49 CFR an employer must ensure any emp | azard class of the material (2) Select authorized hazmat Properly mark the package (6) Properly label the packa sponse information (9) Review shipping paper to verify of informance to 49 CFR (11) Load hazardous material in to to (13) Select, provide or affix placards to transport vehic ployee performing any function affecting the transport of the employee performs and must be retrained every thirty | ge (7) Prepare compliance to 49 ransport vehicle cle to indicate that | |
| | DOT SI | nipping Description | | |
| Number/Type of Package | IN Number Droper Chinning Name Hazard (Jace Dacking Group W/P | | Weight | |
| Box(es) | UN3268, S | Safety Devices, Class 9 | Lbs. | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| classified, desc | ribed, packaged, marked and labe e applicable regulations of the De | | tion | |
| NAME: | SIGNATU | IRE:DA | A <i>TE:</i> _ | |

| GUIDE 171 | or later or later or protect | Page 281 |
|---|--|----------|
| ERG2012 Substances (Low to Moderate Hazard) | FIRE Small Fire Small Fire Unity Fire Water spray, fog or regular foam. Do not scarbin spilled material with ligh pressure water streams. Water spray, fog or regular foam. Do not scarbin spilled material with ligh pressure water streams. Mave containers with flooding quantities of water until well after fire is out. Withdraw mimicalishy in case of rising sound from venting safety devices or discoloration of tank. ALWAY'S stay away from tanks engulied in life. Stop leafy five can do it without risk. Stop leafy five can do it without risk. Stop leafy five can do it without risk. Small Day Spill With clear with a sand or other non-combustible absorbent material and place into containers from spill area. Small Spill Use to writh sand or other non-combustible absorbent material and place into containers from spill area. Small Spill Use by with sand or other non-combustible absorbent material and place into containers from spill area. Small Spill Use by with sand or other non-combustible absorbent material and place into containers from spill Whove widn to fresh air. Cover powder spill for later disposal. Wow widn to fresh air. Gover powder spill with plastic sheet or tap to minimize spreading. Present entry into waterways, sewers, basements or confined areas. FIRST ALID Wow widn to fresh air. Give affiliar respiration if victur is not breathing. Administer oxygen if breathing is difficult. Remove and isolate contaminated dothing and shoes. In case of contact with substance, immediately flush skin or eyes with running water for at least 20 minutes. Ensure that medical personnel are aware of the material(s) involved and take precautions to protect themselves. Ensure that medical personnel are aware of the material(s) involved and take precautions to protect themselves. | |
| ERG2012 | oing Paper not ack cover. ast 50 meters arce shown irections; also, | |
| GUIDE Substances (Low to Moderate Hazard) | FIRE OR EXPLOSION Some may but moting in eadily. Some may but not but none ignile readily. Some may but but none ignile readily. Some may be transported hot. HEALTH Contains may septode when heated. Indiation of Asbestos dust may have a damaging effect on the lungs. Inhalation of Asbestos dust may have a damaging effect on the lungs. Inhalation of Asbestos dust may have a damaging effect on the lungs. Inhalation of Asbestos dust may have a damaging effect on the lungs. Some liquids produce vapors that may cause ofdiziness or suffocation. Bundf from fire control may cause polithinion. PUBLIC SATATY CALL EMERGENCY RESPONSE Telephone Number on Shipping Paper first. If Shipping Paper not available or no answer, refer to appropriate telephone number listed on the inside back cover. As an immediate presculatory measure, isolate spill or leak area in all directions for at least 50 meters (150 feet) for fiquids and at least 25 meters (75 feet) for solids. Say upwind. Natural religibitars grotective dothing will only provide finited protection. Structural inergiptars protective dothing will only provide finited protection. Scholl solid the materials, increase, in the downwind direction, as necessary, the isolation distance shown under PUBLIC SAFETY. Fire this int car or tank truck is involved in a fire, ISOLATE for 800 meters (1/2 mile) in all directions; also, consider initial evacuation for 800 meters (1/2 mile) in all directions. | |
| GUIDE 171 | FIRE OR EXPLOSION Some may burn but non Containers may explod Some may be transport HEALTH Inhalation of material may contact may cause burn Contact may cause burn Contact may cause burn Had the may produce initiat Some liquids produce or relative may produce in the may produce or some liquids produce or answer of the may produce or some liful to may produce in the control or supplied or no answer or supplied or no answer or supplied in the may produce or supplied in the control or supplied in the light or suppl | Page 280 |

| RCRC Locations | | | | | |
|----------------|--------|------------------------------------|---------------|-------|-------|
| RCRC | | KCKC Locations | | | |
| CODE | Parent | Address | City | State | Zip |
| 00708 | HPD | 2511 Lovi Rd B/L 3/3A | FREEDOM | PA | 15042 |
| 01183 | HPD | 20501 PENNSYLVANIA ROAD STE 140 | BROWNSTOWN | MI | 48192 |
| 01326 | HPD | 9040 BURROUGH DOVER LANE | PENNSAUKEN | NJ | 08110 |
| 01615 | AER | 144 MAKAALA ST | HILO | Н | 96720 |
| 01728 | AER | 1123 Buffalo Run | Missouri City | TX | 77489 |
| 01729 | AER | 5915 CORRIDOR PARKWAY | SCHERTZ | TX | 78154 |
| 02276 | AER | 4300 Round Lake Rd. W. Unit 200 | ARDEN HILLS | MN | 55112 |
| 02454 | AER | 1605 SURVEYOR BLVD. | CARROLLTON | TX | 75006 |
| 03001 | AER | 8333 WASHINGTON PL NE Suite E | ALBUQUERQUE | NM | 87113 |
| 03199 | AER | 7103 E. 47TH AVE. Dr. | DENVER | СО | 80216 |
| 03956 | FMP | 300 Calais Dr STE #1 | ANCHORAGE | AK | 99503 |
| 04861 | AER | 5503 F ST | OMAHA | NE | 68117 |
| 05399 | FJ | 1002 South 56th Ave | PHOENIX | AZ | 85043 |
| 05495 | AER | 4161 DIXON AVE | DES MONIES | IA | 50313 |
| 05514 | HPD | 3645 DEVELOPERS RD. | INDIANAPOLIS | IN | 46227 |
| 06201 | FJ | 1040 S Rockefeller | Ontario | CA | 91761 |
| 06583 | AER | 600 South Theresa Ave. | ST LOUIS | МО | 63103 |
| 06586 | FJ | 11515 Granite St | CHARLOTTE | NC | 28273 |
| 06615 | HPD | 8242 SANDY COURT | JESSUP | MD | 20794 |
| 06952 | FJ | 7145 INDUSTRIAL | EL PASO | TX | 79915 |
| 06953 | FJ | 550 Gills Drive | ORLANDO | FL | 32824 |
| 06954 | FJ | 5286 Georgia Hwy 85, Suite 200 | FOREST PARK | GA | 30297 |
| 06955 | FJ | 545 Ford Avenue | JACKSON | MS | 39209 |
| 06959 | FJ | 6200 SW 29th Ste A | OKLAHOMA CITY | OK | 73179 |
| 07089 | FJ | 4304 Eubank Road | RICHMOND | VA | 23231 |
| 07748 | AER | 1049 KIKOWAENA PLACE | HONOLULU | HI | 96819 |
| 07953 | AER | 231 PAPA ST. | KAHULUI | HI | 96732 |
| 08263 | AER | 11 Chapin Road, Unit A | PINE BROOK | NJ | 07058 |
| 08453 | AER | 18637 72nd Ave S | KENT | WA | 98032 |
| 08454 | AER | 5220 N. E. 152ND PLACE | PORTLAND | OR | 97230 |
| 08587 | AER | 2999 MILLER STREET | SAN LEANDRO | CA | 94577 |
| 08731 | AER | 8250 NE Underground Dr. Pillar 153 | KANSAS CITY | MO | 64161 |
| 08858 | AER | 2233 S. 1800 WEST | WEST VALLEY | UT | 84119 |
| 09001 | AER | 3311 CORPORATE DR | JOLIET | IL | 60431 |
| 09121 | HPD | 444 WHITNEY ST | NORTHBOROUGH | MA | 01532 |
| 09252 | HPD | 1901 LEMOYNE AVE. | SYRACUSE | NY | 13208 |