# **TECHNICAL INSTRUCTIONS**

# FOR

# SAFETY RECALL GOR

# FRONT PASSENGER AIRBAG INFLATOR MODULE

# **CERTAIN 2010 MY 4RUNNER**

# **UPDATE 7-17-18**

#### Update 07-17-18

- The Technician Certification Requirements have changed

Update 4-18-18

- The parts section has been updated


All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to have successfully completed E-Learning course SC18A (if you had previously completed E-Learning Course SC18A, you do not have to take SC18A), in addition to "Safety Recall and Service Campaign Essentials", and currently hold at least one of the following certifications levels:

- Toyota Certified (Electrical)
- Toyota Expert (Any Specialty)
- Master
- Master Diagnostic Technicians

Always check which technicians can perform the recall remedy by logging on to <u>https://www.uotdealerreports.com</u>. It is the dealership's responsibility to select technicians with the above certification level or greater to perform this repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.


# I. OPERATION FLOW CHART

The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow *ALL* steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



## **II. BACKGROUND**

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. According to Takata, the propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause inflator rupture during airbag deployment. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.



## **III. IDENTIFICATION OF AFFECTED VEHICLES**

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

## **IV. PREPARATION**

#### A. PARTS

Model	Part Number	Part Description	Quantity
	04007-14335	Instrument Panel Airbag Module	1
4Runner	62220-35030-B0	Left Front A-Pillar Garnish (Gray)	1*
	62220-35030-E0	Left Front A-Pillar Garnish (Sand)	

## OR

Model	Part Number	Part Description	Quantity
	04007-58135	Instrument Panel Airbag Module	1
4Runner	62220-35030-B0	Left Front A-Pillar Garnish (Gray)	- 1*
	62220-35030-E0	Left Front A-Pillar Garnish (Sand)	

\*The left front A-Pillar garnish needs to be replaced on vehicles manufactured prior to August 2013. Only one garnish is required per vehicle depending upon color code. The kit contains the garnish and the non-reusable clip.

#### **Non-Desiccated Part Recovery**

Dealers should <u>discontinue the installation</u> of the non-desiccated parts listed below for recall, customer pay repairs AND over-the-counter sales (if applicable).

Model	Model Year	Part Number	Part Description
4Runner	2010-2013	73960-35080 73960-35081	AIR BAG ASSY, INSTR PNL PASS

Toyota requires all dealers to return any parts listed above that still remain in dealer inventory by utilizing the Hazmat Part Return Program available. Dealers will be issued a refund for all part returns. This part return program is outlined in *PANT Bulletin 2014-042*.

#### Important Note:

In order to return the inflator, packages must NOT be opened/tampered with.

#### A. TOOLS & EQUIPMENT

- Standard hand tools
   Torque wrench
- Techstream Molding remover set

GOP/GOR/HOA CAMPAIGN TOOLS – These tools are required when performing this repair.


Image	Name	Quantity
	Barcode Scanner (The scanner distributed for F0J can read bar and QR codes)	1

NOTE: This scanner *CANNOT* be ordered through the parts or tools system. If additional tools are needed, they can be sourced locally.


## **SST** –These are essential service tools that the dealership should have.

Part Number	Part Name	e Quantity	
09950-50013	Puller C Set *	1	
	* The set above includes the following tools.		
Part Number	Part Name	Quantity	
09951-05010	Hanger 150	1	
09952-05010	Slide Arm	2	
09953-05020	Center Bolt 150	1	
09954-05070	Claw No. 7	2	

# **V. SAFETY PRECAUTIONS**



## VI. SRS SYSTEM HEALTH CHECK



#### 1. PERFORM A HEALTH CHECK


- a) Confirm the Techstream is connected to the dealership's internet.
- b) When launching the Techstream software the VIN may need to be entered manually.

NOTE: All letters of the VIN *MUST* be entered in ALL CAPS, or the VIN will need to be reentered when running the diagnostic report.

- c) Perform a health check.
  - Note: The VIN may auto populate on the later model year vehicles, if this happens DO NOT change the VIN.


#### 2. RUN A DIAGNOSTIC REPORT


a) After the health check has completed, run a diagnostic report by clicking on the link on the health check screen.





• This campaign only covers the replacement of the passenger airbag module. NO other SRS components are covered under this campaign.

# CAUTION-PLASTIC RETAINING CLIPS ARE FRAGILE. REMOVE WITH CARE









#### 1. REMOVE THE AIRBAG MODULE

a) Refer to TIS for instructions on airbag removal:

#### <u>2010 MY</u>



NOTE: The left front A-Pillar garnish needs to be replaced on vehicles manufactured prior to August 2013. Only one garnish is required per vehicle depending upon color code. The kit contains the garnish and the non-reusable clip. (see parts information)

#### 2. LAUNCH THE SERIAL NUMBER RECORDING APPLICATION

**STOP** 

- The AIRBAG MODULE serial number MUST be recorded using the barcode scanner (provided at the launch of SSC F0J).

  The barcode scanner is the second seco
  - The barcode scanner application MUST be completed on every vehicle. These numbers MUST be included on every warranty claim that is submitted for module replacement or the claim may be subject to debit.
  - The technician performing the work MUST have valid TIS login credentials and an internet connection to perform the inspection and scanning process.
- a) Log in to TIS and input the VIN of the vehicle in the Vehicle Inquiry tab.
- b) Confirm the VIN is applicable and that the campaign has not been completed.
- c) Click on the link to launch the serial number recording application.
  - Note: The Serial Number Recording Application is the same as the previous application, so the screens will still indicate an older campaign.

Enter a 17 Digit VIN below to sear			
a) Vehicle Information			
Division: TOYOTA	Model: Corolla	Grade: CE	Model Year: 2003
Drive Type: 2WD Date of First Use:	Body Type: 4Dr. Sedan Production Date: 01/18/2002	Engine Family: 4-cylinder - 1ZZ Plant Code: Z - FREMONT PLANT - NUMMI	Transmission:
VIN: 1NX -BR32E-000000000	Standard Equipment: Click here	to display	
Exterior Color: 03M5, SANDRIF	T METALLIC	Interior Color: FA41, FA41 Interior Trim Color: FA, *	Interior Fabric: F, *
Vehicle accessories are not curre	ntly available. Try your query again later.		
Campaign Service History	Warranty DTC History Dia	gnostic Report	
Service Campaign			d Tundra Vehicles, 2002-2003 Model Year

- d) Reenter TIS password in the serial number recorder application.
- NOTE: The person logged-in to TIS <u>MUST</u> be the person performing the repair.

Front Pas	senger A	irbag Inflat	or Module - S	Safety Recall	
		SSC - [	DSF		
				12345	
User ID: SuzukiR Technician Name: Russell Suzuki		e: Russell Suzuki			
Dealer Code: Time: 06/10/2014 02:07 PM PDT			Dealer Name:		
			Airbag Serial #:		
Original Inflator Serial #:			flator Serial #		
original innator serial st			neprocement in		
	VIN: STD	BT41	BEIGE M. M.]		
	1	Milease*			
		Mileage			
Task	Dealer	User	Time	Status	
Airbag # Record				Not Started	
Inflator # Record				Not Started	
Terms & Conditions				Not Started	
New Airbag #				Not Started	

e) Record the vehicle mileage into the serial number recording application.

NOTE:

• If this screen indicates that the module has already been replaced on this VIN, there is no need to perform the campaign again.

#### 3. CONNECT THE BARCODE SCANNER

- a) Connect the barcode scanner to the USB port on the Techstream.
- b) The scanner will automatically connect and a beep will be heard when the scanner is ready.

NOTE:

- The scanner was provided for SSC F0J.
- The scanner works best in low light conditions.
- Always hold the scanner directly in front of and parallel to the barcode label.

#### 4. SCAN THE AIRBAG SERIAL NUMBER

# **ATTENTION:** This information is **CRITICAL**

- a) Scan the AIRBAG ASSEMBLY serial number 2 times.
  - Confirm that the cursor is in the first serial number box then scan the bar code.
  - 2) Position the cursor in the second serial number box and rescan the bar code.

b) Click next.

NOTE:


STOP

- If both the serial numbers do not match, confirm and reenter.
- If the serial number barcode will not scan, it can be entered manually.
- AIRBAG SERIAL NUMBER IDENTIFICATION

   The airbag serial number is *ALWAYS* the 12 *DIGITS* located between the asterisks.
   The 3 digits before the asterisk *ARE NOT* part of
  the serial number, and *SHOULD NOT* be entered or
  an inaccurate response may be returned.
  Airbag Serial Number Label Example




The AIRBAG serial number MUST be recorded prior to replacement.






d) Click submit.



[ ] · · · · · · · · · · · · · · · · · ·	Bag/AirBagController.portlet?_nfpb=true&_windowLabel=Stand
Front Passenger Airbag	g Inflator Module - Safety Recall 👘 🗧
	SSC - DSF
User ID: SuzukiR	Technician Name: Russell Suzuki
Dealer Code:	Dealer Name:
Time: 06/10/2014 05:13 PM PDT	Airbag Serial #: **********96
Original Inflator Serial #: AAEL5110212	Replacement Inflator Serial #: AAEL5110213
<ul> <li>If agree to complete the safety recall's remaining</li> <li>agree to perform a vehicle Health Check with T</li> </ul>	echstream upon completion of the safety recall's technical instructions.
Russell Suzuki has successfully con	firmed completion of Airbag Inflator Module Safety Recall for
VIN - 5TD BT44A	335 [2003 Sequoia BEIGE M. M.]
Warrant	ty Authorization #: b5511e9f
Airbag inflator mod	dule was replaced under this safety recall.
	records and then click 'Close' to resume working.

- h) Confirm agreement by checking the two boxes.
- i) Record the Warranty Authorization # to be included in the warranty claim.
- j) Place the old module in the parts box and take it immediately to the parts department. **NOTE:**
- Confirm the cursor is in the correct serial number input box before scanning.
- If the serial number barcode will not scan, it can be entered manually.
  If there are any difficulties or concerns with this process, email
- quality\_compliance@toyota.com with details.

#### AIRBAG SERIAL NUMBER IS MISSING OR IS UNREADABLE



## VIII. FRONT PASSENGER AIRBAG REINSTALLATION

#### 1. INSTALL THE NEW AIRBAG

a) Refer to TIS for instructions on airbag installation:

#### <u>2010 MY</u>


- 2. RECONNECT THE NEGATIVE BATTERY CABLE
- 3. PREFORM ANY NEEDED VEHICLE INITIALIZATIONS
- 4. PERFORM A HEALTH CHECK AND DIAGNOSTIC REPORT

# ◄ VERIFY REPAIR QUALITY ►

- Confirm all precautions are follow to ensure safety during the repair
- Confirm the entire serial number checker application is completed and the warranty authorization # is recorded on *EVERY* vehicle
- Confirm the old module is handled safely and given to the appropriate parts professional for shipment
  - If you have any questions regarding this update, please contact your regional representative.

## **IX APPENDIX**

#### A. CAMPAIGN DESIGNATION DECODER



#### Examples:

A0D = Launched in 2010, Remedy Phase, 4<sup>th</sup> Campaign Launched in 2010 B1E = Launched in 2011, Interim Phase, 5<sup>th</sup> Campaign Launched in 2011 C1C = Launched in 2012, Interim Phase, 3<sup>rd</sup> Campaign Launched in 2012

#### **B. CAMPAIGN PARTS DISPOSAL**

**ALL** inflators that are removed from vehicles under this campaign **MUST** be packaged and shipped back to the inflator manufacturer following the manufacturer's instructions. The instructions can be found in the following locations:

- Attached to the dealer letter
- Included in the parts box