IMPORTANT UPDATE

TECHNICAL INSTRUCTIONS

FOR

SAFETY RECALL GLG/GLH and HLA

(Note: These technical instructions may be used on any IS 250/350 or IS F vehicle covered under GLG/GLH and HLA) FRONT PASSENGER AIRBAG MODULE

CERTAIN 2006 - 2013 MY IS 250/350 and 2008 - 2013 MY IS F

Updated 4-18-18

Update 4-18-18

- The parts section has been updated
- Added inflator part option
- Previous update made obsolete (Update 2-28-17)
- Removed cross bar bolt replacement

Update 1-9-18

2013 MY added

Update 3-2-17

- 2012 MY added

Update 3-1-17

- Update to the scanner wording on page 13.

Update 2-28-17

STOP

The scanning information on page 45 has been updated. There is NO NEED to scan the inflators. This model requires replacement of the Airbag Module only.

Update 2-24-17

- Added replacement of airbag attachment bolts and part number.

Update 2-9-17

Updated Technician Certification.

The repair quality of covered vehicles is extremely important to Lexus. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly:


- MASTER SERVICE TECHNICIANS
- MASTER DIAGNOSTIC SPECIALISTS

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

NOTE: To support additional service capacity, Lexus Certified and Senior Service Technicians, with <u>at</u> <u>least 36 months Lexus experience</u> AND <u>L652 course credit</u>, may also perform this repair following successful completion of course LSC13B.


I. OPERATION FLOW CHART

The flow chart is for reference only. *DO NOT* use it in place of the full technical instructions. Follow *ALL* steps as outlined in the full technical instructions to confirm the campaign is completed correctly.



II. BACKGROUND

The subject vehicles are equipped with front passenger airbag inflators produced by Takata. The propellant in these inflators may degrade after prolonged exposure to high absolute humidity and fluctuating high temperatures. Degraded propellant can cause inflator rupture during airbag deployment. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material, striking the vehicle occupants, and result in serious injury or death.



III. IDENTIFICATION OF AFFECTED VEHICLES

A. COVERED VIN RANGE

- Check the TIS Vehicle Inquiry System to confirm the VIN is involved in this Safety Recall, and that the campaign has not already been completed prior to dealer shipment or by another dealer.
- TMS warranty will not reimburse dealers for repairs conducted on vehicles that are not affected or were completed by another dealer.

IV. PREPARATION

A. PARTS

Part Number	Part Description	Quantity
04006-29353	Instrument Panel Passenger Airbag	1
04006-66108*	Front Pillar Garnish Kit	1
04006-66108*	Front Pillar Garnish Kit	1

*The kit contains 2 clips

OR

Part	Number		Part Description		Quantity	
		Inst	rument Panel Passenger Airbag In			
04007-06353			Please reference inflator techn	1		
			instructions for R&R procedu			
*The kit above includes the following parts.						
	Part Num	ber	Part Description	Quant	ity	
	-		- Inflator			
	-		Self-locking Nut	5		
	-		Position Determining Plate	1		

Non-Desiccated Part Recovery

Dealers should <u>discontinue the installation</u> of the non-desiccated parts listed below for recall, customer pay repairs AND over-the-counter sales (if applicable).

Model	Model Year	Part Number	Part Description
IS 250 – IS 350, IS-F and IS 250C – IS350C	2006-2013	73960-53020 73960-53060	AIR BAG ASSY, INSTR PNL PASS L/DOOR

Lexus requires all dealers to return any parts listed above that still remain in dealer inventory by utilizing the Hazmat Part Return Program available. Dealers will be issued a refund for all part returns. This part return program is outlined in *PANT Bulletin 2014-042*.


Important Note:

In order to return the inflator, packages must NOT be opened/tampered with.

B. TOOLS & EQUIPMENT

- Standard hand tools
- Torque wrench
 Techstream
- Molding remover set

GLG/GLH/HLA CAMPAIGN TOOLS – These tools where previously provided to the dealership for campaign DLC and will be used for campaign ELG. These tools are required when performing this repair.



NOTE: This tool *CANNOT* be ordered through the parts or tools system. There is a very limited supply of tools, but if additional tools are needed, contact your area representative.

SST –These are essential service tools that the dealership should have.

Part Number	Part Name	Quantity
09950-50013	Puller C Set *	1
Part Number	Part Name	Quantity
09951-05010	Hanger 150	1
09952-05010	Slide Arm	2
09953-05020	Center Bolt 150	1
09954-05021	Claw No. 2	2

V. SAFETY PRECAUTIONS



VI. SRS SYSTEM HEALTH CHECK

Division:	TOYOTA	-
Model:	< Select >	-
ModelYear		-
Engine:		*
Option		-
		*
		~
Optional Informati	on	
VIN: <		
Memo:		*
		81

1. PERFORM A HEALTH CHECK


- a) Confirm the Techstream is connected to the dealership's internet.
- b) When launching the Techstream software the VIN may auto populate if not then it **MUST** be entered manually.

NOTE: All letters of the VIN *MUST* be entered in ALL CAPS, or the VIN will need to be reentered when running the diagnostic report.

c) Perform a health check.


2. RUN A DIAGNOSTIC REPORT


a) After the health check has completed, run a diagnostic report by clicking on the link on the health check screen.



- The serial number recording application will be disabled and the inspection cannot be completed if a health check and diagnostic report is not performed and recorded by TMS.
- This campaign only covers replacement of the passenger dash airbag. If other SRS repairs are needed they are NOT covered under this campaign.

VII. FRONT PASSENGER AIRBAG REMOVAL COMPONENTS





1. DISCONNECT THE NEGATIVE BATTERY TERMINAL



Wait at least 90 seconds after disconnecting the cable from the negative battery terminal to prevent airbag and seat belt pre-tensioner deployment.


Follow all precautions as outlined on TIS before servicing the SRS system.

2. INSTRUMENT PANEL PRECAUTIONS AND REMOVAL



Prior to dash removal make note of the following precautions. Over time some dash components could be easily damaged if not carefully removed.





Removing the No. 3 air register


Remove any peripheral parts on left and right side of the register to allow access to the back of the register.

Wrap the tip of a screwdriver with tape.


Lock the 4 claws inside the register as shown.

NOTE: Do not use a molding removal tool to remove the register it could be damaged.







NOTE: When removing the register DO NOT push on the connector or wiring as it could be damaged.



Using your finger on the left side push out at the point shown to disengage the 4 claws.



Using your finger on the right side push out at the point shown to disengage the 3 claws and remove the register from the instrument panel.



NOTE: DO NOT contact the postioning tabs while removing the instrument panel as the panel could be damaged.

R1601050001F01


a) Refer to TIS for removal instructions


∴ Clamp

IS 250/350	2006 MY	<u>2007 MY</u>	2008 MY	<u>2009 MY</u>	<u>2010 MY</u>	<u>2011 MY</u>	<u>2012 MY</u>	2013 MY
IS F	<u>2008 MY</u>	<u>2009 MY</u>	<u>2010 MY</u>	<u>2011 MY</u>	<u>2012 MY</u>	<u>2013 MY</u>		

3. REMOVE THE AIRBAG FROM THE DASH

- a) Remove the 3 screws and the side defroster nozzle.
- b) Remove the 2 screws and the heater to register duct.






VIII. AIRBAG RECORDING

1. LAUNCH THE SERIAL NUMBER RECORDING APPLICATION

Note: The Serial Number Recording Application is the same application used for DLC.

• The AIRBAG ASSEMBLY serial numbers MUST be recorded using a barcode scanner (provided at the launch of SSC DLC).



- The technician performing the work MUST have valid TIS login credentials and an internet connection to perform the inspection and scanning process.
- a) Log in to TIS and input the VIN of the vehicle in the Vehicle Inquiry tab.
- b) Confirm the VIN is applicable and that the campaign has not been completed.
- c) Click on the link to launch the serial number recording application.

Enter a 17 Digit VIN below to search	for applicable information:		
V 11 1NX BR32E 00000000			
a) Vehicle Information			
Division: TOYOTA	Model: Corolla	Grade: CE	Model Year: 2003
Drive Type: 2WD	Body Type: 4Dr. Sedan	Engine Family: 4-cylinder - 1ZZ	Transmission:
Date of First Use:	Production Date: 01/18/2002	Plant Code: Z - FREMONT PLANT - NUMMI	
VIN: 1NX -BR32E-000000000	Standard Equipment: Click here	to display	
Exterior Color: 03M5, SANDRIFT	METALLIC	Interior Color: FA41, FA41	
		Interior Trim Color: FA, *	Interior Fabric: F, *
Vehicle accessories are not current	ly available. Try your query again later.		
Campaign Service History	Warranty DTC History Dia	gnostic Report	
Service Campaign			
Commission Descriptions, Safety I	Read Dos Development Nation 2003 2004 Mar	del Year Corolla, Corolla Matrix, Sequoia, an	d T d V-Lide- 2002 2002 Madel V
Campaign Description: Safety r	Front Passenees Index million Medule	del rear Corolla, Corolla Platrix, Sequola, an	la runara venicies, 2002-2003 Model rear

d) Reenter TIS password in the serial number recording application.

NOTE: The person logged-in to TIS MUST be the person performing the repair.

Front Pass	senger A		tor Module - S	afety Recall	
		SSC - [JSF	~ ~ ~ ~ ~ ~	
				0000	
User ID: Suzukik			Technician Name	er Bussell Sundri	
Dealer Code:			Dealer Name:		
Time: 06/10/2014 02:07 PM PC			Airbag Scriel #:		
Original Inflator Serial #:			Replacement Inflator Serial #:		
	VIN: STD	BT444	SECGE M. M.)		
	-	Micage*			
	· · · · ·	micage			
Task	Dealer	User	Time	Status	
Airbag # Record Inflator # Record				Not Started Not Started	
Terms & Conditions				Not Started	

e) Record the vehicle mileage into the serial number recording application.

NOTE:

- A task status screen will populate next and at other intervals during the repair. This screen will indicate if the inflator was replaced or in some limited cases that the entire airbag assembly was replaced. Click 'next' to proceed to the next step. This information will be used for record keeping by TMS.
- If this screen indicates that the campaign has already been completed on this VIN, there is no need to perform the campaign again.

2. CONNECT THE BARCODE SCANNER

a) Connect the barcode scanner to the USB port on the Techstream.

b) The scanner will automatically connect and a beep will be heard when the scanner is ready. **NOTE:**

- The scanner was provided for SSC DLC.
- The barcode scanner works best in low light conditions.
- Always hold the scanner directly in front of and parallel to the barcode label.

3. SCAN THE AIRBAG SERIAL NUMBER

ATTENTION: This information is CRITICAL

- a) Scan the AIRBAG ASSEMBLY serial number 2 times.
 - 1) Confirm the cursor is in the first serial number box then scan the serial.
 - 2) Position the cursor in the second serial number box then scan the serial.
- b) Click next.

NOTE:

STOP

- If both serial numbers that are entered do not match, confirm and reenter.
- If the serial number barcode will not scan, it can be entered manually.


AIRBAG SERIAL NUMBER IDENTIFICATION


- The airbag serial number is *ALWAYS* the 12 *DIGITS* located between the asterisks.
- The 3 digits before the asterisk *ARE NOT* part of the serial number, and *SHOULD NOT* be entered or an inaccurate response may be returned.


Airbag Serial Number Label Example



The AIRBAG ASSEMBLY serial number MUST be recorded prior to replacement.







T3 :: SuzukiR - Google Chrome	
t3qa.tms.toyota.com/t3Portal/portle	ts/tis/airBag/AirBagController.portlet?_nfpb=true&_windowLabel=Standa
Front Passenger A	Airbag Inflator Module - Safety Recall 🛛 🖨
	SSC - DSF
User ID: SuzukiR	Technician Name: Russell Suzuki
Dealer Code:	Dealer Name:
Time: 06/10/2014 05:13 PM PDT	Airbag Serial #: ********96
Original Inflator Serial #: AAEL5110212	Replacement Inflator Serial #: AAEL5110213
-	the following terms and conditions on 06/10/2014 05:13 PM PDT
 * I agree to complete the safety recall's r * I agree to perform a vehicle Health Che 	-
 * I agree to complete the safety recall's r * I agree to perform a vehicle Health Che 	remaining technical instructions.
 * I agree to complete the safety recall's r * I agree to perform a vehicle Health Che Russell Suzuki has success 	remaining technical instructions. ack with Techstream upon completion of the safety recall's technical instructions. assfully confirmed completion of Airbag Inflator Module Safety Recall for
 I agree to complete the safety recall's r I agree to perform a vehicle Health Che Russell Suzuki has succes VIN - 	eemaining technical instructions. eck with Techstream upon completion of the safety recall's technical instructions. esfully confirmed completion of Airbag Inflator Module Safety Recall for [2003 Sequoia BEIGE M. M.]
 * I agree to complete the safety recall's r * I agree to perform a vehicle Health Che Russell Suzuki has succes VIN - Airbag integration 	remaining technical instructions. ack with Techstream upon completion of the safety recall's technical instructions. assfully confirmed completion of Airbag Inflator Module Safety Recall for [2003 Sequoia BEIGE M. M.] Warranty Authorization #: b5511e9f
 * I agree to complete the safety recall's r * I agree to perform a vehicle Health Che Russell Suzuki has succes VIN - Airbag integration 	eek with Techstream upon completion of the safety recall's technical instructions. ssfully confirmed completion of Airbag Inflator Module Safety Recall for [2003 Sequoia BEIGE M. M.] Warranty Authorization #: b5511e9f flator module was replaced under this safety recall.

i) Place the old airbag in the parts box and return it to the parts department.


NOTE:

- Keep all shipping paperwork with the box that it came in.
- Confirm the cursor is in the correct serial number input box before scanning.
- If the serial number barcode will not scan, it can be entered manually.
- If there are any difficulties or concerns with this process, email quality_compliance@toyota.com with details.

AIRBAG SERIAL NUMBER IS MISSING OR IS UNREADABLE

STOP

If the airbag serial number and barcode are not legible or are not present, check the box in the application indicating the serial number is not legible.




IX. VEHICLE REASSEMBLY

1. REINSTALL THE AIRBAG ASSEMBLY INTO THE INSTRUMENT PANEL

a) Position the airbag assembly in the instrument panel, engage the straps, and then install the 4 bolts.

NOTE: Ensure the airbag connectors is positioned as shown



- b) Install the 2 screws and the heater to register duct.
- c) Install the 3 screws and the side defroster nozzle.

2. REINSTALL THE DASH

a) Refer to TIS for reinstallation instructions

IS 250/350	2006 MY	2007 MY	2008 MY	<u>2009 MY</u>	<u>2010 MY</u>	<u>2011 MY</u>	2012 MY	<u>2013 MY</u>
IS F	2008 MY	2009 MY	2010 MY	<u>2011 MY</u>	2012 MY	2013 MY		

- 3. RECONNECT THE NEGATIVE BATTERY CABLE
- 4. PERFORM A HEALTH CHECK AND DIAGNOSTIC REPORT
- 5. PERFORM ANY NEEDED SYSTEM INTIALZATIONS


◄ VERIFY REPAIR QUALITY ►

- Confirm all precautions are follow to ensure safety during the repair
- Confirm the entire serial number checker application is completed and the warranty authorization # is recorded on EVERY vehicle
- Confirm the old airbag is handled safely and given to the appropriate parts professional for shipment

If you have any questions regarding this update, please contact your area representative.

X. APPENDIX

A. CAMPAIGN DESIGNATION DECODER



B. CAMPAIGN PARTS DISPOSAL

ALL airbags that are removed from vehicles under this campaign **MUST** be packaged and shipped back to the manufacturer following the manufacturer's instructions. The instructions can be found in the following locations:

- Attached to the dealer letter
- Included in the parts box