

H081NAS1
TECHNICAL BULLETIN
 13 MAR 2018



© Jaguar Land Rover North America, LLC

NOTE: The information in Technical Bulletins is intended for use by trained, professional Technicians with the knowledge, tools, and equipment required to do the job properly and safely. It informs these Technicians of conditions that may occur on some vehicles, or provides information that could assist in proper vehicle service. The procedures should not be performed by 'do-it-yourselfers'. If you are not a Retailer, do not assume that a condition described affects your vehicle. Contact an authorized Jaguar service facility to determine whether this bulletin applies to a specific vehicle.

INFORMATION

SECTION:

303-04C/D/F: Fuel Charging and Controls

SUBJECT/CONCERN:

SAFETY RECALL: Underhood Petrol Fuel Leak

AFFECTED VEHICLE RANGE:

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
E-PACE (X540)	2018	Z00291-Z03437	Graz (Austria)	INGENIUM I4 2.0L Petrol
F-PACE (X761)	2018	099558	Solihull	INGENIUM I4 2.0L Petrol
F-PACE (X761)	2018	243940-290251	Solihull	INGENIUM I4 2.0L Petrol

MODEL:	MODEL YEAR:	VIN:	ASSEMBLY PLANT:	APPLICABILITY:
F-TYPE (X152)	2018-2019	K51500-K55584	Castle Bromwich	INGENIUM I4 2.0L Petrol
XE (X760)	2018	P18140-P36970	Castle Bromwich	INGENIUM I4 2.0L Petrol
XF (X260)	2018	Y55539-Y64763	Castle Bromwich	INGENIUM I4 2.0L Petrol

MARKETS:

NORTH AMERICA

CONDITION SUMMARY:

SITUATION:

An issue has been identified on certain vehicles within the listed Affected Vehicle Range for an underhood gasoline fuel leak. The brazing of the fuel rail end caps is inconsistent and may not provide the design condition, so not sealing the fuel rail ends. Fuel vapor and liquid fuel leaks can occur over time. This can lead to a liquid fuel leak into the engine bay.

Fuel odor may be noticed by the driver and they may also observe liquid fuel if the hood is lifted. Should leaking fuel come into contact with a sufficiently hot surface, there is an increased risk of fire.

ACTION:

Retailers are required to **HOLD** affected new vehicles that are within your control and refrain from releasing the vehicles for **new vehicle sale** pending completion of the Workshop Procedure detailed in this Technical Bulletin. Unsold vehicles should have this performed as part of the Pre-Delivery Inspection (PDI) process but **must** have it completed prior to vehicle handover to the customer.

Affected vehicles already in the hands of customers should be updated at the next available opportunity.

PARTS:

NOTE:

Order only the expected percentage demand of parts identified.

DESCRIPTION	PART NO./SUNDRY CODE	QTY./VALUE	EXPECTED PERCENTAGE DEMAND
Fuel rail	JDE40127	1	100
Injector refit kit	T2H33724	4	100

SPECIAL TOOLS:

Refer to TOPIx Workshop Manual/Workshop Procedure for any required special tools.

WARRANTY:

NOTE:

Use the Jaguar Land Rover claims submission system to make sure that a vehicle is affected by this program prior to undertaking any rework action.

At the time of confirming a booking for vehicle repair, make sure that **all** outstanding Recall and Service Actions are identified to ensure the correct parts are available and adequate workshop time is allocated for repairs to be completed at one visit.

Warranty claims must be submitted quoting the Program Code and the relevant Option Code; this will result in payment of the stated time. The SRO and parts information is included for information only. The Option Code(s) that allows for the drive in/drive out allowance may only be claimed if the vehicle is brought back into the workshop for this action alone to be undertaken.

Repair procedures are under constant review and therefore times / prices are subject to change; those quoted here must be taken as guidance only. Use the Jaguar Land Rover claims submission system to obtain the latest repair time.

Warranty claims must be submitted or payment within 30 calendar days of completion of the repair.

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
--------------	-------------	-------------	-----	--------------	-------------------	------------

PROGRAM CODE	OPTION CODE	DESCRIPTION	SRO	TIME (HOURS)	PARTS/SUNDRY CODE	QTY./VALUE
H081	A	Fuel rail - Renew	19.60.13	1.0 - E-PACE (X540) 1.0 - F-PACE (X761) 0.9 - F-TYPE (X152) 0.9 - XE (X760) 1.0 - XF (X260)	JDE40127 T2H33724	1 4
H081	B	Fuel rail - Renew Drive in/drive out	19.60.13 10.10.10	1.0 - E-PACE (X540) 1.0 - F-PACE (X761) 0.9 - F-TYPE (X152) 0.9 - XE (X760) 1.0 - XF (X260) 0.2	JDE40127 T2H33724 -	1 4 -

Normal Warranty policies and procedures apply.

WORKSHOP PROCEDURE

- 1 Replace the fuel rail (see TOPIx Workshop Manual section 303-04C/D/F: Fuel Charging and Controls - INGENIUM I4 2.0L Petrol - Removal and Installation - Fuel Rail).