IMPORTANT UPDATE

TECHNICAL INSTRUCTIONS

FOR

SAFETY RECALL JOV

HYBRID SYSTEM SOFTWARE UPDATE

CERTAIN: 2010-2014 PRIUS

Technical Instructions for the 2012-2014 Prius V are in a separate document


Update 12.21.2018: The Calibration Verification Check has been removed until further notice. Update 1.17.2019: The Calibration Verification Check has been reactivated. Update 1.17.2019: Updates to the 2010 CID charts were made.

The repair quality of covered vehicles is extremely important to Toyota. All dealership technicians performing this recall are required to successfully complete the most current version of the E-Learning course "Safety Recall and Service Campaign Essentials". To ensure that all vehicles have the repair performed correctly; technicians performing this recall repair are required to currently hold <u>at least one</u> of the following certification levels:

- Expert Technician (Hybrid)
- Master Technician
- Master Diagnostic Technician

It is the dealership's responsibility to select technicians with the above certification level or greater to perform this recall repair. Carefully review your resources, the technician skill level, and ability before assigning technicians to this repair. It is important to consider technician days off and vacation schedules to ensure there are properly trained technicians available to perform this repair at all times.

I. OPERATION FLOW CHART



II. IDENTIFICATION OF AFFECTED VEHICLES

 Check the TIS Vehicle Inquiry System to confirm that each VIN is eligible for this Safety Recall, and that it has not already been completed prior to dealer shipment or by another dealer.

Note: TMNA warranty will not reimburse dealers for repairs completed on vehicles that are not affected or were completed by another dealer.

III. PREPARATION

1. PARTS

| Part Number | Part Description | Quantity |
|------------------|-------------------------------|----------|
| 00451-00001-LBL* | Authorized Modification Label | 1 |


*Labels can be ordered in packs of 25 from the MDC through the Dealer Daily Website

2. TOOLS, SUPPLIES & EQUIPMENT

- Standard Hand Tools
- Techstream 2.0 / Techstream Lite with software version 13.30 or greater installed
- GR8 Battery Diagnostic Station
- T-SB-0134-16

SST – These Special Service Tools required for this repair:

| Part Number | Tool Name | Quantity |
|---------------|-------------------------|----------|
| 09891-47020 | Inverter Case Separator | 1 |
| Campaign tool | Joint Fuse removal tool | 1 |




The fuse removal tools were shipped to the dealers for a previous campaign. Additional tools will also be sent.

IV. BACKGROUND

The involved vehicles were designed to enter a failsafe driving mode in response to certain hybrid system faults. Toyota has found that in rare situations, the vehicle may not enter a failsafe driving mode as intended. If this occurs, the vehicle could lose power and stall. While power steering and braking would remain operational, a vehicle stall while driving at higher speeds could increase the risk of a crash.

This recall remedy will address a new condition in the vehicles involved in previous Safety Recall E0E. The previous recall did not anticipate the new condition remedied with this recall.

V. INSPECT INVERTER CONDITION




VI. REPAIR INVERTER ASSEMBLY

Note: Repairing the inverter required only if DTC's P0A94, P324E, P3004 or P0A1A is present. If these DTC's are not present, skip to section VII. Determine CID Status on page 7.

1. DETERMINE INVERTER ASSEMBLY TYPE

a. Using the flowchart below determine the inverter type (A or B).



2. DETERMINE REPAIR COMPONENTS BASED ON DTC DETAIL CODE AND INVERTER TYPE

- a. If multiple DTCs are present save the freeze frame data.
- b. After saving the freeze frame data, clear codes and confirm what DTCs reset.
- c. If multiple codes return, follow the repair manual diagnosis procedure for the DTC with Freeze Frame Data Occurrence Order value of "1".
- d. Use the correct table below to identify the parts required for repair, the correct parts are listed in the bottom row of each table.

| DTC | DTC DETAIL CODE | IPM REPLACEMENT | • MG-ECU • CURRENT SENSOR • INVERTER WIRE HARNESS | MG-ECU CURRENT SENSOR IPM INVERTER WIRE HARNESS | INVERTER ASSY |
|----------|-----------------------|------------------------------------|--|---|------------------|
| | 127 | | | X | |
| | 172 | Х | | | |
| | 442 | | | X | |
| | 547 | | Х | | |
| | 548 | | | X | |
| | 549 | | Х | | |
| | 550 | | | X | |
| | 553 | X | | | |
| P0A94 | 554 | | Х | | |
| | 555 | | | X | |
| | 556 | | Х | | |
| | 557 | X | | | |
| | 564 | | | X | |
| | 585 | | | X | |
| | 587 | | | X | |
| | 589 | | | X | |
| | 590 | | | X | |
| P324E | 788 | | | X | |
| | 151 | | | X | |
| | 155 | | Х | | |
| | 156 | | Х | | |
| P0A1A | 166 | | Х | | |
| | 200 | | X | | |
| | 658 | | Х | | |
| | 659 | | Х | | |
| | 791 | | Х | | |
| | 131 | | | | Х |
| D2004 | 132 | | | | X |
| P3004 | 800 | X | | | |
| | 801 | Х | | | |
| | | | | 04899-47020 (1) | |
| | | 04900 47020 (4) | G920H-47030 (1) | 08887-02809 (2) | |
| PARTS & | | 04899-47020 (1) 08887-02809 (2) | G920J-52010 (1) | G920H-47030 (1) | |
| QUANTITY | | 08887-02809 (2) 04899-47060 (1) | G9208-47090 (1) | G920J-52010 (1) | ORDER BY |
| (QTY) | | 08826-00100 (1) | 04899-47060 (1) | G9208-47090 (1) | VIN |
| (((11) | | 90430-18008 (1) | 08826-00100 (1) | 04899-47060 (1) | |
| | | 30430-10000 (1) | 90430-18008 (1) | 08826-00100 (1) 90430-18008 (1) | |

TYPE A



Thermal grease for IPM replacement is NOT interchangeable. Only grease specified for the Prius inverter can be used. Grease for the Highlander IPM replacement will result in inverter failure if used.

| DTC | DTC DETAIL CODE | IPM REPLACEMENT | MG-ECU | • MG-ECU • IPM | MG-ECU CURRENT SENSOR IPM | INVERTER ASSY |
|------------------------------|-----------------------|---|--|--|---|------------------|
| | 127 | | | Х | | |
| | 172 | X | | | | |
| | 442 | | | Х | | |
| | 547 | | Х | | | |
| | 548 | | | | Х | |
| | 549 | | Х | | | |
| | 550 | | | Х | | |
| | 553 | X | | | | |
| P0A94 | 554 | | Х | | | |
| | 555 | | | | Х | |
| | 556 | | Х | | | |
| | 557 | X | | | | |
| | 564 | | | Х | | |
| | 585 | | | Х | | |
| | 587 | | | Х | | |
| | 589 | | | Х | | |
| | 590 | | | Х | | |
| P324E | 788 | | | | X | |
| | 151 | | | | X | |
| | 155 | | Х | | | |
| | 156 | | Х | | | |
| | 166 | | Х | | | |
| P0A1A | 200 | | Х | | | |
| IVAIA | 658 | | Х | | | |
| | 659 | | Х | | | |
| | 791 | | Х | | | |
| | 792 | | Х | | | |
| | 793 | | Х | | | |
| | 131 | | | | | Х |
| D 2004 | 132 | | | | | Х |
| P3004 | 800 | X | | | | |
| | 801 | X | | | | |
| PARTS & QUANTITY (QTY) | | 04899-47020 (1) 08887-02809 (2) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1) | G920H-47030 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1) | 04899-47020 (1) 08887-02809 (2) G920H-47030 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1) | 04899-47020 (1) 08887-02809 (2) G920H-47030 (1) G920J-52010 (1) 04899-47060 (1) 08826-00100 (1) 90430-18008 (1) | ORDER BY VI |



TYPE B

Thermal grease for IPM replacement is NOT interchangeable. Only grease specified for the Prius inverter can be used. Grease for the Highlander IPM replacement will result in inverter failure if used.

3. TO REPAIR THE INVERTER, CLICK ON THE RELEVANT LINK BELOW:

2010 Prius: Intelligent Power Module Transistor Removal

2011 Prius: Intelligent Power Module Transistor Removal

2012 Prius: Intelligent Power Module Transistor Removal

2013 Prius: Intelligent Power Module Transistor Removal


2014 Prius: Intelligent Power Module Transistor Removal

4. CONTINUE TO THE NEXT SECTION TO CONFIRM CID'S STATUS

VII. DETERMINE CID STATUS

1. DETERMINE STATUS of HYBRID CONTROL SYSTEM CID's

- a. Locate the <u>Update</u> column for the Hybrid Control System in the <u>Stored Data</u> tab.
- b. Determine the status of the <u>4 CID's</u> for the Hybrid Control ECU; indicated by a <u>YES</u> or <u>NO</u> in the Update column.
- Note: It's possible that all 4 CID's need to be updated, as well as it's possible that only 1, 2 or 3 of the 4 CID's need to be updated. If any of the CID's indicate 'Yes', proceed with the update procedure.



VIII. VEHICLE PREPERATION

The ECU reprograming procedure is detailed in <u>T-SB-0134-16.</u> Reference this Bulletin for additional detailed procedures and information.

1. VEHICLE BASICS

- a. Confirm the following conditions:
 - Vehicle in the IG position (engine off).
 - Transaxle in Park.
 - Parking brake engaged.
 - Turn off all electrical accessories(i.e. Headlights, wipers, climate control, audio system, etc.)

2. CONNECT THE 12v BATTERY TO A POWER SUPPLY (GR8)

- a. Connect the GR8 or other type of a power supply (not a battery charger) to the 12v battery.
- b. Select the Power Supply Mode from the Charge Menu of the GR8.



A power supply *MUST* be used during reprogramming. ECU damage will occur if the battery voltage is not properly maintained during this re-flash procedure.

Note: A power supply must be connected directly to the 12v battery terminals and <u>NOT</u> the remote jump posts under the hood (if equipped).

3. VERIFY TECHSTREAM SETUP

- a. Verify that the Techstream meets the following conditions:
 - Software version 13.30 or greater is installed.
 - The Techstream battery is fully charged. If not, connect the Techstream to a 120v source.
 - The DLCIII cable is in good condition.



The Techstream battery must be maintained during the update procedure. If necessary, plug the Techstream into a 120v outlet to ensure that a failure does not occur.

Note: If the Techstream communication with the vehicle fails during the re-flash procedure, the ECU will be damaged and must be replaced.


4. Verify Techstream Configuration

- a. From the menu at the top of the screen, select: Setup / Techstream Configuration.
- b. Continue to the third setup screen: Required Information.
- c. Verify that "US Dealer 1" is selected as the User Type.

| Please input the following information. Required Information |
|--|
| This Information is used for error report follow up. |
| Dealer Name Toyota |
| Dealer Code |
| Dealer Phone 123-456-7890 |
| Dealer Country United States VRegion |
| This selection is used to configure Techstream network settings. |
| User Type US Dealer 1 - |
| Example: TOYOTA/LEXUS/SCION Dealers in the U.S. for one.tis.toyota.com |
| |

5. MAINTAIN BRAKE SYSTEM PRESSURE

- a. Depress the brake pedal fully 2 times within 2 seconds.
 - Note: You may hear the hydro-boost pump run for a few seconds when completing these steps. This procedure will prevent the pump from running during the calibration update procedure.



- 6. REMOVE JOINT FUSE FROM ENGINE ROOM FUSE BOX
 - a. Confirm the joint fuse orientation before removal because the fuse can be installed in either direction.
 - b. Using the fuse puller remove the joint fuse that encases the CDS (30A), RDI (30A) and HTR (50A).

Permanent damage to the ECU's can happen if these fuses are not removed.

Removing these fuses will stop the vehicle from performing onboard diagnostic tests during the update, which could cause the update to fail and damage the ECU.

IX. CUWC APPLICATION

1. INSTALL CUWC FILE INSTALLER (Only required once for each Techstream)

- a. In TIS, select the following:
 - TIS / Diagnostics / Reprograming

| Home T | Service Lane | TAS RTS | TQCN / PRS | QAT Admin | | |
|--------------------------|---|-------------------|------------|------------|--|--|
| Library Diagnostics | • Tech Assistance | • Vehicle Inquiry | | | | |
| Scantool | Reprogramming | Add / Remove Key | Telematics | Navigation | | |
| Calibrations | 1 | | | | | |
| Calibration/Multimedia S | earch Form | | | | | |
| | Choose the criteria you would like to search by: Division/Model/Year Calibration ID/Multimedia ID VDS | | | | | |
| | | Division: TOYOT | A 🔻 | | | |
| | | Model: All | T | | | |
| | | Year: ALL | | | | |
| | | Clear | Search | | | |
| | - | | | | | |
| ECU Calibrations | Multimedia Upda | tes | | | | |

b. On the right side of the screen, select the following from the Reference Documents:


- CUWC Reprogramming Installer
- Follow the on-screen instructions to complete the installation.

| Reference Documents |
|--|
| CUWC Reprogramming Installer To support Safety Recall JOV you will need to download this reprogramming installer |
| Multimedia Software Download Instructions Step-by-step instructions for downloading multimedia software update files to USB f |
| Safety Recall A0G – 2003 Sequoia – Skid Control ECU Update Software application and installation guide |
| Vehicle Reprogramming Tips This quick reference sheet outlines reprogramming best practices. |
| Toyota ECU Flash Reprogramming Bulletin T-SB-0012-13 A complete guide to reprogramming with TIS Techstream and Techstream Lite. |

Note: The installation of the CUWC Reprograming Installer will only need to be completed one time for each Techstream.

(cont. on next page)

Installation of the CUWC Reprograming Installer is required on each Techstream to install the new format of Calibration ID's. This new format will automatically, if needed, run the Calibration Wizard twice to complete the installation of updated CID's in both the Power Management and Motor Generator ECU's.



The following message will appear when the CUWC installation application is running. <u>This image</u> <u>cannot be closed</u> manually. When the installation of all necessary CID's is complete, the image will close.

Message displayed during CID update process:




MULTIPLE CID'S MAY BE UPDATED

The CUWC Application will update the Hybrid Control System CID #1 (PM Main) using the Calibration Wizard, as required for Safety Recall JOV. Additionally, it will update CID #2, #3, and #4 of the Hybrid Control System using the Calibration Wizard, as needed, if the vehicle has not had Safety Recall EOE completed. When selecting an installation link from the charts below, please understand that the Calibration Wizard may **AUTOMATICALLY** run twice to complete the installation. The first installation will update CID #1 (PM Main) as required on all vehicles, and update CID #2 (PM sub) if necessary. The Calibration Wizard will then close as normal. If CID's #3 and #4 need to be updated, the Calibration Wizard will **AUTOMATICALLY** open again and compete these installations. DO NOT exit the application or shut off the vehicle or Techstream while the large CUWC text box is present on the screen. Permeant damage to the ECU will occur.

CID #1: Power Management Main CID #2: Power Management sub


CID #3: Motor Generator #1 CID #4: Motor Generator #2



X. CID INSTALLATION

2. INSTALLATION OF CID'S

- a. Identify the Hybrid Control CID #3 & #4 from the Stored Data tab.
- b. Referencing the correct model year in the chart's below, identify the chart that has the correct CID #3 & #4.
- c. Select the Group # link (blue text) to begin the update process.
- d. Follow the instruction on the screen to complete the installation.



| | ı | | |
|-------|------------------|--|----------------------|
| | | 896B3470 <i>1000</i> | |
| | | 896B3470 <i>1100</i> | |
| | | 896B3470 <i>1200</i> | |
| | | 896B3470 <i>1300</i> | |
| | CID #1 | 896B3470 <i>1400</i> | <u>2010 Prius #1</u> |
| | | 896B3470 <i>1500</i> | CID #1: 896B34732000 |
| | | 896B3470 <i>1600</i> | CID #2: 896B54701100 |
| | | 896B3470 <i>1700</i> | CID #3: 898844701400 |
| 2010 | | 896B3470 <i>1800</i> | CID #4: 898844702300 |
| Prius | | 896B3470 <i>1900</i> | |
| | CID #2 | 896B54701000 | |
| | | 896B54701100 | _ |
| | | 89884470 1200 | |
| | CID #3 | 89884470 1300 | |
| | | 89884470 1400 | |
| | | 89884470 2100 | |
| | CID #4 | 89884470 2200 | |
| | | 89884470 2300 | |
| | | | |
| | | 896B34701000 | |
| | | 896B3470 <i>1100</i> | |
| | | 896B3470 <i>1200</i> | |
| | | 896B34701300 | |
| | CID #1 | 896B3470 <i>1400</i> | <u>2010 Prius #2</u> |
| | | 896B3470 <i>1500</i> | CID #1: 896B34732000 |
| | | 896B3470 <i>1600</i> | CID #2: 896B54701100 |
| | | 896B3470 <i>1700</i> | CID #3: 898844708200 |
| 2010 | | 896B3470 <i>1800</i> | CID #4: 898844709200 |
| Prius | | | |
| | | 896B3470 <i>1900</i> | _ |
| | CID #2 | 896B54701000 | - |
| | CID #2 | 896B54701000 896B54701100 | |
| | | 896B54701000 896B54701100 89884470 8000 | |
| | CID #2 CID #3 | 896B54701000 896B54701100 89884470 8000 89884470 8100 | |
| | | 896B54701000 896B54701100 89884470 8000 89884470 8100 89884470 8200 | |
| | CID #3 | 896B54701000 896B54701100 89884470 8000 89884470 8100 89884470 8200 89884470 9000 | |
| | | 896B54701000 896B54701100 89884470 8000 89884470 8100 89884470 8200 | |

| Year | CID# | Original | Current |
|-------|--------|----------------------|----------------------|
| | | 896B34714000 | |
| | | 896B34714100 | |
| | | 896B34714200 | |
| | CID #1 | 896B34714300 | |
| | | 896B34714400 | 2011 Prius #1 |
| | | 896B34714500 | CID #1: 896B34714700 |
| 2011 | | 896B34714600 | CID #2: 896B54701100 |
| Prius | CID #2 | 896B54701100 | CID #3: 898844701400 |
| | | 89884470 1200 | CID #4: 898844702300 |
| | CID #3 | 89884470 1300 | |
| | | 89884470 1400 | |
| | | 89884470 2100 | |
| | CID #4 | 89884470 2200 | |
| | | 89884470 2300 | |
| | | | |
| | | 896B34714000 | |
| | | 896B34714100 | |
| | | 896B34714200 | |
| | CID #1 | 896B34714300 | |
| | | 896B34714400 | 2011 Prius #2 |
| | | 896B34714500 | CID #1: 896B34714700 |
| 2011 | | 896B34714600 | CID #2: 896B54701100 |
| Prius | CID #2 | 896B54701100 | CID #3: 898844708200 |
| | | 89884470 8000 | CID #4: 898844709200 |
| | CID #3 | 89884470 8100 | |
| | | 89884470 8200 | |
| | | 89884470 9000 | |
| | CID #4 | 89884470 9100 | |
| | | 89884470 9200 | |

| Year | CID# | Original | Current |
|-------|--------|----------------------------|----------------------|
| | | 896B34720000 | |
| | | 896B34720100 | |
| | CID #1 | 896B34720200 | |
| | | 896B34720300 | 2012 Prius #1 |
| | | 896B34720400 | CID #1: 896B34720500 |
| 2012 | CID #2 | 896B54708000 | CID #2: 896B54708000 |
| Prius | | 89884470 1200 | CID #3: 898844701400 |
| | CID #3 | 89884470 1300 | CID #4: 898844702300 |
| | | 89884470 1400 | |
| | | 89884470 2100 | |
| | CID #4 | 89884470 2200 | |
| | | 89884470 2300 | |
| | | | |
| | | 896B34720000 | |
| | | 896B34720100 | |
| | CID #1 | 896B34720200 | |
| | | 896B34720300 | 2012 Prius #2 |
| | | 896B34720400 | CID #1: 896B34720500 |
| 2012 | CID #2 | 896B54708000 | CID #2: 896B54708000 |
| Prius | | 89884470 <mark>8000</mark> | CID #3: 898844708200 |
| | CID #3 | 89884470 8100 | CID #4: 898844709200 |
| | | 89884470 <mark>8200</mark> | |
| | | 89884470 9000 | |
| | CID #4 | 89884470 9100 | |
| | | 89884470 9200 | |

| Year | CID# | Original | Current |
|-------|--------|----------------------|----------------------|
| | | 896B34736000 | |
| | CID #1 | 896B34736100 | |
| | | 896B34736200 | <u>2013 Prius #1</u> |
| | | 896B34736300 | CID #1: 896B34736400 |
| 2013 | CID #2 | 896B57602000 | CID #2: 896B57602000 |
| Prius | | 89884470 1200 | CID #3: 898844701400 |
| 11100 | CID #3 | 89884470 1300 | CID #4: 898844702300 |
| | | 89884470 1400 | |
| | | 89884470 2100 | |
| | CID #4 | 89884470 2200 | |
| | | 89884470 2300 | |


| | | 896B34736000 | |
|---------------|---------|----------------------|----------------------|
| | 015 /// | 896B34736100 | |
| | CID #1 | 896B34736200 | 2013 Prius #2 |
| | | 896B34736300 | CID #1: 896B34736400 |
| 2010 | CID #2 | 896B57602000 | CID #2: 896B57602000 |
| 2013 Prius | CID #3 | 89884470 8000 | CID #3: 898844708200 |
| FTIUS | | 89884470 8100 | CID #4: 898844709200 |
| | | 89884470 8200 | |
| | | 89884470 9000 | |
| | CID #4 | 89884470 9100 | |
| | | 89884470 9200 | |

| Year | CID# | Original | Current |
|-------|--------|----------------------|----------------------|
| | | 896B34747000 | |
| | CID #1 | 896B34747100 | |
| | | 896B34747200 | <u>2014 Prius #1</u> |
| | CID #2 | 896B57602000 | CID #1: 896B34747300 |
| 2014 | | 89884470 1200 | CID #2: 896B57602000 |
| Prius | CID #3 | 89884470 1300 | CID #3: 898844701400 |
| | | 89884470 1400 | CID #4: 898844702300 |
| | | 89884470 2100 | |
| | CID #4 | 89884470 2200 | |
| | | 89884470 2300 | |

| 2014 Prius | | 896B34747000 | |
|---------------|--------|----------------------------|----------------------|
| | CID #1 | 896B34747100 | |
| | | 896B34747200 | 2014 Prius #2 |
| | CID #2 | 896B57602000 | CID #1: 896B34747300 |
| | CID #3 | 89884470 <mark>8000</mark> | CID #2: 896B57602000 |
| | | 89884470 <mark>8100</mark> | CID #3: 898844708200 |
| | | 89884470 8200 | CID #4: 898844709200 |
| | | 89884470 9000 | |
| | CID #4 | 89884470 9100 | |
| | | 89884470 9200 | |

Note: Although there are 4 CID's for the Hybrid Control System, CID #2 will not be displayed on the Calibration Verification Check. However, the judgement shown in the Calibrations(s) Update Required column does reflect the status of all 4 CID's. There is no need to manually check CID #2.

XI. COMPLETE REPAIR



- 1. REINSTALL JOINT FUSE INTO ENGINE ROOM FUSE BOX
 - a. Confirm the joint fuse orientation before reinstalling because the joint fuse can be installed in either direction.
 - b. Reinstall the joint fuse that encases the CDS (30A), RDI (30A) and HTR (50A).

STOP BE SURE TO ORIENT THE FUSE AS SHOWN ON THE FUSE BLOCK COVER.



- 2. PERFORM VERIFICATION HEALTH CHECK
 - a. Using a Techstream, perform a Health Check.
 - c. Clear DTC's that may have set during the re-flash procedure.
 - d. Re-run the Health Check to confirm that no DTC's reappear.




THIS VERIFICATION HEALTH CHECK IS NECESSARY to update the results and CID's to the National database.

1. CONFIRM CID UPDATE

STOP

a. On the Stored Data tab, confirm the following for the Hybrid Control System:

• The Update column lists "No" for all 4 Hybrid Control System CID's





Note: If you receive the following message <u>after</u> the Verification Health Check, you have not properly completed the Required Calibration Updates!!



2. PERFORM CALIBRATION VERIFICATION CHECK

- a. Proceed to the following location:
 - TIS / Vehicle Inquiry / (input VIN #) / Lookup

| Home IIS Service Lane AS RTS | | | |
|--------------------------------------|--------------------------------|-------------------|-----------------|
| O Library | • Diagnostics | • Tech Assistance | Vehicle Inquiry |
| Vehicle Identification Number Search | | | |
| Enter a 17 D VIN: JTD | igit VIN below to sea KN3DU | Clear | bokup |


- b. Proceed to the following location:
 - Campaign tab / Calibration Verification Check for Safety Recall J0V
 - Input your TIS login password for verification

| Campaign Pervice History Toyol | aCare Warranty DTC History Diagnostic | : Report | |
|---|--|-------------------------|--------------------------------|
| Service Campaign | | | |
| Campaign Description: Campaign Status: Completion Status: [Show Documents] | Safety Recall J0V - Certain 2010-2014 Mo Remedy Not Available Completed | del Year Prius, Certain | Calibration Verification Check |

Note: If the Calibration Verification Check link does not appear, the technician signed onto TIS does not meet the certification requirement of this campaign.

- c. Review the status of the Calibration(s) Update Required.
 - OK: The CID's have successfully loaded. The Calibration(s) Update Required column will say "No" in a green box. Proceed to the next step.
 - NG: The CID's did not successfully update. The Calibration(s) Update Required column will say "Yes" in a red box. Review these instructions and retry the installation process again.


(cont. on next page)



Note: Although there are 4 CID's for the Hybrid Control System, CID #2 will not be displayed on the Calibration Verification Check. However, the judgement shown in the Calibrations(s) Update Required column does reflect the status of all 4 CID's. There is no need to manually check CID #2.

3. PRINT CUSTOMER HEALTH CHECK REPORT

a. From the Stored Data tab, select the Customer Health Check Report button (TIS will launch when button is pressed).



- b. Log in to TIS.
- c. Input Vehicle Mileage and Repair Order number.
- d. Check the "Performed" campaign button for campaign J0V.
- e. Select the Report button.

| \odot | Diagnostic Report | | | |
|--|-------------------|--|--|--|
| Vehicle Information | | | | |
| | Mileage: 7787 | | | |
| Repa | lir Order: 77688 | | | |
| Our systems show the forowing campelans are outstanding. Have any of these campeigns been completed? Theck for SSC door label if unsure.) JOV @ Performed @ Not Performed Report | | | | |


f. Confirm Customer Health Check Report information is correct.

| Θ | Diagnostic Report | | |
|--|------------------------|------------------------------------|--|
| | Vehicle Information | | |
| Vehicle: 2013 Prius Repair Order: 12345 | VIN: JTDKN3DU7D1615492 | Mileage: 13672 | |
| | Health Check Sur | mmary | |
| Checkpoints | Status | Comments | |
| Powertrain | All systems OK | | |
| Chassis | All systems OK | | |
| Electrical | All systems OK | | |
| Network Systems | All systems OK | | |
| Service Campaigns | No Action Required | JOV Performed | |
| | | Performed: 02/20/14, 4:36 PM (PST) | |
| | | Technician Signature | |
| | | Quality Inspector Signature | |

- g. Print Customer Health Check Report from TIS.
- h. Sign and provide to the customer.

4. ATTACH THE AUTHORIZED VEHICLE MODIFICATION LABEL

- a. Fill out the label.
- b. Affix the label to the under-side of the hood.



◄ VERIFY REPAIR QUALITY ►

- Confirm all ECM Calibration has been updated successfully to the NEW CID's.
- Confirm that the Authorized Modification Label has been installed
- If you have any questions regarding this Safety Recall, please contact your regional representative

XII. APPENDIX

A. PARTS DISPOSAL

As required by Federal Regulations, please make sure all recalled parts (original parts) removed from the vehicle are disposed of in a manner in which they will not be reused, **unless requested for parts recovery return**.

B. CAMPAIGN DESIGNATION DECORDER

