

Service Bulletin No. 468

60-Seater J-Coach Egress Window Addition

MODEL:	TYPE:	SECTION/GROUP:	DATE:
J Series	Field Change Program	03- Body	

Ref. MCI NHTSA Recall No.: 18V-692

Ref. MCI Transport Canada Recall No.: 2018-545

Customer Complaint:

Motor Coach Industries ("MCI") has become aware that the 60-seater MY2018-J4500 coaches do not meet the minimum egress area specified in FMVSS 217/CMVSS 217.

Cause:

The egress area was not increased when the increased seating capacity was put into production resulting in noncompliance with FMVSS 217/CMVSS 217 on those units with a 60-passenger seating layout.

Corrective Action:

MCI urges owners of the affected coaches to have the following procedure performed as soon as possible.

WARNING

Read this entire procedure before beginning work.

Use Safe Shop Practices At All Times.

To avoid personal injury:

- a. Turn the main battery disconnect switch to the OFF position.
- b. Ensure that both the front and the rear wheels are chocked.
- *c.* Position the <u>ENGINE RUN</u> and <u>ENGINE START</u> switches on the engine compartment remote control box to the OFF position.
- d. Allow enough time for components to cool down prior to working in the engine compartment.



1.0 Material Requirements:

Service kit **T03-2985** contains the following parts:

Item	Part number	Quantity	Description
1	03-27-1074	4	TRI/MARK ROTARY LATCH
2	03-27-2028	8	SCR, ¼-20 X 7/8" LG. PAN HD
3	03-27-2037	4	LATCH HOUSING
4	03-27-2036	4	RELEASE BAR HINGE
5	03-27-2034	16	SCR, 8-32 X 9/32" LG. TRUSS HD. TAPETITE
6	03-27-1065	4	HINGE PIN
7	03-27-1066	8	SCR, 10-32 X 3/8" LG. TRUSS HD
8	03-27-1067	4	RELEASE BAR SPRING
9	03-27-1914	8	SCR, 8-32 X 5/16" LG. PAN HD
10	03-27-1068	8	RECESS BUMPER
11	03-27-2033	8	SCR, #8 TYPE B X 5/8"LG. PAN HD
12	03-27-2022	4	BRACKET, RELEASE BAR
13	03-27-2023	4	FORMED ROD
14	03-27-2018	4	ROD CLIP
15	03-27-2027	8	NYLON WASHER
16	03-15-7274	6	NAME PLATE- EMERGENCY EXIT, EN, E/J COACH
17	03-15-7275	4	NAME PLATE- EMERGENCY EXIT, FR, E/J COACH
18	03-15-7276	4	NAME PLATE- EMERGENCY EXIT, SP, E/J COACH
19	19-2-37	8	WASHER-LOCK, SST, 1/4DIA
20	19-1-684	8	SCREW-TAPPING,SELF DRILLING,TYPE BSD,#2
21	03-27-1336	4	GASKET-FRICTION, SASH CAM
22	03-27-1338	4	SHIM-OVERCENTER, SASH, CAM



60-Seater J-Coach Egress Window Addition


03-27-1380	4	CAM-NYLON, SASH
03-27-1381	4	CAM-STRIKER, SASH
19-1-603	8	SCREW, PAN HD- #8-32
19-3-155	8	NUT-HEX, LOCK, #8-32, STL
03-27-1137	4	SIDE SASH STRIKER
19-01-1571	8	SCREW-FLANGE WHIZLOCK
19-2-69	16	WASHER-FLAT,1/4"DIA., STEEL ZINC PLATED
19-13-24	20	RIVET 1/8 DIA .126-187 GRIP ALUMINUM.
19-13-169	8	RIVET-BLIND, SELF PLUGGING, MULTI GRIP
19-3-469	8	NUT-RIVNUT, 1/4 - 20
	03-27-1381 19-1-603 19-3-155 03-27-1137 19-01-1571 19-2-69 19-13-24 19-13-169	03-27-1381 4 19-1-603 8 19-3-155 8 03-27-1137 4 19-01-1571 8 19-2-69 16 19-13-24 20 19-13-169 8


2.0 Special Tools

Rivet remover gun, rivet install tool, and Imada push/pull scale.

3.0 Rework Instructions


There is one bolted window on each side of the coach that needs to be converted to egress windows. The following steps demonstrate the instructions for one window. Repeat the entire instructions for the other side to finish the procedure.






3.1 Remove the bolted window components

Remove and discard the 4 screws holding the crash bar to the window.




Remove the 4 screws on the window frame and discard the screws








Using a rivet removal gun, remove the 8 rivets attaching the brackets to the crash bar. Discard the brackets and save the crash bar for later use.




Push the window out with the top still hanging from the hinge, and use a wooden 2" x4" between 20-25" long to hold the window open in that location.






Remove the rivets holding the sash retainer to the frame, 03-27-1189, and discard the retainers.



3.2 Installing components for egress window

3.2.1 Install side-sash striker


Install side-sash striker, 03-27-1137, by aligning the slots of the striker to the existing holes previously used for the sash retainer. Be sure to align the slot center with the center of the hole. Fasten with washers, 19-2-69, and monobolt rivets, 19-13-169.





3.2.2 Install sash cam assembly

Drill 4 new 0.391" diameter holes into the frame through the interior angle, 03-16-1759, at the location indicated below using a 25/64" drill bit.




Make the newly drilled holes into 0.547"x0.625" slots into the interior angle only. Be sure not to slot the frame. Install a 19-3-469 rivnut in each slot of the interior angle.






Assemble the Cam-sash by assembling the cam-nylon sash, 03-27-1380, to the cam-striker sash, 03-27-1381, by using screw, 19-1-603, and hex nut, 19-3-155, as shown below



Remove the backing paper of friction gasket, 03-27-1336, and attach onto the interior angle by aligning the slots of the gasket to the just drilled holes on the interior angle.


Position sash cam assembly over the friction gasket and secure the sash tube with washer, 19-2-69, lock washer, 19-2-37, and screw, 19-01-1571, in that order.






3.2.3 Assemble egress latch mechanism to the window

Install the rod clip, 03-27-2018, to the tri mark rotary latch as shown in the pictures below.




Install formed rod, 03-27-2023, using nylon washers, 03-27-2027, and the release bar bracket, 03-27-2022, as shown in the picture below to the rod clip. Place nylon washers on both sides of the formed rod.







Drill two holes into the latch housing at the locations shown below using a 11/64" drill bit.



Install a recess bumper, 03-27-1068, at each hole using a screw, 03-27-2033 as shown below.




Drill 4 holes on the angle bar of the window frame using 0.3818" drill bit and using an angle grinder cut two squares as shown below.








Install tri/mark rotary latch, 03-27-1074, and latch housing, 03-27-2037, using 2 screws, 03-27-2028, as shown in pictures below.




Install the release bar spring, 03-27-1067, to latch housing using screws, 03-27-1914, such that the profile of the spring sits on the profile of the latch housing.








Place the release bar hinge on the release bar spring such that the holes in the latch housing and release bar hinge are horizontal.



Fix the release bar hinge by inserting the hinge pin, 03-27-1065, through the holes of the latch housing and fasten screws, 03-27-1066, on either ends of the housing to lock the position.






Position shim over center sash, 03-27-1336, on back of the crash bar at the locations indicated below. Using the shim as a template drill four 0.109 holes. Be sure to drill the holes only through the one layer of aluminum extrusion of the crash bar.




Position the crash bar on the window frame such that there is 0.37" gap between the forward facing edge of the release bar cover and the rear facing edge of the post cover.





Mark the location of the release bar hinge holes and the release bar bracket holes on the crash bar and drill four 0.17" holes using 9/64 drill bit. Be sure to drill only through one layer of aluminum extrusion of the crash bar.

Fix the release bar hinge and release bar bracket using screws, 03-27-2034.



Carefully remove the wooden 2x4 installed earlier to allow the window to close.

3.3 Install decals

3.3.1 Install decals on the RH side


Remove the rivets on the existing decals using a rivet removal gun and discard the rivets and the decals.





Clean the crash bar with isopropyl alcohol and allow 5-10 minutes of flash off time.

Position a new English decal, 03-15-7274, such that the left hole in the plate aligns with an already existing hole from the removal of the previous decals.



Mark the right hole of the plate in the crash bar and drill a 0.12" diameter x 0.37" depth hole. Fasten the decal using two aluminum blind rivets, 19-13-24, at the two holes.

Position the Spanish decal, 03-15-7276, if a US coach, or the French decal, 03-15-7275, if a Canadian coach, next to the English decal and mark the holes on the crash bar.

	Spanish decal
TITIS - 2 WINDOW - ARR SALIDA DE EMERGENCIA BAR - 2 WINDOW - MORAN - 2 ESTA BARRA - 2 BAR - 0 OPEN - 2 WINDOW - 2 ESTA BARRA - 2 ESTA BARRA - 2	Spanish decar

Drill two 0.12" diameter x 0.37" depth holes and fasten the decal using two aluminum blind rivets, 19-13-24.

Blind rivets PARA ABRIR LA VENTANA ABARRA Spanish decal



3.4.2 Install decals on the LH side

Remove the rivets on the existing decals using a rivet removal gun and discard the rivets and the decals.

Clean the crash bar with isopropyl alcohol and allow 5-10 minutes of flash off time.

Position a new English decal, 03-15-7274, such that the right hole in the plate aligns with an already existing hole from the removal of the previous decals.

Mark the left hole of the plate in the crash bar and drill a 0.12" diameter x 0.37" depth hole. Fasten the decal using two aluminum blind rivets, 19-13-24, at the two holes.

Position Spanish decal, 03-15-7276, if a US coach, or French decal, 03-15-7275, if a Canadian coach, next to the English decal and mark the holes on the crash bar.


Drill two 0.12" diameter x 0.37" depth holes and fasten the decal using two aluminum blind rivets,19-13-24.

3.4.3 Install decals on the ABS post cover

Locate the ABS post cover between the newly converted egress window and the adjacent egress window.

Clean it with isopropyl alcohol and allow 5-10 minutes of flash off time.

Position and align the Emergency Exit English nameplate, 03-15-7274, as shown in the figure below.



Mark the holes on the post cover and drill 0.12" diameter x 0.37" depth holes.

Secure the nameplate to the ABS post cover using aluminum blind rivets, 19-13-24.



4.0 Test the new Egress window


Secure the hook at the top of the Imada push/pull scale. Attach the hook to the center bottom of the crash bar and pull upward.

Verify the reading to push/pull scale. A minimum of 12lbs and no more than 19lbs is required to close sash tight and snug.



Torque the screws on the sash-cam brackets to 5 Ft-Lbs. until the bracket is solid in position.

- If the reading is above the maximum required 19lbs loosen the 2 screws of sash-cam as illustrated below; push the cam bracket outward and re-tighten the 2 screws.
- If the reading is below minimum 12lbs loosen the 2 screws of sash-cam as illustrated; push the cam bracket inward and re-tighten the 2 screws.



Torque the screws on the sash-cam brackets to 5 Ft-Lbs. until the bracket is solid in position.



5.0 Field Change Program Conditions:

The parts required for this change will be supplied without charge.

A labor allowance of 5 hours will be granted for rework of the window on affected J series coaches.

This labor allowance will be credited to your MCI Fleet Support Parts Account on receipt of the attached "MCI Field Change Program Verification Form" and a "Warranty Claim Form" as detailed in your Owner Warranty manual to MCI's Warranty department. An "MCI Field Change Program Verification Form" needs to be submitted for each VIN affected. Photocopy the attached "MCI Field Change Program Verification Form" as required for the number of affected coaches in your fleet.

Motor Coach apologizes for any inconvenience resulting from this campaign but urges you to implement this change as soon as possible.

Sincerely,

Motor Coach Industries



5.1 MCI FIELD CHANGE PROGRAM (FCP) VERIFICATION

CONTACT INFORMATION				
CUSTOMER NAME:				
(PLEASE PRINT				
FCP INFORM	ATION – ONE FORM PER UNIT			
FCP#:	Coach Model Mo	del Year		
COACH SERIAL #:	DATE COMPLETED / /			
(At least the last 5 digits)				
MILEAGE:				
IMPORTANT: TO RECEIVE CREDIT FOR ANY ALLOWABLE LABOR CHARGES, THIS VERIFICATION FORM MUST BE RETURNED TO MCI UPON COMPLETION OF THE FCP.				
SUBMITTED BY: (Please Print)				
<i>I</i> _ <i>I</i> _		_ DATE		
TITLE: (Please Print)		-		
SIGNATURE:		_		
COMMENTS:				



FAX TO: 800-360-8886

Mail or fax the completed limited warranty claim form and verification form to MCI's warranty department, or photocopy and mail to:

MCI Fleet Support

Attn: Warranty Department

7001 Universal Coach Drive Louisville, KY 40258

Fax Number 1-800-360-8886

To receive credit for the hours used to complete this task. Contact the MCI Fleet Support Technical Center at 1-800-241-2947 for any further information.