

GROUP	NUMBER
RECALL	19-01-001H
DATE	MODEL(S)
MARCH 2019	APPLICABLE VEHICLES BELOW

SUBJECT:

HIGH PRESSURE FUEL PIPE INSPECTION AND REPLACEMENT (RECALL CAMPAIGN 180)

* IMPORTANT

*** Dealer Stock and Retail Vehicles ***

Dealers must perform this Recall Campaign on all affected vehicles prior to customer retail delivery and whenever an affected vehicle is in the shop for any maintenance or repair.

When a vehicle arrives at the service department, access Hyundai Motor America's "Warranty Vehicle Information" screen via WEBDCS to identify open Campaigns.

Description: The high pressure fuel pipe may have been damaged, misaligned, or improperly torqued during prior engine replacement allowing fuel to leak, increasing the risk of a fire. This bulletin describes the procedure to confirm the high pressure fuel pipe is properly installed.

Applicable Vehicles:

Certain 2011-2014 MY Sonata (YF) vehicles with 2.0L Turbo and 2.4L engines

Certain 2015-2018 MY Sonata (LF) vehicles with 2.0L Turbo and 2.4L engines

Certain 2013-2018 MY Santa Fe Sport (AN) vehicles with 2.0L Turbo and 2.4L engines

Certain 2014-2015 MY Tuscon (LM) vehicles with 2.4L engines

Certain 2018 MY Tucson (TL) vehicles with 2.4L engines

SST Information:

Description	Part #	Comment
TORQUE WRENCH SOCKET		
	09314-3Q100-01	
OIL TEST PAPER	SP045-07305	1 box contains 100 test strips

Note: The above tools will be provided to all dealers. Additional units can be ordered through Bosch at 1-866-539-4248.

Parts Information:

Model	MY	Part Name	Part Number	QTY	Comment
Sonata (YF)	11-14 MY	HIGH PRESSURE FUEL PIPE	35305-2G700QQH	1	
Sonata (LF)	15-18 MY	HIGH PRESSURE FUEL PIPE	35305-2GGA0QQH	1	Only required if fuel
Santa Fe	13-16 MY	HIGH PRESSURE FUEL PIPE	35305-2G700QQH	1	pipe replacement is needed based on
Sport (AN)	17-18 MY	HIGH PRESSURE FUEL PIPE	35305-2GGA0QQH	1	vehicle inspection. Refer to Steps
Tucson (LM)	14-15 MY	HIGH PRESSURE FUEL PIPE	35305-2G700QQH	1	7 and 10.
Tucson (TL)	18MY	HIGH PRESSURE FUEL PIPE	35305-2GGA0QQH	1	
Vehicles with 2.0L Turbo	ALL	O-RING (NIPPLE ASSY-RAD)	25649-2G540QQH	1	

Warranty Information:

Model / Engine	Op. Code	Operation	Op. Time	Causal Part No.	Nature Code	Cause Code
	91C004I0	FUEL LEAKAGE INSPECTION	0.3 M/H	11235- 06226-K	E74	ZZ7
All Models 2.4L	91C004R0	FUEL LEAKAGE INSPECTION AND HIGH PRESSURE FUEL PIPE REPLACEMENT	0.6 M/H			
	91C004I1	FUEL LEAKAGE INSPECTION	0.7 M/H			
All Models 2.0L Turbo	91C004R1	FUEL LEAKAGE INSPECTION AND HIGH PRESSURE FUEL PIPE REPLACEMENT	0.9 M/H			

Notes:

- 1) Submit Claim on Campaign Claim Entry Screen
- 2) If a part is found in need of replacement while performing this campaign and the affected part is still under warranty, submit a separate claim using the same Repair Order. If the affected part(s) are out of warranty, request a Prior Authorization # for goodwill consideration prior to completing the Campaign.
- 3) Oil test paper will be reimbursed via sublet.
- 4) Two gallons of coolant will be reimbursed on all 2.0L Turbo claims.

TSB #: 19-01-001H Page 2 of 12

A CAUTION

Follow all procedures in TSB 19-FL-001H. If fuel pipe installation is required based on vehicle inspection, follow the exact tightening process and sequence to install the fuel pipe. Fuel leakage can occur if the fuel pipe is installed incorrectly.

Service Procedure:


1. Record the vehicle's audio presets, then disconnect the negative (-) battery cable.

For 2.0L Turbo vehicles, also remove the engine undercover.

2. Remove the engine cover, air duct, and air intake hose according to the applicable vehicle shop manual.



3. Remove debris on the high pressure fuel pump and the high pressure fuel pipe nuts at (A) and (B) using compressed air.



TSB #: 19-01-001H Page 3 of 12


4. For 2.4L vehicles, skip to Step 5.

For 2.0L Turbo vehicles, disconnect the recirculation solenoid valve connector (C) and hose (D).






4A. **For 2.0L Turbo vehicles**, remove the breather hose (E) and recirculation hose (F).



4B. **For 2.0L Turbo vehicles**, remove the intercooler inlet hose retaining bolt.




TSB #: 19-01-001H Page 4 of 12

4C. **For 2.0L Turbo vehicles**, loosen the intercooler inlet hose clamps and remove the intercooler inlet hose.



4D. For 2.0L Turbo vehicles, remove the ground.



5. Disconnect the ignition coil connector and remove the ignition coil from cylinder #4.

Tightening Torque: 3.9 ~ 5.9N.m (0.4 ~ 0.6kgf.m, 2.9 ~ 4.3lb-ft)



TSB #: 19-01-001H Page 5 of 12

6. For 2.4L vehicles, skip to Step 7.

For 2.0L Turbo vehicles, remove the PCSV Purge control solenoid valve) connector, hoses, and assembly.





6A. For 2.0L Turbo vehicles, drain about $\frac{1}{2}$ gallon of coolant from the radiator.



6B. **For 2.0L Turbo vehicles**, remove the two upper radiator hose bolts (G) from the water temperature control assembly. Replace the O-ring (H) with a new one during reinstallation.

Note: The O-ring (H) does not require a second replacement if the high pressure fuel pipe is replaced.





TSB #: 19-01-001H Page 6 of 12

7. Set a torque wrench to 19.5 lb-ft and check the torque of the fuel pipe nuts (A) and (B) **using the SST**.

Tightening Torque: 26.5 ~32.4 Nm (2.7 ~ 3.3 kgf.m, 19. 5 ~ 23.9 lb-ft)

If both the fuel pipe nuts meet the minimum specification of 19.5 lb-ft:

Continue to the next step.

If either of the fuel pipe nuts are below the minimum specification of 19.5 lb-ft:


 Skip to Step 11 to replace the fuel pipe assembly.

8. Install the ignition coil in cylinder #4, connect the ignition coil connector, and connect negative (-) battery cable.

For 2.0L Turbo vehicles, also install the upper radiator hose (with new O-ring) and top off the coolant.

Tightening Torque (ignition coil): 3.9 ~ 5.9N.m (0.4 ~ 0.6kgf.m, 2.9 ~ 4.3lb-ft)

9. Start the vehicle and rev the engine to 4,000 RPM three times.





TSB #: 19-01-001H Page 7 of 12


10. While the engine is idling, check the area where the fuel pipe connects to the high pressure fuel pump (A) and fuel rail (B) for any indication of fuel leakage or smell.

While the engine is idling, wipe the areas around the high pressure fuel pipe nuts and the gap between the pipe and nuts using the oil test paper.




If the oil test paper appearance does not change:

- Reinstall all removed parts in the reverse order of removal.
- Reprogram the vehicle's audio presets.
- For 2.0L Turbo vehicles, refill and bleed the cooling system.
- Check for DTCs and perform the appropriate diagnostic service. Ensure no warning lights are present to complete the procedure.







NOT OK:

If the oil test paper becomes darker or if there is indication of fuel leakage/smell, follow the procedure to replace the high pressure fuel pipe.

High Pressure Fuel Pipe Replacement (if required):

11. If high pressure fuel pipe replacement is required based on the steps above, repeat Steps 1-5 from above as needed for 2.4L vehicles.

For 2.0L Turbo vehicles, repeat Steps 1-6B.

12. Release the residual pressure in fuel line. Refer to the 'Release residual pressure in fuel line' section in the applicable vehicle shop manual.

Shop Manual > Fuel System > Fuel Delivery


Shop Manual > Fuel System > Fuel Delivery System



Do NOT perform any repairs on the high pressure fuel components immediately after the engine stops due to high pressure fuel in the system.

TSB #: 19-01-001H Page 8 of 12

13. Remove the two (2) ignition wiring harness retaining bolts.



14. **For 2.4L vehicles**, remove the PCSV Purge control solenoid valve) connector, hoses, and assembly.

Note: The PCSV was previously removed for 2.0T vehicles in a prior step.



15. Remove the fuel pipe clamp bolt and bracket.

Tightening Torque: 7.8 ~11.8 Nm (0.8 ~ 1.2 kgf.m, 5.8 ~ 8.7 lb-ft)




TSB #: 19-01-001H Page 9 of 12

16. Remove the high pressure fuel pipe nut (A) from the high pressure fuel pump **using the SST**.

Tightening Torque:


26.5 ~32.4 Nm (2.7 ~ 3.3 kgf.m, 19.5 ~ 23.9 lb-ft)



17. Remove the high pressure fuel pipe nut (B) from the delivery pipe **using the SST**.

Tightening Torque:


26.5 ~32.4 Nm (2.7 ~ 3.3 kgf.m, 19.5 ~ 23.9 lb-ft)



18. Loosen the function block nut (C) and remove and discard the old high pressure fuel pipe. Transfer the center bracket from the old pipe to the new pipe if needed.

Tightening Torque:

7.8 ~11.8 Nm (0.8 ~ 1.2 kgf.m, 5.8 ~ 8.7 lb-ft)



TSB #: 19-01-001H Page 10 of 12

A CAUTION


Follow the exact tightening process and sequence below to install the fuel pipe. Follow all procedures in TSB 19-FL-001H.

- Torque wrench is <u>required</u> for installation.
- Do not fully tighten or use a power tool when noted.
- Fuel leakage can occur if the fuel pipe is installed incorrectly.

19. Install the new high pressure fuel pipe **using the correct sequence.** Hand-tighten the fuel pipe nuts (A) and (B) at both ends of the fuel pipe.



Do NOT fully tighten.
Do NOT use a power tool.



20. Attach the fuel pipe center bracket clamp to the engine by hand-tightening bracket nut (C). Then tighten nut (C) completely **using a torque wrench**.

Tightening Torque:

7.8 ~11.8 Nm (0.8 ~ 1.2 kgf.m, 5.8 ~ 8.7 lb-ft)

21. Tighten the fuel pipe nuts (A) and (B) completely at both ends of the fuel pipe **using a torque wrench with the SST**.

Tightening Torque:

26.5 ~32.4 Nm (2.7 ~ 3.3 kgf.m, 19.5 ~ 23.9 lb-ft)

22. Reinstall all removed parts in the reverse order of removal. Reprogram vehicle's audio presets. **For 2.0L Turbo**, fill and bleed the cooling system with new coolant.



Torque wrench required



Torque wrench and SST required

TSB #: 19-01-001H Page 11 of 12

SUBJECT:

23. Start the vehicle and rev the engine to 4,000 RPM three times. Check for any indication of fuel leakage or fuel smell with an unused portion of the test paper used previously.

24. Check for any DTCs and perform the appropriate diagnostic service. Ensure no warning lights are present to complete the procedure.

TSB #: 19-01-001H Page 12 of 12