### CONDITION OF CONCERN

On certain subject Mazda6 vehicles in salt belt states, it is possible the front cross member may be corroded due to suspected insufficient paint coating. Continued use of the vehicle may allow the corrosion to progress, causing the support of the right lower control arm to decrease. Passing over a pothole may result in breakage of the cross member and reduced steering control, increasing the risk of a crash.


# PRELIMINARY ACTION (Until repair parts are available): Parts expected to be available in early January 2019

As repair parts are not currently available, a final repair cannot be performed at this time, and preliminary action is necessary until the parts are available.

- 1) Inspect the condition of the front cross member, and determine if it passes the inspection criteria.
- 2) a) If the cross member passes inspection, please ask the customer to return to the dealer for repair when repair parts are available (parts available notification).
  - b) If the cross member fails inspection, please arrange a free rental or loaner vehicle for the customer to use as a replacement for their vehicle until repair parts are available.

## **OUITLINE OF REPAIR (After Parts are Available)**

- OK vehicle: If the cross member passes inspection, install a support brace and A/C drain hose, and apply anti-rust cavity wax to the cross member.
- Not OK vehicle: If the cross member fails inspection, replace the cross member with a modified one and install a drain hose.



Support brace

Please refer to the Inspection and Repair Procedure document on MGSS for the details.

## **SUBJECT VEHICLES**

Model	Subject VIN range	Subject build date range	Note
2009-2010MY Mazda6	1YV HP**** 95 M00001 – M52259 1YV HZ**** A5 M00014 – M58879	I From Fontilary 4 Julia	Currently or ever registered in Salt belt states

The asterisk symbol "\*" can be any letter or number.

## **OWNER NOTIFICATION**

Mazda notified U.S. owners by first class mail on November 9, 2018.

## PARTS INFORMATION FOR PARTS ORDERING

Description	Part Number	Quantity	Remarks
Cross Member Kit I4	0000-I4-2818	1	Includes cross member and drain hose.
Cross Member Kit V6	0000-V6-2818	1	Includes all gaskets, cross member and drain hose.
Side member kit	0000-GD-2818	1	Includes nut-fastener kit, bracket and drain hose.
Cavity Wax	0000-07-712 AM	1	For vehicles requiring Side Member Kit

## PARTS INFORMATION FOR WARRANTY CLAIMS

Description	Part Number	Quantity	Remarks Scra		Scrap
Cross Member	GS3L-34-80XE	1		For I4 (2.5L) engine	YES
Cross member	GS4H-34-80XD	1		For V6 (3.7L) engine	YES
Gasket	CA01-40-305	1	Vehicles that fail cross member inspection	E 1/0 (0.7L)	\/F0
Seal Ring	CA02-40-581	1		For V6 (3.7L) engine	YES
Gasket	CY01-40-305A	1			
Side member kit	GSYM-34-H1X	1	Vehicles that pass cross member inspection	Component: support brace and bracket	
Nut-Fastener kit	GSYM-34-H2X	1		Component: nuts, fasteners, bolts and washers	N/A
Cavity Wax	7777-SP-P67	1		Protectant – Note: This is 1/8 of a can of cavity wax.	
Drain hose	GSY0-61-52X	1	For All vehicles N/		N/A
Campaign Label	9999-95-065A-06	1=50 labels	Obtain in Mazda e-Store (no charge)		

## **WARRANTY CLAIM PROCESSING INFORMATION**

## For Tentative Action (until repair parts are available):

	Inspection Only
Process Number	AJ047A
Symptom Code	99
Damage Code	99
Part Number Main Cause	7777-SP-P54
Quantity	0
Labor Operation Number	XXP8YXCX
Labor Hours	0.5 H

Note: Repair will be performed at a later date when the repair parts are available.

## Repair at a later date: Parts are available and vehicle already inspected

	Installation of Support Brace & Drain Hose Application of Wax	
Process Number	AJ047B	
Symptom Code	99	
Damage Code	99	
Part Number Main Cause & Quantity	GSYM-34-H1X Qty 1	
Related Parts Number & Quantity	GSYM-34-H2X Qty 1 GSY0-61-52X Qty 1 7777-SP-P67 Qty 1	
Labor Operation Number	XXP8ZXRX	
Labor Hours	2.3 H (I4 engine) 1.5 H (V6 engine)	

## Repair at a later date: Parts are available and vehicle already inspected

	Replacement of Cross Member Installation of Drain Hose Adjustment of Wheel Alignment				
Process Number			AJ047B		
Symptom Code	99				
Damage Code			99		
Part Number Main Cause & Quantity			KE Qty 1 (I4 end KD Qty 1 (V6 end	9 ,	
Related Parts Number & Quantity	GSY0-61-52X Qty 1				
	CA01-40-305 Qty 1 (3.7) V6 CA02-40-581 Qty 1 (3.7) V6 CY01-40-305A Qty 1 (3.7) V6		V6		
	Operation No.	Labor Hours	Applicable to:	Note (operation)	
	XXP91XRX	2.9 H	l4 Eng.	Cross member	
Labor Operation Number &	XXP91XRX	3.1 H	V6 Eng.	replacement & Drain hose Installation	
Labor Hours	XXP94AAX	1.1 H	Wire type	Alignment adjustment	
	XXP94BAX	0.7 H	Wireless type	Alignment adjustment	

Note: If any other parts need to be replaced due to damage caused directly by failure of the front cross member or if additional time is required, submit applicable part numbers, quantities, and time as related parts <u>AFTER YOU RECEIVE PRIOR AUTHORIZATION FROM THE WARRANTY DEPARTMENT.</u>

# For Inspection & Repair (After repair parts are available): Previous inspection and claim not performed check eMDCS

	Inspection (OK) Installation of Support Brace & Drain Hose Application of Wax	
Process Number	AJ047C	
Symptom Code	99	
Damage Code	99	
Part Number Main Cause & Quantity	GSYM-34-H1X Qty 1	
Related Parts Number & Quantity	GSYM-34-H2X Qty 1 GSY0-61-52X Qty 1 7777-SP-P67 Qty 1	
Labor Operation Number	XXP92XRX	
Labor Hours	2.7 H (I4 engine) 1.9 H (V6 engine)	

	Inspection (Not OK) Replacement of Cross Member Installation of Drain Hose			
	Adjustment of Wheel Alignment			
Process Number	AJ047C			
Symptom Code	99			
Damage Code	99			
Part Number Main	GS3L-34-80XE Qty 1 (I4 engine)			
Cause & Quantity		GS4H-34-80XD Qty 1 (V6 engine)		
Related Parts Number	GSY0-61-52X Qty 1			
& Quantity	CA01-40-305 Qty 1 (3.7) V6			
	CA02-40-581 Qty 1 (3.7) V6			
		CY01-40-3	305A Qty 1 (3.7	) V6
	Operation No.	Labor Hours	Applicable to:	Note (operation)
	XXP93XRX	3.3 H	I4 Eng.	Inspection, Cross member replacement &
Labor Operation Number &	XXP93XRX	3.5 H	V6 Eng.	Drain hose Installation
Labor Hours	XXP94AAX	1.1 H	Wire type	Alignment adjustment
	XXP94BAX	0.7 H	Wireless type	Alignment adjustment

Note: If any other parts need to be replaced due to damage caused directly by failure of the front cross member or if additional time is required, submit applicable part numbers, quantities, and time as related parts <u>AFTER YOU RECEIVE PRIOR AUTHORIZATION FROM THE WARRANTY DEPARTMENT.</u>

## For vehicles of which cross member was replaced with modified one:

(Repaired prior to launch of recall): Approximately May 2018 and later. MUST CHECK eMDCS and list of applicable vehicles already repaired.

	Installation of Drain Hose	
Process Number	AJ047D	
Symptom Code	99	
Damage Code	99	
Part Number Main Cause & Quantity	GSY0-61-52X Qty 1	
Labor Operation Number	XXP9JXRX	
Labor Hours	0.3 H (I4 engine) 0.2 H (V6 engine)	

### **RENTAL CAR INFORMATION**

Mazda recommends the usage of the MCVP loaner vehicle when available. If all MCVP loaner vehicles are in use and unavailable, and the customer needs a rental car, then use your local rental facility and offer a rental car. Be sure that every effort is made to repair the car within one business day or less in order to allow the next customer the same experience.

### **Rental Car Warranty Claim Information**

	MCVP Vehicle Preferred	Rental Agency Vehicle
Warranty Type Code		A
Symptom Code		99
Damage Code		99
Part Number Main Cause		5555-28-18IR
Part Quantity		0
Labor Operation Code		MM024XRX
Labor Hours	N/A	0
Sublet – Rental Car		
Sublet Invoice Number	MCVP does not require claim submission	Number from Rental Invoice or Dealer Purchase Order
Sublet Type Code		Enter "Z9" (other)
Sublet Amount		Up to \$30.00 per day for
		the number of days
		customer had rental car
Sublet Text		Number of days rental car
		was supplied to customer

Rental expenses exceeding the two-day limit will require prior <u>Warranty Department</u> <u>Authorization</u>, as outlined in the Mazda Rental Car Reimbursement Program policy.