

Part 573 Safety Recall Report

19V-326

Manufacturer Name : Jaguar Land Rover North America, LLC**Submission Date :** APR 25, 2019**NHTSA Recall No. :** 19V-326**Manufacturer Recall No. :** H208**Manufacturer Information :****Population :**

Manufacturer Name : Jaguar Land Rover North America, LLC

Number of potentially involved : 7,060

Address : 100 Jaguar Land Rover Way

Estimated percentage with defect : 100 %

MAHWAH NJ 07495

Company phone : 8188500

Vehicle Information :

Vehicle 1 : 2014-2015 JAGUAR F-TYPE

Vehicle Type : LIGHT VEHICLES

Body Style : 2-DOOR

Power Train : NR

Descriptive Information : Jaguar Land Rover have identified certain F-TYPE 2014 and 2015 Model Year vehicles, previously remedied in recall J047, that may have had a seat belt service part installed containing the same defect as the parts from the original recall. Number of vehicles affected is 7060.

In the affected vehicles the seatbelt harness connector which connects the Seatbelt Tension Sensor (STS) to the Occupant Classification Sensor Control Module (OCSCM) may not have been correctly wired. The OCSCM senses whether there is an occupant in the front passenger seating position, and the STS senses whether tension on the seatbelt indicates a child restraint is being used in the front passenger seating position. Both sensors provide information to the restraint control module (RCM) which informs whether the front passenger airbag should be activated, depending on whether the sensors detect the seat is occupied and/or that it is occupied by an adult passenger.

Should the STS not have been wired correctly, the front passenger air bag may not be suppressed, and may remain activated, even when a child restraint is placed in the front passenger seat or a small statured adult occupies the passenger seat.

Production Dates : AUG 31, 2012 - DEC 09, 2014**VIN Range 1 : Begin :** SAJWA6FC6E8K00001 **End :** SAJWA6ET4F8K19746 Not sequential

Description of Defect :

Description of the Defect : Jaguar Land Rover have identified certain F-TYPE 2014 and 2015 Model Year vehicles, previously remedied in recall J047, that may have had a seat belt service part installed containing the same defect as the parts from the original recall.

In the affected vehicles the seatbelt harness connector which connects the Seatbelt Tension Sensor (STS) to the Occupant Classification Sensor Control Module (OCSCM) may not have been correctly wired. The OCSCM senses whether there is an occupant in the front passenger seating position, and the STS senses whether tension on the seatbelt indicates a child restraint is being used in the front passenger seating position. Both sensors provide information to the restraint control module (RCM) which informs whether the front passenger airbag should be activated, depending on whether the sensors detect the seat is occupied and/or that it is occupied by an adult passenger.

Should the STS not have been wired correctly, the front passenger air bag may not be suppressed, and may remain activated, even when a child restraint is placed in the front passenger seat or a small statured adult occupies the passenger seat.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : In the event of a crash necessitating deployment of the front passenger air bag, a child or small stature occupant may be at an increased risk of injury.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

Supplier Identification :**Component Manufacturer**

Name : Jaguar Land Rover Limited

Address : Abbey Road

Whitley Coventry FOREIGN STATES CV3 4LF

Country : United Kingdom

Chronology :

See File "Recall H208 Chronology".

Description of Remedy :

Description of Remedy Program : Owners will be notified and instructed to take their vehicle to a Jaguar approved repairer who will inspect the seat belt assembly. If required, the technician will complete a repair to the seatbelt tension sensor harness.

There will be no charge to owners for this inspection or replacement.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

Recall Schedule :

Description of Recall Schedule : Owner notification letters will occur on or before June 21, 2019.
Notifications to dealers will occur on May 09, 2019.

Planned Dealer Notification Date : MAY 09, 2019 - MAY 09, 2019

Planned Owner Notification Date : JUN 21, 2019 - JUN 21, 2019

* NR - Not Reported