

# Part 573 Safety Recall Report

## 19V-384

**Manufacturer Name :** Newmar Corporation

**Submission Date :** MAY 22, 2019

**NHTSA Recall No. :** 19V-384

**Manufacturer Recall No. :** FL-816 & #19V-367



### Manufacturer Information :

Manufacturer Name : Newmar Corporation

Address : 355 North Delaware Street  
PO Box 30 Nappanee IN 46550

Company phone : 574-773-7791

### Population :

Number of potentially involved : 3

Estimated percentage with defect : 100 %

### Vehicle Information :

Vehicle 1 : 2019-2019 Newmar Mountain Aire

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could increase the risk of a vehicle crash. Correction: potentially affected vehicles will be inspected and repaired as necessary at no charge.

2019 Mountain Aire=2

Production Dates : OCT 15, 2018 - NOV 27, 2018

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

Vehicle 2 : 2019-2019 Newmar Essex

Vehicle Type : BUSES, MEDIUM & HEAVY VEHICLES

Body Style :

Power Train : NR

**Descriptive Information :** On certain motorhomes, the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness. Reduced brake effectiveness could increase the risk of a vehicle crash. Correction: potentially affected vehicles will be inspected and repaired as necessary at no charge.

2019 Essex=1

Production Dates : OCT 15, 2018 - NOV 27, 2018

VIN Range 1 : Begin : NR End : NR

☐ Not sequential

**Description of Defect :**

Description of the Defect : the brake caliper mounting bolts may be incorrectly torqued. This could result in caliper bolts loosening. Insufficiently torqued bolts may not provide adequate clamping force between the brake caliper and brake anchor plate potentially resulting in reduced brake effectiveness.

FMVSS 1 : NR

FMVSS 2 : NR

Description of the Safety Risk : Reduced brake effectiveness could increase the risk of a vehicle crash.

Description of the Cause : NR

Identification of Any Warning that can Occur : NR

**Supplier Identification :****Component Manufacturer**

Name : Daimler Trucks North America LLC

Address : P.O. Box 3849  
Portland OREGON 97208

Country : United States

**Chronology :**

On 5/21/2019 DTNA gave notice to Newmar of a safety defect. On 5/22/2019, Newmar is giving notice of safety defect.

**Description of Remedy :**

Description of Remedy Program : potentially affected vehicles will be inspected and repaired as necessary at no charge.

How Remedy Component Differs from Recalled Component : NR

Identify How/When Recall Condition was Corrected in Production : NR

**Recall Schedule :**

Description of Recall Schedule : On or before 7/21/2019, customer/dealer letters will be mailed.

Planned Dealer Notification Date : JUL 21, 2019 - JUL 21, 2019

Planned Owner Notification Date : JUL 21, 2019 - JUL 21, 2019

\* NR - Not Reported