OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :Ford Motor CompanySubmission Date :JUL 05, 2019NHTSA Recall No. :19V-515Manufacturer Recall No. :19S22

Manufacturer Information :

Manufacturer Name : Ford Motor Company Address : 330 Town Center Drive Suite 500 Dearborn MI 48126-2738 Company phone : 1-866-436-7332

Population:

Number of potentially involved : 57,488 Estimated percentage with defect : 100 %

Vehicle Information :

Vehicle 1:	2012-2012 Ford Focus			
• •	LIGHT VEHICLES			
Body Style :				
Power Train :	GAS			
Descriptive Information :	This action includes certain 2012 and 2017MY Focus vehicles equipped with 2.0L GDI gasoline engines and 2013-2014MY Focus vehicles equipped with 2.0L GTDI gasoline engines that had their powertrain control module software reprogrammed as part of recall 18S32.			
	Vehicles that have not had 18S32 performed are not affected by this action and will receive updated software under the existing 18S32 program.			
	32,373 2012MY 2.0L GDI vehicles are affected.			
	These vehicles are not produced in VIN order. Information as to the applicability of this action to specific vehicles can best be obtained by either calling Ford's toll-free line (1-866-436-7332) or by contacting a local Ford or Lincoln dealer who can obtain specific information regarding the vehicles from the Ford On-line Automotive Service Information System (OASIS) database.			
Production Dates :	OCT 07, 2010 - JUL 23, 2012			
VIN Range 1 :	Begin : NR End : NR			
Vehicle 2:	2013-2014 Ford Focus ST			
Vehicle Type :	LIGHT VEHICLES			
Body Style :				
Power Train :	GAS			
Descriptive Information :	This action includes certain 2012 and 2017MY Focus vehicles equipped with 2.0L GDI gasoline engines and 2013-2014MY Focus vehicles equipped with 2.0L GTDI gasoline engines that had their powertrain control module software reprogrammed as part of recall 18S32.			
The i	nformation contained in this report was submitted pursuant to 49 CFR §573			



19V-515

Part 573 Safety Recall Report

19V-515

Page 2

				ffected by this action and will
	receive updated software under the existing 18S32 program. 3,966 2013-2014MY 2.0L GTDI vehicles are affected.			
	3,966 2013-	2014MY 2.0L	aTDI vehicles are affected.	
	this action to line (1-866- specific info	o specific vehic 436-7332) or	cles can best be obtained by by contacting a local Ford or ding the vehicles from the Fo	ation as to the applicability of either calling Ford's toll-free Lincoln dealer who can obtain ord On-line Automotive Service
Production Dates :	MAY 03, 201	12 - DEC 11, 20	14	
VIN Range 1:1	Begin :	NR	End: NR	□ Not sequential
Vehicle 3.	2017-2017	Ford Focus		
Vehicle Type :				
Body Style :				
Power Train :	GAS			
Descriptive Information :	gasoline eng	ines and 2013 had their pow	-2014MY Focus vehicles eq	vehicles equipped with 2.0L GE uipped with 2.0L GTDI gasoline ware reprogrammed as part of
			18S32 performed are not a under the existing 18S32 pr	ffected by this action and will ogram.
	21,149 2017	MY 2.0L GDI v	vehicles are affected.	
	this action to line (1-866- specific info	o specific vehic 436-7332) or [cles can best be obtained by by contacting a local Ford or ding the vehicles from the Fo	ation as to the applicability of either calling Ford's toll-free Lincoln dealer who can obtair ord On-line Automotive Service
Production Dates :		e e		
VIN Range 1:		NR	End: NR	☐ Not sequential
Description of Defect : Description of the Defe	with new A CPV th fuel vapo occurs, th	v software that at is stuck ope or managemen he customer m	ot have the powertrain cont will detect a malfunctionin n in these vehicles can cause t system, potentially deform ay observe a Malfunction Ir el gauge indication, drivabil	g canister purge valve (CPV). e excessive vacuum in the ning the fuel tank. If this ndicator Light (MIL),

FMVSS 1 :	NR
FMVSS 2 :	NR
Description of the Safety Risk :	A vehicle without the intended 18S32 calibrations remains at risk for an engine stall while driving without warning or without the ability to restart, increasing the risk of a crash.
Description of the Cause :	The updated software calibrations that were intended to be installed in certain 2012 and 2017MY Focus 2.0L GDI and 2013-2014MY Focus 2.0L GTDI vehicles in accordance with safety recall 18S32 were not properly developed or released into service.
	Affected vehicles may illuminate a Malfunction Indicator Light (MIL) or customers may observe inaccurate fuel gauge indication, inaccurate distance to empty indication and/or have drivability concerns.

Supplier Identification :

Component Manufacturer

Name : NR Address : NR NR Country : NR

Chronology:

In November 2018, a dealer contacted Ford about the service software for Focus 2.0L GTDI vehicles equipped with Ford Performance Racing calibrations. Ford personnel undertook a review of the software calibration intended for use on these vehicles as part of recall 18S32. During this review Ford identified that the powertrain control module (PCM) calibrations used to service the 2013-14 MY Focus GTDI engine applications for 18S32 were not updated.

Based on insufficient supply of replacement fuel tanks, the initial 18S32 customer letter informed owners of all vehicles affected by that program that they would be contacted by Ford when they should schedule a repair appointment with their dealer. However, dealers were able to perform the 18S32 repair on vehicles that were brought in for service. For the specific model year and powertrain variants included in this defect notice, this included calibrations that had not been updated and released properly.

During development of updated calibration software for 2013-2014MY Focus vehicles equipped with a 2.0L GTDI engine, Ford further identified two 2012MY and four 2017MY Focus 2.0L GDI calibrations that were also not released properly for service.

On June 28, 2019, Ford's Field Review Committee reviewed the concern and approved a field action.

The information contained in this report was submitted pursuant to 49 CFR §573

Ford is not aware of any reports of accident or injury related to this condition.

Description of Remedy : Description of Remedy Program : Owners will be notified by mail and instructed to take their vehicle to a Ford or Lincoln dealer to have the Powertrain Control Module (PCM) reprogrammed with new software that will detect a malfunctioning CPV and prevent a potential excessive fuel vapor system vacuum condition from occurring. Dealers will check for Diagnostic Trouble Codes (DTC) and replace the CPV as necessary. If the CPV is replaced, dealers will inspect and replace the carbon canister, fuel tank and fuel delivery module as necessary. There will be no charge for this service. Until the vehicle is serviced for this concern customers are advised to maintain at least 1/2 tank of fuel. Ford provided the general reimbursement plan for the cost of remedies paid for by vehicle owners prior to notification of a safety recall in February 2019. The ending date for reimbursement eligibility is August 19, 2019. Ford will forward a copy of the notification letters to dealers to the agency when available. How Remedy Component Differs New software calibrations to update certain 2012 and 2017MY Focus 2.0L from Recalled Component: GDI and 2013-2014MY Focus 2.0L GTDI vehicles are released for service. Identify How/When Recall Condition This issue does not affect current production vehicles. was Corrected in Production :

Recall Schedule :

Description of Recall Schedule :	Notification to dealers is expected to occur on July 8, 2019. Mailing of owner notification letters is expected to begin July 29, 2019 and is		
	expected to be completed by August 2, 2019.		
Planned Dealer Notification Date :	JUL 08, 2019 - JUL 08, 2019		
Planned Owner Notification Date :	JUL 29, 2019 - AUG 02, 2019		

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573