OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :BMW of North America, LLCSubmission Date :AUG 06, 2019NHTSA Recall No. :19V-579Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : BMW of North America, LLC Address : P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

Vehicle Information :

Vehicle 1:	2008-2012 BMW 1 Series Coupe (128i, 135i, 135is)				
Vehicle Type :	: LIGHT VEHICLES				
Body Style :	2-DOOR				
Power Train :	GAS				
Descriptive Information :	Approximately 22,188 vehicles were equipped with a blower-regulator wiring harness in which the connectors at the ends of the harness are coated with tin which could lead to fretting corrosion at its connection to the blower-regulator.				
	Basis for recall population determination: Vehicle assembly and supplier production records were evaluated for the start date of the blower-regulator wiring harness containing silver coated connectors at the ends of the harness.				
	Recall component differentiation to non-recall component: The recall component (blower-regulator wiring harness) has tin coated connectors at the end of the harness, while the non-recall component has silver coated connectors at the end of the harness.				
Production Dates :	NOV 01, 2007 - SEP 05, 2011				
VIN Range 1:					
	Approximately 19,793 vehicles were equipped with a blower-regulator wiring harness in which the connectors at the ends of the harness are coated with tin which could lead to fretting corrosion at its connection to the blower-regulator.				
	Basis for recall population determination: Vehicle assembly and supplier production records were evaluated for the start date of the blower-regulator wiring harness containing silver coated connectors at the ends of the harness.				
The i	nformation contained in this report was submitted pursuant to 49 CFR §573				



Number of potentially involved : 41,981

Estimated percentage with defect : 1%

Population :

19V-579

art 573 Safety	Reca	ll Rep	ort	19V-579	Page
(b ha	lower-regu	lator wiring	harness) has tin coate	component: The recall con ed connectors at the end of lver coated connectors at th	the
Production Dates : N	OV 12, 2007	7 - MAY 26, 2			
VIN Range 1 : Beg	gin :	NR	End: NR	□ Not	sequential
Description of Defect :	m1 · 1			ring harness. The blower-	1.
	controls the conditional conjunction the wiring could lead which wo electrical temperatu	he blower-m ing system. (on with relat g harness, wh l to frictional uld occur at resistance at ure increase.	otor's fan speed (air f Over time, irregulariti ive movements of the nich connects to the ti corrosion. In combin maximum blower-mo this connection could	low) within the heating and es in the crimp connection tin-coated connector at the n-coated blower-regulator nation with very high curre tor fan speed, variations in l occur, which could lead to ld be damaged, and could le	d air in e end of pin, nt flow, the o a
	partial con current flo	ntact of indiv		his could result in an irreg	
FMVSS 1 : FMVSS 2 :					
Description of the Safety Risk : Potential overheating could occur. If this condition occurs, there is a rist the heat generated could melt the plastic surrounding the blower-regulated and increase the risk of a fire.					
Description of the Cause : Identification of Any Warning that can Occur :	The heating	0	000	uddenly stop functioning. eable within the vehicle int	
Supplier Identification :					
Component Manufacturer					
Name : LEONI Bordnetz-S	Systeme Gm	bH			
Address : Flugplatzstraße 7	•				
Kissingen FOREIG		97318			
Country : Germany					

The information contained in this report was submitted pursuant to 49 CFR \$573

Part 573 Safety Recall Report

19V-579

Chronology :

Please refer to BMW's October 25, 2017, and amended December 20, 2017, Part 573 reports assigned NHTSA Recall ID 17V-676 involving Model Year 2008 – 2012 BMW 3 Series vehicles. Subsequent to the filing and implementation of 17V-676, the field continued to be monitored.

Between 2018 and 2019, NHTSA requested BMW to provide updates and to hold periodic discussions with the agency regarding BMW's engineering and field monitoring progress for other models with a similar design.

In May 2019, BMW became aware of the first field report involving interior damage to a 1 Series, specifically a Model Year 2011 135i Convertible. The vehicle inspection in June 2019 indicated that the damage seemed to be consistent with an issue involving the blower regulator wiring harness.

Production records were reviewed to determine the number and production range of potentially affected vehicles.

On July 30, 2019, BMW decided to conduct a voluntary recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue involving the BMW 1 Series.

Description of Remedy :

Description of Remedy Program :	The blower-regulator wiring harness will be inspected and a new part will be installed. Additional components will be replaced, if necessary, as determined at the time of repair.		
	Owners will be notified by First Class mail and instructed to take their vehicle to an authorized BMW center to have the remedy performed for free. Owners who have replaced the blower-regulator wiring harness at their own expense prior to the recall notification may be eligible for reimbursement according to BMW Group's reimbursement plan in accordance with 49 CFR 573.13 and 49 CFR 577.11.		
	Recalled Component: Blower-Regulator Wiring Harness with Tin-Coated End Connectors; p/n : No BMW part number.		
Identify How/When Recall Condition was Corrected in Production :	NR		

Recall Schedule :

Description of Recall Schedule :	Dealer notification is planned to begin and end on Aug 6, 2019.
	Owner notification is planned to begin and end on Sep 27, 2019.

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

19V-579

Planned Dealer Notification Date :AUG 06, 2019 - AUG 06, 2019Planned Owner Notification Date :SEP 27, 2019 - SEP 27, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573