OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name : Mercedes-Benz USA, LLC. Submission Date : AUG 21, 2019 NHTSA Recall No.: 19V-586 Manufacturer Recall No.: NR

Manufacturer Information :

Manufacturer Name : Mercedes-Benz USA, LLC. Address: 13470 International Parkway Jacksonville FL 32218 Company phone: 1-877-496-3691

Vehicle Information :

	2018-2019 Mercedes-Benz C300
Vehicle Type :	LIGHT VEHICLES
Body Style :	4-DOOR
Power Train :	GAS
Descriptive Information :	205.048 WF4J 2301 Vehicles, 205.083 WF8D 12144 Vehicles The recall population was determined through production records. Vehicles outside of the affected recall population have mounting brackets manufactured according to current production specifications.
Production Dates :	AUG 02, 2018 - JUL 21, 2019
	Begin : 55SWF4JB0JU276244 End : 55SWF8EBXKU308152 Not sequential
Vehicle 2:	2018-2019 Mercedes-Benz C300 4MATIC
Vehicle Type :	LIGHT VEHICLES
Body Style :	4-DOOR
Power Train :	GAS
Descriptive Information :	205.049 WF4K 1595 Vehicles,
1	205.084 WF8E 8915 Vehicles
	The recall population was determined through production records. Vehicles outside of the affected recall population have mounting brackets manufactured according to current production specifications.
Due duetter Deter	
	AUG 02, 2018 - JUL 21, 2019
vin kange 1:	Begin :55SWF4JB0JU276244End :55SWF8EBXKU308152Image: Not sequential
Vehicle 3:	2019-2019 Mercedes-Benz C43 AMG 4MATIC
	LIGHT VEHICLES
Body Style :	
Power Train :	
The ir	nformation contained in this report was submitted pursuant to 49 CFR §573

云 🔨 🔂

19V-586



Number of potentially involved : 26,584 Estimated percentage with defect : 100 %



Part 573 Safety Recall Report

19V-586

of	5.064 WF6E 1629 Vehicles e recall population was determined through production records. Vehicles outside the affected recall population have mounting brackets manufactured according to rrent production specifications.	
	IG 02, 2018 - JUL 21, 2019	
	in : 55SWF4JB0JU276244 End : 55SWF8EBXKU308152 Not sequential	
0 0		
Description of Defect :		
Description of the Defect :	Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vehicles, has determined that on certain Model Year ("MY") 2018-2019 C-Class vehicles (205 platform) the mounting bracket for the 12V starter battery might not have been manufactured according to current production specification.	
FMVSS 1 :	NR	
FMVSS 2 :	NR	
	If the battery is not properly secured, it could shift and disconnect the terminals in the event of a crash. If this were to occur, the vehicle's power supply would be interrupted, impairing different post-crash functionalities that serve to reduce consequential damage and assist in rescuing the occupants according to the type and severity of accident. These potentially impaired functions could include: activation of the Mercedes-Benz emergency call system, activation of hazard warning lights, activation of interior emergency lighting, lowering of the front side windows, opening of the central locking system, and/or raising of the electrically adjustable steering column. Furthermore, if the battery detaches from the vehicle in a crash, it could become a road hazard, increasing the risk of injury for other road users.	
Description of the Cause :	Due to a production deviation at a supplier, a certain batch of battery mounting brackets might not meet current production specifications.	
	The customer might be made aware of the issue by rattling/knocking noises from the engine compartment during driving.	
Supplier Identification :		
Component Manufacturer		
Name : Arkal Automotive	USA	
Address : 2490 Innovation Drive		
Auburn ALABAMA 36832		
Country : United States		

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

19V-586

Chronology :

In mid-January 2019, DAG launched initial investigations based on an information received from its supplier regarding potential deviations in the production process of certain battery mounting brackets. The investigation revealed that the tightening torque of the bolt connection between battery mounting bracket and base plate was too high, potentially leading to cracks in the material of the mounting brackets. Beginning in March 2019, DAG conducted an analysis of the potential for crack propagation in the mounting brackets and if so, the rate and time period it could occur. In April 2019, analyses indicated that the initial cracks might advance further due to loads and vibrations during driving. The cracks might ultimately cause the mounting bracket to break. Beginning in May 2019, DAG considered the potential consequences of a broken mounting bracket. The analysis was focused primarily on the battery mounting bracket's potential behavior during a crash and, if the mounting bracket did fail, the possible impacts on the performance of the battery itself. In parallel, the range of potentially affected vehicles was determined by analyzing supplier documentation. In the beginning of August 2019, DAG determined that a potential safety risk cannot be ruled out.

Description of Remedy :

Description of Remedy Program :	As a precautionary measure, an authorized Mercedes-Benz dealer, will replace the battery mounting bracket on the affected vehicles. Pursuant to 49 C.F.R. § 577.11(e), MBUSA does not plan to provide notice about pre-notice reimbursement to owners since all involved vehicles remain covered under the new vehicle warranty.
from Recalled Component : Identify How/When Recall Condition	Battery mounting brackets manufactured according to specification with correct tightening torque. A2056202802 Halter Batterie A change in the production procedure of our supplier ensures that this issue can no longer occur from August 2, 2019 onwards.
Recall Schedule : Description of Recall Schedule : Planned Dealer Notification Date : Planned Owner Notification Date :	

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573