OMB Control No.: 2127-0004

Part 573 Safety Recall Report

Manufacturer Name :BMW of North America, LLCSubmission Date :AUG 14, 2019NHTSA Recall No. :19V-599Manufacturer Recall No. :NR

Manufacturer Information :

Manufacturer Name : BMW of North America, LLC Address : P.O. Box 1227 Westwood NJ 07675-1227 Company phone : 18005257417

Vehicle Information :

17 1 • 1 4					
Vehicle 1:	2019-2019 BMW i3 BEV	I			
Vehicle Type :	LIGHT VEHICLES				
Body Style :	4-DOOR				
Power Train :	HYBRID ELECTRIC				
Descriptive Information :	Approximately 27 vehic may not have been prod		Electronics (EME) module that		
	Basis for recall population determination: Supplier production information was used to identify the start and end date of the EME modules which may have been subject to an out-of-specification production process which was then correlated with vehicle assembly information to determine the start date and the end date of potentially affected vehicles.				
		ence to non-recall component it Board (PCB) that may not ha			
Production Dates :	JAN 09, 2019 - FEB 25, 2	019			
Production Dates : VIN Range 1 :		019 End: NR	□ Not sequential		
VIN Range 1:			☐ Not sequential		
VIN Range 1 : Vehicle 2 :	Begin : NR 2019-2019 BMW i8		☐ Not sequential		
VIN Range 1 : Vehicle 2 : Vehicle Type :	Begin : NR 2019-2019 BMW i8 LIGHT VEHICLES		☐ Not sequential		
VIN Range 1 : Vehicle 2 : Vehicle Type : Body Style :	Begin : NR 2019-2019 BMW i8 LIGHT VEHICLES		☐ Not sequential		
VIN Range 1 : Vehicle 2 : Vehicle Type : Body Style : Power Train :	Begin : NR 2019-2019 BMW i8 LIGHT VEHICLES 2-DOOR HYBRID ELECTRIC	End : NR			



Number of potentially involved : 139 Estimated percentage with defect : 10 %

Population :

19V-599

ion :

Part 573 Safety Recall Report

19V-599

	affected vehic	cles.				
		inted Circuit	nce to non-recall componen Board (PCB) that may not h			
Production Dates :	FEB 07, 2019	- MAR 06, 20)19			
VIN Range 1:B	egin :	NR	End: NR	□ Not sequential		
	2019-2019 B					
Vehicle Type : Body Style :		LES				
Power Train :		CTRIC				
-	11	pproximately 106 vehicles contain an Electric Motor Electronics (EME) module that hay not have been produced to specifications.				
	to identify the an out-of-spe assembly info	asis for recall population determination: Supplier production information was used o identify the start and end date of the EME modules which may have been subject t n out-of-specification production process which was then correlated with vehicle ssembly information to determine the start date and the end date of potentially ffected vehicles.				
	contains a Pri specifications	inted Circuit s.	nce to non-recall componen Board (PCB) that may not h	-		
	contains a Pri specifications DEC 19, 2018	inted Circuit s.	Board (PCB) that may not h	-		
Production Dates : VIN Range 1 : B Description of Defect :	contains a Prispecifications DEC 19, 2018 egin : UUIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII	y recall invol oduction at a ave been pro resistance a 'he EME mod	Board (PCB) that may not h D19 End: NR ves the Electric Motor Elect sub-supplier, the EME's Pr oduced to specifications. Th t certain PCB contact points lule would detect this conditional conditiona	nave been produced to		
Production Dates : VIN Range 1 : B Description of Defect :	contains a Prispecifications DEC 19, 2018 egin : Uning primay not h transition contact. T down high I : NR	y recall invol oduction at a ave been pro resistance a 'he EME mod	Board (PCB) that may not h D19 End: NR ves the Electric Motor Elect sub-supplier, the EME's Pr oduced to specifications. Th t certain PCB contact points	tronics (EME) module. rinted Circuit Board (PCB) nis could lead to an increase in s and cause a loss of electrical		
Production Dates : VIN Range 1 : B Description of Defect : Description of the Defec	contains a Prispecifications DEC 19, 2018 legin : t : This safet During pr may not h transition contact. T down high l : NR 2 : NR c : A shut do propulsio power rei	nted Circuit - MAR 29, 20 NR y recall invol oduction at a ave been pro resistance a 'he EME moo n-voltage elec wn of high-vo n, increasing	Board (PCB) that may not h D19 End: NR ves the Electric Motor Elect sub-supplier, the EME's Pr oduced to specifications. Th t certain PCB contact points lule would detect this condi- ctrical power.	tronics (EME) module. inted Circuit Board (PCB) is could lead to an increase in s and cause a loss of electrical ition and, appropriately, shut and result in a loss of er, the 12-volt electrical		

Supplier Identification :

Component Manufacturer

Name : Zollner Elektronik AG Address : Manfred-Zollner Strasse 1 Zandt FOREIGN STATES Country : Germany

Chronology :

In early July, BMW became aware of several field incidents, from non-US markets, involving high-voltage electrical power loss on Model Year 2019 BMW i3 and i8 vehicles. An initial review of the incidents was conducted, but the nature of the power loss was not clear.

Further reviews were conducted, which also involved the Electric Motor Electronics (EME) supplier and subsupplier. The Tier-1 supplier informed BMW that certain EME modules may not have been produced to specifications. The supplier indicated that the EME's Printed Circuit Board (PCB) may not have been produced to specifications on a specific assembly line by the Tier-2 supplier.

A review of the Tier-2 supplier's production records was able to identify the production dates of potentially affected PCBs.

Vehicle manufacturing and Tier-1/Tier-2 supplier production records were examined in order to determine the number, and production dates, of potentially affected vehicles.

On August 7, 2019, BMW decided to conduct a voluntary recall.

BMW has not received any reports, nor is BMW otherwise aware, of any accidents or injuries related to this issue.

Description of Remedy :

Description of Remedy Program :	The Electric Motor Electronics (EME) will be replaced. Owners will be notified by First Class mail and instructed to take their vehicle to an authorized BMW center to have the remedy performed for free. If this condition were to occur to a potentially affected vehicle prior to the recall, the remedy would be covered by the BMW New Vehicle Limited Warranty program. Therefore, reimbursement for a pre-notification remedy re Part 573.13 and Part 577.11 is not necessary.
How Remedy Component Differs	Electric Motor Electronics (EME) p/n 8488543, 848854, 8488547,
from Recalled Component :	8488548

The information contained in this report was submitted pursuant to 49 CFR §573

Part 573 Safety Recall Report

Identify How/When Recall Condition NR was Corrected in Production :

Recall Schedule :

Description of Recall Schedule :	Notification to dealers is expected to begin and end on August 14, 2019. Notification to owners is expected to begin and end on October, 7, 2019.
Planned Dealer Notification Date :	AUG 14, 2019 - AUG 14, 2019
Planned Owner Notification Date :	OCT 07, 2019 - OCT 07, 2019

* NR - Not Reported

The information contained in this report was submitted pursuant to 49 CFR §573