

DAIMLER VANS USA, LLC One Mercedes-Benz Drive Sandy Springs, GA, 30328 Phone: (770) 705-0600 Fax: (770) 705-0117 MBUSA.com

# newschannel update

то: Mercedes-Benz Dealer Principals, General Managers,	FROM: Anthony Washington, Department
Sales Managers, Service Managers, Parts Managers	Manager, Regulatory Mgmt & Campaigns
RE: <b>Recall Campaign Launch Notification</b> LED Rear Fog Lamps Model Years 2019 Mercedes-Benz (907) Sprinters	DATE: March 25, 2019

### **IMPORTANT CAMPAIGN INFORMATION**

L



Campaign	Campaign Description :				
2019030013	<b>VS3NEBELED</b>	LED Rear Fog Lamps			
This is to notify you of the <b>Recall Campaign</b> concerning the signal acquisition and actuation module on approximately <u>1,202</u> MY19 Sprinter (907) vehicles. The recall campaign will be visible on the <u>www.safercar.gov</u> website and may generate questions from customers. All affected vehicles will be flagged as "Open" in VMI on <b>March 25, 2019</b> .					
Background					
lssue	Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vans, has determined that on certain Mercedes-Benz Sprinter vehicles (platform 907, open model designation) for the NAFTA market, the rear fog lamp in the LED rear lamps may not be activated at all or activated with a delay even though the vehicle's rear fog light switch is in the "on" position and its activation is indicated to the driver in the instrument cluster. In this case, the customer's expectation regarding a safely functioning rear fog lamp might would not be met which could increase the risk of an accident.				
What We're Doing	An authorized dealer will encode the signal acquisition and actuation module on the affected vehicles.				
Parts	No replacement parts ar	e required.			
		Vehicles Affected			
Vehicle Model	Model Year 2019				
Vehicle Model	Platform 907 (Sprinter)				
		Vehicle Populations			
Total Recall Population	Approximately 1,202				
Dealer Inventory	131				
Given this notice, it is	Given this notice, it is <u>a violation of Federal Law</u> for a dealer to sell or lease any <u>new</u> MY19 Sprinter vehicles in dealer inventory covered by this notification until the vehicle has been repaired.				
Loaner and demonstrator vehicles should not be driven, and must not be retailed until repaired. Additionally, given this notice, it is <u>a violation of Federal Law f</u> or <u>rental companies</u> to rent new MY19 Sprinter vehicles covered by this notification until the vehicle has been repaired.					
		Next Steps/Notes			
Customer Notification Timeline Owner		notification letters will be mailed in late April.			
VAOMs/RSMs This recall may generate questions from your dealers. Please forward this notice to dealers ASAP.		recall may generate questions from your dealers. Please forward this notice to your ers ASAP.			
		recall may affect vehicles in your fleet. Please contact your respective DVUSA fleet esentative for further information and next steps. For repairs, please contact your erred DVUSA dealer.			
While we regret any inconvenience this may cause, DVUSA is determined to maintain a high level of vehicle quality and customer satisfaction.					

## **Recall Campaign Bulletin**



Campaign No. 2019030013, March 2019

#### TO: ALL MERCEDES-BENZ CENTERS

Model 907 (Sprinter), Model Years 2019 SUBJECT: LED Rear Fog Lamps

Daimler AG ("DAG"), the manufacturer of Mercedes-Benz vans, has determined that on certain Mercedes-Benz Sprinter vehicles (platform 907, open model designation) for the NAFTA market, the rear fog lamp in the LED rear lamps may not be activated at all or activated with a delay even though the vehicle's rear fog light switch is in the "on" position and its activation is indicated to the driver in the instrument cluster. In this case, the customer's expectation regarding a safely functioning rear fog lamp might would not be met which could increase the risk of an accident. An authorized dealer will encode the signal acquisition and actuation module on the affected vehicles.

Prior to performing this Recall Campaign:

 Please check VMI to determine if the vehicle is involved in the Campaign and if it has been previously repaired.

 Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.

Please note that Recall Campaigns do not expire and may also be performed on a vehicle with a vehicle status indicator.

Approximately 1,202 vehicles are involved.

Order No. V-RC-2019030013 This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

<u>Recall Campaign Bulletin</u>

Recall Campaign Bu

## Warranty Information

## **Operation items and work units**

<b>Operation number</b>	<b>Operation text</b>	Labor Time (hrs.)	Damage Code
02 2443 Operations: Connect/disconnect vehicle diagnosis system		0.1	82 92 251 7
02 2445Operations: Connect/disconnect charger (vehicle diagnosis system connected)0.1		82 922 51 7	
02 2444 Operations: Perform SCN coding in control unit (vehicle diagnosis system connected)		0.1	82 922 51 7

### Procedure

Check				
1	Check, whether the vehicle is affected by the measure	For authorized Mercedes-Benz service partners, only the entry in the "Extended VEGA Application"(EVA) system, in the "Current" tab, is decisive. An additional test of the affected vehicles in the workshop information system (WIS) or vehicle list is thereby not necessary.		
SCN o	coding			
2	Connect diagnostic system.	It is absolutely essential to precisely follow the operation steps as described in the vehicle diagnosis system.		
3	Connect charging equipment. Maintaining on- board electrical system voltage when performing test and diagnosis work on vehicle	During the entire work procedure a sufficiently large voltage supply must be provided for the vehicle's on-board electrical system. Otherwise any undervoltage that occurs may damage the control units. Follow the operating instructions for the charger. Use the charger to ensure that an adequate power supply (min. 12.5 V) is provided for the onboard electrical system battery.		
4	Perform SCN coding in the signal acquisition and actuation module.	See process description in diagnostic system "INFO".		
5	Disconnect diagnostic system.			
6	Remove charger from vehicle.			