



SERVICE BULLETIN

TCE-SB011 | October 2017

THUNDER CREEK EQUIPMENT
ThunderCreek.com

SERVICE CONTACT

Ryan Baarda
1833 Highway 163 | Pella, IA 50219
P: 866.535.7667
F: 641.620.8302
E: ryanb@ldj-products.com

Subject: Fuel Caps and Sight Gauges

Model Numbers – R250 container trailer

Conditions Found:

1. Axles installed incorrectly
2. Brake working improperly

Facts:

1. In the first condition found, the axles could have been installed backwards from the manufacture
2. In the second condition found, because of the axles being installed incorrectly the brakes could fail to operate properly.

Solutions:

1. The first and second condition is resolved by making sure that the axles are installed properly from the factory.

Repair:

To check the proper installment of the axle, look at the brake backing plate, the two slots should be at the bottom of the backing plate with a bolt head at the top of the backing plate and the two brake wires coming out towards the rear of the trailer. Please see attached print to verify.

Warranty: Warranty labor will be paid at 1.5 hours per axle being corrected.

All service reimbursement claims must be emailed to: ryanb@thundercreek.com

All questions regarding this Service Bulletin should be directed to Ryan Baarda at: 866.535.7667 toll-free or 641.620.4037 direct, or email ryanb@thundercreek.com

