

Campaign No. 2020080007, August 2020

Revision B 9-18-2020

TO: ALL MERCEDES-BENZ CENTERS

SUBJECT: Model W204 and C204 Model Years 2012-2015 Replace Front Passenger-side Airbag

Based on the defect decision of TK Holdings, Inc. ("Takata"), in certain front passenger-side airbags produced by Takata used in certain Model Year 2012-2015 Mercedes-Benz vehicles, under specific circumstances, the front passenger-side airbag inflator housing may explode during deployment due to excessive internal pressure. This condition is more likely to occur if the vehicle has been exposed to high levels of absolute humidity for extended periods of time. A passenger side inflator explosion during deployment could result in sharp metal fragments striking the passenger or other occupants, possibly causing serious injury or death. To remedy this concern, an authorized Mercedes-Benz dealer will replace the front passenger-side airbag on the affected vehicles.

Prior to performing this Recall Campaign:

- VMI must always be checked before performing campaigns to verify that the campaign is required on a specific vehicle. Always check for any other open campaigns, and perform accordingly.
- Please review the entire Recall Campaign bulletin and follow the repair procedure exactly as described.
- For more instruction on the SRS light please see attachment A

Approximately 130,417 vehicles are involved.

Order No. P-RC-2020080007

This bulletin has been created and maintained in accordance with MBUSA-SLP S423QH001, Document and Data Control, and MBUSA-SLP S424HH001, Control of Quality Records.

Recall Campaign Bulletin

Recall Campaign Bulletin

WARNING!

There is a risk of injury or death when performing testing or repair work on vehicles and when handling vehicle components. Be sure to read and observe all relevant safety instructions in WIS. This procedure must only be performed by trained personnel using proper tools and equipment.

Note: View the passenger-side airbag replacement videos prior to performing this procedure:

- Location: The Learning Link.
- Course Code:
- X0070E-US.MTA (AKUBIS®: Passenger's Airbag Replacement)
- Video is for reference purposes, be sure to follow work sequence and instructions in this Procedure.

1. Load the *Mercedes-Benz PartScan* App. on Apple[®] iPhone[®] or Android[®] smart phone.

- For Apple[®] iPhone[®] Users: The *MB PartScan* App is designed for generations of iPhone 5s and newer. However, for optimal experience and performance, we advise that an iPhone 6 and newer be used for scanning with the *MB PartScan* App."
- Download app from Apple[®] store for iPhone[®] or Google[®] play for Android[®] (same as any other app download) then scan the QR code below to continue download (follow on-screen instructions).
- To install and transmit the data a WiFi connection is required.
- After downloading the App, a one-time security authentication is required by means of encrypted QR code. Verification can be performed by scanning the QR code below, before using the application.
- Ensure that only authorized personnel access to the QR Code the workshop receives.
- The following e-mail address is provided in the event UHD App support is required for the Mercedes-Benz PartScan App process: <u>Mbdiagnosis@mbusa.com</u>



- The PartScan App must be utilized properly for every Takata airbag recall repair.
- If the VIN is missing, illegible or incomplete, it must be entered manually
- The <u>airbag</u> barcode scan may only be skipped if the barcode is missing, illegible or incomplete.
- Never scan a "dummy" barcode to skip the entry fields See Example below
 - When only the passenger airbag replacement is required scan and only press the passenger airbag "scan old component".
- Always make sure the proper airbag is scanned in the respective entry field in the App (driver airbag for driver-side, passenger airbag for passenger-side)
- Part Scan Examples: Driver-side airbag only and Passenger-side airbag only scans



i Note: Prior to replacing airbag, please check for SRS errors or messages in the instrument cluster:

• If an SRS error message is pending before start of work, it must be documented and accounted for through the details outlined in Attachment A, page 15 Perform the recall repair accordingly.

Work Procedure W/C204

- 1. Disconnect ground line from the on-board electrical system battery.
- 2. Remove right A-pillar trim (A, figure 2).





3. <u>Remove glove box housing</u>

i For basic data of model 204, see **AR68.10-P-1200CW**

i Release inner retaining ring **(figure 3)** at the AUX connection towards the inside. The connection can then be removed from the glove box housing.

i Pull iPod cable *with* rubber grommet out of glove box housing until the connector plug makes contact with the housing. *Do not pull cable out of rubber grommet* because it is bonded to the rubber grommet and will otherwise be damaged!

i Pull out the iPod cable as far as possible and set down glove box housing on the windshield *with* exterior iPod cable connected (figure 4).



Figure 3



Figure 4

4. Remove air duct (B, figure 5) above the glove compartment.



Figure 5

5. Unclip and remove cover (C, figure 6) at the instrument panel on top.

 i With a sound system, also remove speaker under the cover.



Figure 6

- 6. <u>Remove</u> center console (AR68.20-P-2000CW).
- 7. Remove automatic climate control and operating unit. I For basic data of model W204, see AR83.40-P-6350CW
- 8. Remove trim (D, figure 7) around the instrument cluster.

i

For basic data of model W204, see **AR54.30-P-6015CW**.



Figure 7

- 9. <u>Remove the two bottom threaded connections (E, figure 8) of the instrument cluster.</u>
 - i These screws are simultaneously fasteners for the instrument panel.
 - i The upper two screws do not need to be removed.



Figure 8



10. Remove four screws (F, figure 9) for fastening the instrument panel

Figure 9

11. Disconnect electrical contacts (G, figure 10) at the front passenger airbag.



Figure 10

- 12. Remove lock nuts (H, figure 11) for the front the passenger airbag.
 - i

Lock nuts should only be replaced if they are damaged. For more info see:



AH00.00-N-0001-01A / Modification notes 27.10.2016

Figure 11

- 13. Slightly raise instrument panel at the front passenger side and remove the front passenger airbag in a downwards direction. Take special care not to crack the dashboard material. DO NOT REMOVE THE DASHBOARD
- 14. The PartScan App must be utilized properly for every Takata airbag recall repair. Use the "Scan VIN" button (figure 12) to scan the vehicle identification number either by the barcode or the text field.

After scanning, compare the vehicle identification number that has been read in the app and correct any scanning errors manually.

i All required data can also be read off and entered manually.



Figure 12

Figure 13

Figure 14

- 15. Since no driver airbag is replaced under this campaign, skip the driver airbag "Scan old/new component" barcode scan by leaving the field blank. DO NOT scan a "dummy" driver airbag bar code!
- **16.** Scan barcodes of the removed passenger airbag using the button <u>"Sc</u>an old component" (figure 13).

Ensure that the lower barcode (J, figure 14) is scanned.

L	1
	i

This step can be omitted only if bar code is incomplete, illegible, or missing.

i All required data can also be read off and entered manually.

- 17. Scan the barcodes of the new passenger airbag using the button "Scan new component" (figure 13).
 - **i** Ensure that the lower barcode **(J, figure 14)** is scanned.

LI All required data can also be read off and entered manually.

18. Create a scan ID via the "Send" button (figure 15).

i The generated scan ID (figure 16) must be recorded in writing in the workshop order and then stored in a tamper-proof manner.

Delete PartScan O 🛈	Delete PartScan O ①
16986001 ? 1016	16986001
Send following data?	Data sent successfully.
Data belongs to a PC	concalisent successionly.
VIN: WD02H66BXHA264493	ID: 000101
Driver airbag - New component 16986801029116701636680018	
Front passenger airbag - New compone	
20486046020000701636600098	
Scan again Send	ОК
Last sent IC: 000010	Lost sent ID: 00007
Send	Send

i For order invoicing, it is **<u>mandatory</u>** to enter the "ID" in the comment field of the **EVA / VEGA** application.

ID: _____

Figure 15

Figure 16

19. Carefully insert the new front passenger airbag from below and fasten to the instrument panel with 4 nuts.

i Contrary to the work instructions in WIS, it is **not** necessary to check the supplemental restraint system with XENTRY/DAS following front passenger airbag replacement. Step 21 completes this check.

Mm Nut of front passenger airbag at instrument panel 5 Nm.

20. Place instrument panel back into position and install the air ducts (K, figure 17) correctly.

i The air ducts are pulled out when the instrument panel is raised.





- 21. Assemble in reverse order.
- **22.** Connect ground line to on-board electrical system battery.
- 23. Turn the transmitter key in the electronic ignition lock to **position 1** and check whether the airbag indicator lamp (L, figure 18 or 19) correctly switches off after a few seconds.
 - i The SRS check is thus completely ensured after airbag replacement.





Figure 19

Special Tools



i_{Note:}

- Requested parts must be returned in accordance with the warranty parts return requirements section found in the policy and procedures manual.
- Use the attached hazmat shipping document as a guide for shipping airbags.

I Note (regarding WIS documents referenced in this Procedure): Replacement of parts not listed in the parts table of this Procedure are not claimable under this campaign. If replacement of additional part(s) is necessary, check coverage prior to submitting under warranty.

Primary Parts Information

Qty.	Part Name	Part Number
As required	Front passenger airbag Type W204	A 204 860 12 00 05
As required	Front passenger airbag Type C204 Coupe	A 207 860 03 00 05

i Note:

- Please be aware that only the part number(s) referenced in the Campaign Bulletin is/are approved for use to repair the vehicle. Repairs performed using any other part(s) will not have been performed in accordance with the campaign. Accordingly, warranty claims submitted with reference to an improper part number(s) will be denied.
- The following allowable labor operation should be used when submitting a warranty claim for this repair:

Warranty Information

Operation: Replace front passenger airbag (02-1688)

Damage Code	Operation Number	Labor Time (hrs.)
91 931 07 7	02-1688	1.4

(Includes: Disconnecting and connecting ground cable of on-board electrical system battery).

i Note

Operation Number labor times are subject to change.



Attachment A - SRS Light Diagnosis/Repair Process - Takata Airbag Recall Only



- 4. Ensure RO is documented properly
- 5. Attach RO to warranty claim

Claim against new "21" damage code





Hazardous Materials Shipping Instructions - GROUND



Steps to Return an Airbag:

REQUIRED PACKAGING:

- Carefully open received box and remove new . airbag. Keep box intact & save all contents!
- Place used airbag into replacement airbag box, re-using any packaging material (e.g., cardboard inserts) used for the new airbag. Package as the new airbag was packaged.
- Use plastic adhesive tape 50 mm wide to secure the box closed. Do not obscure labels or text on the box with the tape.
- Ensure that the 4G fiberboard box is not ripped or damaged.

REQUIRED LABELS:

A Class 9 Miscellaneous label must be clearly visible on one side of the box.

REQUIRED PACKAGE MARKINGS:

The following words ("marking") must also be clearly visible on the same side of the box as the Class 9 label:

Safety devices UN3268 (font size must be >= 1/2 inch)

- Affix "To/From" address label to same or adjacent packaging face as the hazardous markings/labels.
- The UN 4G code preprinted near the bottom edge of the box must also be clearly visible.

Questions? Contact MBUSA Corporate EH&S at (630) 462-3440 or (770) 705-2578

DOCUMENTATION:

Include a HAZMAT bill of lading (see above example) with the package. For returns via DDS or FedEx Ground, the system will generate the Hazmat bill of lading.

COMMENTS:

- Note: The Packing Group and the EX# are no longer required to be printed on the HAZMAT bill of lading.
- Package example:





The UN 4G code preprinted near the bottom edge of the box must also be clearly visible.

OVERPACKS (more than 1 airbag sent as 1 shipment):

- Package each airbag in a separate UN spec box prepared with the labels/markings described above.
- Place each individual airbag box inside a larger non-UN spec box to keep the shipment together.
- This larger box is called an "OVERPACK."

Questions? Contact MBUSA Corporate EH&S at (630) 462-3440 or (770) 705-2578



12/5/2016