

SIB 65 05 19

2022-02-04

RECALL 19V-015: DRIVER'S FRONT AIR BAG MODULE – PRIOR PARTS REPLACEMENT

This Service Information bulletin (Revision 5) replaces SI B65 05 19 dated October 2019

Whats New:

Parts – air bag module 6877590 has superseded to 5A45C60

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

MODEL

E-Series	Model Description	Production Date	Affected Option Code / Engine
E39	5 Series Sedan	September 2000 thru July 2003	with the Basic steering wheel (SA0710 Retrofitted)
E39	5 Series Sedan	September 2000 thru August 2001	with M Sports steering wheel (SA0710)
E53	X5 Sports Activity Vehicle	April 2000 thru September 2003	with the Basic steering wheel (SA0710 Retrofitted)

AFFECTED VEHICLES

This Recall involves a total vehicle population of approximately 157,549 (69,112 E39, 88,437 E53) vehicles from Model Year 2000 thru 2004. The number of potentially affected vehicles is much smaller and we expect; only around 3% of these vehicles will require parts replacement.

Vehicles in dealer inventory are affected by this Recall. Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System) or with the Key Reader.

Affected vehicles may have had their original steering wheel which was not affected, switched to the sport steering wheel which may include a Takata PSDI-4 inflator. The air bag will be checked on all affected vehicles and replaced if necessary.

SITUATION

BMW AG is conducting a Voluntary Safety Recall on certain E39 BMW 5 Series and E53 SAV vehicles.

This recall campaign **ONLY** involves **sports steering wheel (SA0710)** equipped vehicles with the Takata PSDI-4 inflator.

Some customers may have switched their original steering wheel which was not affected, to the sport steering wheel which may include this Recalled inflator.

To complete this recall we will perform an inspection of the installed air bag.

Only those 3% of the vehicles under this recall will need to receive a replacement air bag. The other 97% will only have an inspection performed.

All customers affected by this Recall will be sent repair letters to inform them that their vehicle is affected. To assist you with customer concerns, please reference the attached Q&A that will be updated as information becomes available.


CAUSE

Due to a supplier production error, certain air bags from supplier Takata may not have been produced to specifications.

CORRECTION

Check the driver's air bag and if necessary, replace it.


PROCEDURE



Basic Steering Wheel Equipped Vehicles (with or without MFL button controls)

This steering wheel's air bag is **NOT** affected, air bag removal for inspection is **NOT** necessary

Submit a claim for checking only.



Optional Sports Steering Wheel Equipped Vehicles (with or without MFL button controls)

This steering wheel's air bag **MAYBE** affected, remove, inspect and replace the air bag as necessary.

Submit a claim for the inspection or the inspection/replacement repair that applies.

Vehicles equipped with Optional Sports Steering Wheel only

- 1. Remove the driver's air bag in accordance with repair instructions **REP 32 34 020** "Removing and installing/replacing air bag units".
- 2. Check the label on the back of the driver's air bag.

Is the label yellow with a white number sticker with printed serial number BAM XXX - 1085 (as shown) printed below the bar code?



YES- replace air bag following attached procedure.



NO - the driver's air bag is not affected.

Air bags from other manufacturers (non-Takata, Autoliv), or Takata air bags with different chemical compositions (white label) are not affected by this recall and **DO NOT** need to be replaced.

Reinstall the driver's air bag.





Before installing the replacement part, the new air bag module's serial number (circled) must be documented by the technician on the repair order so it can also be entered into the warranty claim's comment section.

PARTS INFORMATION

Note: Only request and invoice the applicable part number specified and listed in this Service Information bulletin.

Performing a part number look-up in ETK by VIN or model will result with the wrong part(s) being invoiced and installed.

Part Number	Description	Quantity
32 30 6 877 590; Or 32 30 5 A45 C60	Hub Cap (Impact plate) Air bag M sports steering wheel (SA0710)	1

PARTS RETENTION AND RETURN

The parts replaced to perform and submit for this Recall repair procedure are the property of BMW NA.

Your center is responsible for the proper identification, storage and documentation of these parts. They must be held in a secure retention area until notification of claim payment is made by BMW NA through DCSnet.

Upon claim payment, a DCSnet part return tag will be generated for the driver's front air bag module with special handling instructions.

 Please DO NOT return these recalled air bag modules directly to Lightning Resources or the WPRC. Inflatable air bags are classified as dangerous goods by the Department of Transportation (DOT) and require special preparation, packing and labeling for transport.

Your center is responsible for following all rules and regulations that apply to shipping dangerous goods as described in the attachment.

A shipping procedure has been created for returning the replaced air bag modules directly to Takata. There is also a procedure available for "Bulk Shipping 15 or more air bag modules" at one time to Takata. These procedures are contained in the "Part Return Program Instructions" and "Bulk Ship" PDF attachments to this bulletin; please read both of them. Effective immediately, please use the following email address when scheduling bulk shipment returns to Takata:

Scfieldaction.14305@xpo.com

The parts are to be packaged in the same packaging that the new part arrived in for shipment back to Takata.

The returns pickup schedule has been changed from weekly to every two weeks (bi-weekly)

Parts returned to warranty for this recall that are not manufactured by 'Takata', and don't have the **YELLOW label** as noted above will be debited. **WHITE label** Takata gas generators contain a different chemical composition and are NOT part of this recall

WARRANTY INFORMATION

Note: The new air bag module's serial number (item B) must be documented on the repair order and in the warranty claim's comment section.

Reimbursement for this Recall will be via normal claim entry utilizing the following information:

Defect Code:	0032790200	E39 E53 Check drivers airbag, replace if
Belect Gode.	0032730200	necessary

A. Checking the "Sports" Steering Wheel Air Bag Label or Visually Confirming (without removal) the Vehicle is Equipped with the Basic Steering Wheel/Air Bag Assembly

Labor Operation:	Labor Allowance:	Description:
00 67 184	5 FRU	Checking the driver-side front air bag (No repair is necessary) (Main work)
Or:		
00 67 753	3 FRU	Checking the driver-side front air bag (No repair is necessary) (Plus work)

Or:

B. Checking the "Sports" Steering Wheel Label and Replacing the Air Bag

Labor Operation:	Labor Allowance:	Description:
00 67 185	5 FRU	Check and replace the driver-side front air bag (Main work)
Or:		

·	-	
00 67 754	3 FRU	Check and replace the driver-side front air bag (Plus
		work)

Only one of the listed flat rate unit numbers may be quoted for reimbursement purposes.

Mobile Assistance - Off Site Repair

2/8/22, 10:58 AM

For centers that qualify, this Recall repair is eligible to be performed and submitted as a Mobile Assistance Off-Site Repair which includes an additional labor allowance.

Qualifying BMW centers are those that currently own and operate a Mobile Assistance Program vehicle. Other centers that may qualify are those have officially registered their interest in conducting mobile service and mobile assistance work for the BMW Roadside Assistance Program.

If you have not already registered, please send an email with contact information to roadside.assistance@bmwna.com.

Claim - Labor Reimbursement (Reimbursement Percentage Increased)

When a vehicle is eligible for this Recall repair and it is performed under this program, qualifying centers will be reimbursed for the corresponding labor operation's published AIR flat rate unit (FRU) allowance at a rate of 200 percent. This mobile assistance repair work is subject to the same policy and procedures that apply to the warranty repair work being performed in your workshop.

Time Control and Documentation

While repair-specific punch times are not necessary for this repair work being performed on a vehicle off-site (outside your center), the on-call technician must still punch on the corresponding repair order (electronic or manual) prior to leaving your BMW center when he or she is dispatched. The technician must punch off the repair order upon their return to your center.

In cases where the technician is out on the road for an extended period of time (for example, on multiple calls), only one on/off punch time is required.

Claim Submission

In addition to the Takata Air Bag Recall repair order line item, please open an additional line item as describe below:

Defect Code:	85820269TK	Takata Recall - Mobile Assistance Off-Site	e Repair
Labor Operation	Description		Labor Allowance
32 99 000	Additional labor allowance to perform "off-site" repair through Mobile Assistance		# FRU*

Claim the applicable labor operation's stated FRU allowance in full a second time using the defect code and labor operation provided above.

Notes:

- Identify this line time as "Additional labor for a Mobile Assistance off-site repair."
- Itemize the additional labor claimed and explain the repair performed on the repair order and in claim comment section.
- Labor operation code 32 99 000 is not considered a Main labor operation.

Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

With this Technical Campaign, a prior repair reimbursement is not likely. Typically, a customer would have their driver's front air bag module replaced as a result of an accident. In such a case, either an insurance company or the customer themselves, paid for the replacement of the above mentioned air bag module in conjunction with the accident repairs. Such cases are not covered by this campaign and are not entitled to reimbursement.

QUESTIONS REGARDING THIS BULLETIN

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Please contact the Warranty department by either using the Live Chat that's available in the Warranty Documentation Portal or through IDS by selecting Coverage, Policy, Coding Questions and Mileage Corrections
Parts inquiries	Submit an IDS ticket to the Parts Department

Supporting Materials

picture as pdf B650519 Parts Bulk Ship Return.pdf

picture as pdf B650519 Recall Notice.pdf

picture as pdf B650519 19V-015 E53 E39 DAB QA 14Jan2019 final.pdf

picture as pdf B650519 Parts Return Program Instructions.pdf

SAFETY RECALL NOTICE

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 19V-015: Driver's Front Air Bag Module – Prior Parts Replacement (B65 05 19)

BMW of North America, LLC is conducting a Voluntary Safety Recall (effective January 14, 2019) on certain BMW 5 Series and X5 SAV vehicles that were produced from April 2, 2000 through September 30, 2003.

Owners will be notified by First Class mail about the Recall and will be instructed to bring their vehicles in for a free repair when parts are available.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Last updated: 2/1/2019

Q1. Which models are included in this Safety Recall Campaign?

Included are approximately 170,148 vehicles, with approximate volumes and production dates as noted below.

<u>Series</u>	<u>Model</u>	<u>Model Year</u>	Approx. Volume	Production Dates
E39 E53	5 Series X5 SAV	2000 – 2003 2000 – 2004	81,713 88,435	Sept 2000 – July 2003 April 2000 – September 2003

Q2. Which inflator is affected?

This recall campaign involves a sport steering wheel equipped with the Takata PSDI-4 inflator. Some customers may have switched their original steering wheel which was not affected, to the sport steering wheel which may include this inflator.

Q3. What is the fix?

The driver's front air bag module will be checked and if a Takata PSDI-4 inflator is found, it will be replaced.

Q4. How long will the repair take?

The repair is <u>FREE</u>. Checking the air bag takes about 30 minutes; if the driver's front air bag module needs to be replaced, it could take approximately one hour. Additional time may be required depending upon your BMW center's schedule.

Q5. How will I be notified of this recall?

You will receive a <u>letter by the beginning of March</u> via First Class mail, advising you of this recall. To ensure BMW of North America, LLC has your most recent contact and vehicle information, please register your vehicle at http://www.bmwusa.com/myBMW. Registration is free, and will give you access to factory initiated campaigns and other information specific to your BMW vehicle.

Q6. Do I have to wait for my letter in order to have my vehicle serviced?

No. You should schedule an appointment <u>immediately</u> with an authorized BMW center for service and repair. You can locate your nearest BMW center at <u>www.bmwusa.com/dealer</u>.

Last updated: 2/1/2019

Q7. What options are available if it is too inconvenient for me to bring my vehicle to a BMW center for service? There are a few options to help overcome the inconvenience of bringing your vehicle in for service like mobile repair, alternate transportation, pickup/drop-off, dealer events and towing. Contact your local BMW center to check what is available.

General Takata Questions

Q1. What is the specific concern?

Takata's investigation to date indicates that exposure to certain environmental conditions (several years of exposure to persistent conditions of high absolute humidity) could lead to overly aggressive combustion in the event of air bag deployment.

Q2. What is desiccant?

Put simply, desiccant is a substance with properties that enable it to soak up water vapor from the air surrounding it.

Q3. Why are other BMW models not included?

Other vehicles have frontal air bags that were produced with different inflators.

Q4. What can happen as a result of this issue?

In a crash where the air bag deploys, the air bag inflator housing may rupture and could cause metal fragments to pass through the air bag cushion material, which may result in injury or death to vehicle occupants.

Q5. Is it possible to find out whether the problem exists in my car?

No. There is no way to detect if your BMW might have an air bag inflator potentially at risk of rupturing upon deployment in an accident.

Q6. How did BMW become aware of this issue?

BMW became aware of this issue through its quality control procedures.

Q7. Can I continue to drive my vehicle?

Yes. However, please contact any authorized BMW center immediately to schedule an appointment to have this important **free repair** performed as soon as possible. If you are not the only driver of this vehicle, please advise all other drivers of this important information.

Last updated: 2/1/2019

Q8. I did not receive a letter from BMW regarding my vehicle. How can I find out if my BMW is included in this recall?

You can check for open recalls a few different ways. You can check for open recalls by entering your vehicle identification number (VIN) at www.bmwusa.com/recall and download a sample owner notification letter and Q&A if your VIN is affected. You can also call or visit your local BMW center's service department to determine if your BMW is affected. Make sure to update your contact information by registering at https://www.bmwusa.com/myBMW.

Q9. What if I am not the current owner of this vehicle?

You can update your vehicle ownership information by registering at http://www.bmwusa.com/myBMW.

Q10. Which states are considered to be high absolute humidity areas?

Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, Texas, Puerto Rico, American Samoa, Guam, Saipan, South Carolina and U.S. Virgin Islands.

Q11. Am I eligible for reimbursement under the TREAD Act if I previously replaced my driver's front air bag module?

In this particular recall, reimbursement is likely not applicable, as you would typically have replaced your frontal air bag module as a result of an accident. In that situation, most likely your insurance company paid for the repair. However, in the very unusual (unlikely) scenario that you previously paid to replace the front air bag module "out-of-pocket" upon learning of this possible defect, you may be eligible for reimbursement. Additional information is provided when BMW mails the letter asking you to make an appointment with an authorized BMW center.

Q12. I'm not the first owner of this vehicle and am concerned it may have been kept in a high humidity state. What can you tell me?

Any vehicle that was ever registered in hot and humid area as defined by NHTSA is given priority on the list of customers being notified about this recall.

Q13. Which states are considered to be high absolute humidity areas?

Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, Saipan, and U.S. Virgin Islands.

Q14. What determines the prioritized locations that are associated with the most at-risk vehicles – and what is the average propellant degradation time in each?

Per the NHTSA, geographic zones have been established based on the temperature fluctuations and humidity and the exposure time required under those environmental conditions to degrade the propellant to the point where it poses an unreasonable risk to safety. High Absolute Humidity ("HAH") definitions are as follows:

"HAH" or "A"	Time until unsafe propellant degradation is projected between 6-9 years.
--------------	--

Last updated: 2/1/2019

"Non-HAH" or "Non-A" Covers vehicles that have not been identified by the vehicle manufacturer as have originally sold or ever registered in the HAH region. This includes Zones B and	
"B"	Time until unsafe propellant degradation is projected between 10-15 years.
"C"	Time until unsafe propellant degradation is projected between 15-20 years.



SI B65 05 19: Recall Campaign: Driver's Air Bag Module

October 2019

BMW / MINI BULK SHIPMENT PACKAGE REFERENCE GUIDE

NOTE: The information outlined in this document pertains to dealers within the Contiguous 48 States.

Dealers in Puerto Rico, the Hawaiian Islands, and Alaska **CANNOT** follow the shipping instructions outlined in this document; they **MUST** contact the following Takata USA representative(s) directly, **once every 2 weeks**, for shipping instructions:

- Dealers in Puerto Rico, please contact: <u>Juan.Armstrong@craneww.com</u>
- Dealers in the Hawaiian Islands, please contact: Becky.Argyropoulos@craneww.com
 - Please make sure to include the required completed Hawaiian Hazardous Materials Shipping Certificate.
- Dealers in Alaska, please contact: SCTakataRestraints_International@xpo.com
 - Important: please be aware that there is an underscore (_) in the above Alaska email address, between the words "Restraints" and "International".
 - Or call the Alaskan Representative; Armando Gonzales at 210-250-5039.

1. Contact Takata:

 Dealers must contact Takata/XPO once every 2 weeks to schedule BULK and SINGLE recall airbag component shipments.

o Email: SCFieldAction.14305@xpo.com

Phone: 210-250-5079

- Takata/XPO will select the return type (bulk or single) based on the shipping quantities (LTL or FedEx PRP), and will supply the dealer with the proper shipping documentation.
 - o If Takata instructs you to return the recall airbag components as a **BULK SHIPMENT**, please follow the instructions outlined below.
 - o If Takata instructs you to return the recall airbag components as a SINGLE SHIPMENT, please follow the

2. Stacking:

Place the recall airbag components neatly on a pallet, and securely shrink-wrap them to the pallet.

Note: The total height of the pallet and boxes cannot exceed 60 inches.



3. Labeling:

Securely attach the following labels on each side of the shrink-wrapped pallet.

- o Class 9 Label
- UN3268 Safety Device *
- OVERPACK USED *

*You can print these labels on letter size white paper, using Microsoft Word.



4. Questions/Concerns:

For any other questions or concerns, please contact the WPRC: <u>AirbagReturns@bmwna.com</u>

SI B65 05 19 - Recall Campaign : Driver's Air Bag Module

October 2019

Defect Code: 00 32 79 02 00

Safety Device Return Procedure for Airbag Recall

ATTENTION

DO NOT USE THE "1.4 LABEL" **AND DO NOT** FOLLOW ANY INSTRUCTIONS FOUND INSIDE THE REPLACEMENT AIRBAG MODULE'S BOX.

DISREGARD THOSE INSTRUCTIONS AND DO NOT RELABEL THE ORIGINAL BOX THAT WILL NOW BE USED FOR RETURNING THE RECALLED AIRBAG.

IMPORTANT

- As the shipper, your center is responsible for proper packaging and documentation completion.
- The person packaging the airbag(s) must have received the Hazardous Material training per 49CFR 172.702. Those training records must be on file at your center.
- The U.S. Department of Transportation ("DOT") will impose substantial fines and/or penalties on the shipper if the packaging, labeling, or documentation is not properly prepared and the customer's (center) copy of the OP 900PRP form is not kept on file for a minimum of two (2) years.

CAMPAIGN DOF – CONTIGUOUS 48 STATE FEDEX GROUND SHIPMENT PREPARATION

As the shipper, you are responsible for proper packing and document completion. The person packaging the module must have received hazardous material training per 49CFR 172.702, and the training records must be on file at your dealership. The U.S. Department of Transportation will impose substantial fines and/or penalties on the shipper if the packaging, labeling, or documentation is not properly prepared and Customer Copy of OP 900PRP form is not kept on file for a minimum of 2 years.

IMPORTANT: Do not deploy the safety device. The person packing the used safety device must read and follow the provided instructions.

Dealers must contact Takata/XPO once every 2 weeks to schedule BULK and SINGLE recall airbag
component shipments. Takata/XPO will select the return type (bulk or single) based on the shipping
quantities (LTL or FedEx PRP), and will supply the dealer with the proper shipping documentation.

Email: <u>scfieldaction.14305@xpo.com</u>

Phone: 210-250-5079

NOTE: Dealers in Puerto Rico, the Hawaiian Islands, and Alaska **CANNOT** follow the shipping instructions outlined in this document; they **MUST** contact the following Takata USA representative(s) directly, **once every 2 weeks**, for shipping instructions:

- Dealers in Puerto Rico, please contact: <u>Juan.Armstrong@craneww.com</u>
- Dealers in the Hawaiian Islands, please contact: <u>Becky.Argyropoulos@craneww.com</u>
 - Please make sure to include the required completed Hawaiian Hazardous Materials Shipping Certificate.
- Dealers in Alaska, please contact: SCTakataRestraints_International@xpo.com
 - Important: please be aware that there is an underscore (_) in the above Alaska email address, between the words "Restraints" and "International".
 - Or call the Alaskan Representative; Armando Gonzales at 210-250-5039

For any other questions or concerns, please contact the WPRC: AirbagReturns@bmwna.com