

- ATTENTION:**
- GENERAL MANAGER
 - PARTS MANAGER
 - CLAIMS PERSONNEL
 - SERVICE MANAGER

IMPORTANT - All Service Personnel Should Read and Initial in the boxes provided, right.

© 2019 Subaru of America, Inc. All rights reserved.



QUALITY DRIVEN® SERVICE

PRODUCT CAMPAIGN BULLETIN

APPLICABILITY: 2019MY Legacy and Outback
SUBJECT: Front Duct Panel Spot Weld

NUMBER: WUH-93R
DATE: 06/26/19
NHTSA: 19V493
REVISED: 07/17/19

Subaru of America, Inc. (Subaru) is recalling certain 2019 model year Legacy and Outback vehicles, due to a potential spot weld issue on the duct located below the cowl panel. A total of 2,107 U.S. vehicles will be affected by this recall, 81 of which are retailed units.

AFFECTED VEHICLES

Model Year	Carline	Production Date Range	Vehicle count
2019	Legacy	May 31, 2019 – June 5, 2019	142
2019	Outback	May 31, 2019 – June 6, 2019	1,965

Not all vehicles in the production ranges listed above are affected by this recall. Coverage must be confirmed by using the Vehicle Coverage Inquiry function on subarunet.com. This information is now available.

REASON FOR THIS RECALL

Potentially affected vehicles may have a long-term reduction in body strength. In the event of a crash, vehicle structure may not perform as designed, increasing the risk of injury.

DESCRIPTION OF THE REMEDY

All potentially affected vehicles will be inspected to determine if this condition exists. If the condition exists, Subaru will replace that vehicle with a comparable new one.

VEHICLE INSPECTION – IN-STOCK VEHICLES

Retailers will perform a preliminary inspection, as described in the “Part A” inspection procedure listed in this bulletin. Vehicles which fail the “Part A” inspection will require further inspection by a Subaru Field Service Engineer (FSE). If the FSE determines that the spot welds were not properly applied during production, Subaru will arrange shipment of that vehicle back to Subaru’s manufacturing facility. Subaru will then arrange to have any such vehicle replaced with a new comparable one.

<p>CAUTION: VEHICLE SERVICING PERFORMED BY UNTRAINED PERSONS COULD RESULT IN SERIOUS INJURY TO THOSE PERSONS OR TO OTHERS.</p> <p>Subaru Service Bulletins are intended for use by professional technicians ONLY. They are written to inform those technicians of conditions that may occur in some vehicles, or to provide information that could assist in the proper servicing of the vehicle. Properly trained technicians have the equipment, tools, safety instructions, and know-how to do the job correctly and safely. If a condition is described, DO NOT assume that this Service Bulletin applies to your vehicle, or that your vehicle will have that condition.</p>	<p style="text-align: center;">Subaru of America, Inc. is ISO 14001 Compliant</p> <p>ISO 14001 is the international standard for excellence in Environmental Management Systems. Please recycle or dispose of automotive products in a manner that is friendly to our environment and in accordance with all local, state and federal laws and regulations.</p>
--	--

Continued...

VEHICLE INSPECTION – RETAILED VEHICLES

Owners will be advised to contact an authorized Subaru retailer of their choice to schedule an appointment to have their vehicle inspected by a Subaru manufacturer's representative (FSE). Owners will also be advised that the retailer will provide a free loaner vehicle until that inspection is performed.

If the FSE determines that the spot welds were not properly applied during production, Subaru will replace the owner's vehicle with a comparable new one at no cost to the owner. The FSE will contact a CRS Senior Representative to handle this as a repurchase transaction. Subaru will also be responsible for paying any taxes, registration, or any other fees that may result from this vehicle exchange.

OWNER NOTIFICATION

Subaru will notify affected vehicle owners by first class mail later this month. Owners with a valid email address on file with Subaru will also be notified by email. Retailers will be advised when that notification begins.

Retailer Responsibility

Any vehicles listed in any recall/campaign that are in retailer stock must be:

- Immediately identified.
- Tagged or otherwise marked to prevent their delivery or use prior to repair.
- Repaired in accordance with the repair procedures outlined in the Product Campaign Bulletin

Retailers are to promptly follow the applicable service procedures, to correct all affected vehicles in their inventory (used, demo & SSLP). Additionally, whenever a vehicle subject to this recall is taken into retailer inventory necessary steps should be taken to ensure the recall correction has been made before selling or releasing the vehicle.

Retailers are to provide the owner with a free loaner or rental vehicle until that inspection can be performed.

INTRODUCTION:

This cowl duct component inspection procedure consists of two parts, **Part A** and **Part B**.

RETAILER RESPONSIBILITIES:

- Review this procedure thoroughly before proceeding.
- Retailers are to perform **ONLY** the **Part A** inspection procedure outlined below on all affected vehicles. The purpose of the **Part A** inspection is to identify those vehicles needing the **Part B** inspection and possible further repair action. The **Part B** inspection is NOT the Retailer's responsibility.
- A completed QMR must be submitted **IMMEDIATELY** after completing the **Part A** inspection procedure for **EVERY** affected vehicle (pass or fail) with the required photos attached.

NOTE: The **Part B** inspection is not necessary on vehicles that pass the **Part A** inspection procedure.

Continued...

SERVICE PROCEDURE:

PART A: Cowl Duct Part Type Determination


1. Open Driver's door.
2. Release the hood and close the driver's door.
3. Open the hood and prop it open securely.
4. Remove both front wiper arms.

Wiper Arm Removal

- 1) Remove the cover - windshield wiper arm.
- 2) Remove the nuts, and remove the arm assembly - windshield wiper.

NOTE:

Since the arm assembly - windshield wiper LH and RH can interfere with each other, remove the driver's side first.




5. **CAREFULLY** remove the plastic cowl trim panels.

Cowl Trim Panel Removal

- 1) Remove the arm assembly - windshield wiper. Ref. to WIPER AND WASHER SYSTEMS>Front Wiper Arm>REMOVAL.
- 2) Remove the cover - front fender UPR.
 - (1) Remove the clip.
 - (2) Release the claws by pulling them forward, and remove the cover - front fender UPR.

CAUTION:

Forcibly removing the part may cause creases.




Continued...

- 3) Remove the cowl panel - side.
 - (1) Remove the clips.
 - (2) Release the claws, and then remove the cowl panel - side.

CAUTION:

Pulling with excessive force may damage the cowl panel - side. If it is difficult to remove, use a plastic remover or equivalent tool.




EI-04636

- 4) Remove the cowl panel assembly.

CAUTION:

- Before removing the cowl panel, use an air blower and nylon brush to sweep gravel from the lower area of the front side of the glass.
- When removing the clip (b), push the claws of the clip first.


- (1) Be careful not to apply excessive force when pulling the clip (b), as the clip may become damaged.
- (2) Remove the clips (a).
- (3) Check the direction of the clip (b), and push the claws from both sides to remove it.
- (4) Remove the cowl panel assembly by pulling it out towards the front of the vehicle.
- (5) Disconnect the washer hose.
 - Models without EyeSight



EI-10938



Continued...

- Models with EyeSight



EI-11574

6. With the cowl trim panel removed, use the photos below to determine if the vehicle is equipped with an **A Jig** or **B Jig** part. The **B Jig** part has an identification weld to distinguish it from the **A Jig** part.



Continued...

CLAIM REIMBURSEMENT AND ENTRY PROCEDURES:


REMINDER: A completed QMR must be received and reviewed by the SOA Claims Team **BEFORE** a claim can be submitted for this inspection. This bulletin will be revised with additional details as they become available.

IMPORTANT REMINDERS:

- SOA strongly discourages the printing and/or local storage of service information as previously released information and electronic publications may be updated at any time.
- Always check for any open recalls or campaigns anytime a vehicle is in for servicing.
- Always refer to STIS for the latest service information before performing any repairs.

Continued...

APPENDIX A: Examples of NG (“B” Jig) and OK (“A” Jig) Duct Panel Weld Inspections



NOTE: In this particular case, the weld is very difficult to see, especially in the supplied photo. Keep in mind, the vehicle's color can make the weld difficult to identify and photograph for making the OK / NG determination.

Continued...

