



RECALL CAMPAIGN BULLETIN

Classification: EL19-019	Reference: NTB19-053	Date: June 26, 2019
-----------------------------	-------------------------	------------------------

VOLUNTARY SAFETY RECALL CAMPAIGN 2017-2019 TITAN; GENERATOR HARNESS

CAMPAIGN ID #: PC673
APPLIED VEHICLES: 2017-2019 Titan (A61)
APPLIED ENGINE: Gasoline V8 (VK56VD)

**Check Service COMM or Dealer Business Systems (DBS)
National Service History to confirm campaign eligibility.**

INTRODUCTION

Nissan is conducting this voluntary safety recall campaign on certain specific model year 2017-2019 Titan vehicles to inspect and, if necessary, replace the generator harness (Engine No. 2 Harness). This service will be performed at no charge to the customer for parts or labor.

IDENTIFICATION NUMBER

Nissan has assigned identification number PC673 to this campaign. This number must appear on all communication and documentation of any nature dealing with this campaign.

DEALER RESPONSIBILITY

It is the dealer's responsibility to check Service COMM or Dealer Business Systems (DBS) National Service History for the campaign status on each vehicle falling within the range of this voluntary safety recall which for any reason enters the service department. This includes vehicles purchased from private parties or presented by transient (tourist) owners and vehicles in a dealer's inventory. **Federal law requires that new vehicles in dealer inventory which are the subject of a safety recall must be corrected prior to sale. Failure to do so can result in civil penalties by the National Highway Traffic Safety Administration.** While federal law applies only to new vehicles, Nissan strongly encourages dealers to correct any used vehicles in their inventory before they are retailed.

Nissan Bulletins are intended for use by qualified technicians, not 'do-it-yourselfers'. Qualified technicians are properly trained individuals who have the equipment, tools, safety instruction, and know-how to do a job properly and safely. NOTE: If you believe that a described condition may apply to a particular vehicle, DO NOT assume that it does. See your Nissan dealer to determine if this applies to your vehicle.

SERVICE PROCEDURE

1. Open the hood.
2. Look down into the area referenced in Figure 1.
 - The generator harness is located between the yellow engine oil dipstick and the power steering pump.



Figure 1

3. Locate the generator harness.
4. Visually inspect the generator harness routing (Figure 2 shows a properly routed generator harness).

NOTE: The generator harness is highlighted with yellow dashes.




Figure 2

- Follow the length of the generator harness and ensure the harness is not trapped, pinched, or cut (Figure 3 and Figure 4 show an improperly routed generator harness).




Figure 3




Figure 4

- The two (2) generator harness retaining clip clamps should be fully locked around the generator harness.




Figure 5

- The two (2) generator harness retaining clips should be fully locked into the generator harness brackets.
- Ensure the generator harness brackets are not bent which could allow the generator harness to rub on the control arm bolt.




Figure 6

- If the generator harness **IS NOT** routed correctly, go to step 5.
 - If the generator harness **IS** routed correctly, go to step 6.
5. Closely inspect the generator harness in the area where it is misrouted.
 - If there is **NO VISIBLE DAMAGE** of any kind to any of the wires within the generator harness, properly route and secure the harness, and ensure the generator harness outer covering is sufficient. Continue to step 6.
 - If there is **VISIBLE DAMAGE** to any of the individual wires within the generator harness, replace the generator harness shown in Figure 7 and highlighted in yellow. Skip to step 7.
 6. Close the hood, and submit a warranty claim using OP Code PC6730 (See **CLAIMS INFORMATION** on the last page).
 7. Close the hood and submit a warranty claim using OP Code PC6731 (See **CLAIMS INFORMATION** on the last page).




Figure 7

PARTS INFORMATION

DESCRIPTION	PART NUMBER	QUANTITY
HARNESS ASSY-ENGINE (generator harness)	(1)	1

(1) Use the VIN of the applied vehicle and reference the Electronic Parts Catalog (EPC).

CLAIMS INFORMATION

Submit a "CM" line claim using the following claims coding:

CAMPAIGN ("CM") ID	DESCRIPTION	OP CODE	FRT
PC673	Inspect Generator Harness	PC6730	0.2 hrs
	Inspect And Replace Generator Harness	PC6731	1.6 hrs

AMENDMENT HISTORY

PUBLISHED DATE	REFERENCE	DESCRIPTION
June 26, 2019	NTB19-053	Original bulletin published