



July 2019

Dealer Service Instructions for:

Safety Recall V76 / NHTSA 19V-498 Fuel Injector Lines

Remedy Available

- 2019 (DJ) RAM 2500 Pickup
- 2019 (D2) RAM 3500 Pickup
- 2019 (DD) RAM 3500 Cab Chassis

2019 (DP) RAM 4500/5500 Cab Chassis

NOTE: This recall applies only to the above trucks equipped with a 6.7L Cummins diesel engine (Sales Code ETL or ETN or ETM).

NOTE: Some vehicles above may have been identified as not involved in this recall and therefore have been excluded from this recall.

IMPORTANT: Some of the involved vehicles may be in dealer new vehicle inventory. Federal law requires you to complete this recall service on these vehicles before retail delivery. Dealers should also consider this requirement to apply to used vehicle inventory and should perform this recall on vehicles in for service. Involved vehicles can be determined by using the VIP inquiry process.

Subject

The diesel engine on about 560 of the above vehicles may have been manufactured with fuel lines with incorrectly formed end fittings that may not properly seal to other fuel system components. Fuel lines that do not properly seal may lead to a fuel leak in the engine compartment. A fuel leak in the engine compartment may lead to a vehicle fire, which may increase risk of injury to occupants and persons outside the vehicle, as well as property damage.

Repair

Cummins will send a representative to inspect the fuel line date codes. If any of the fuel line date codes are found to be within the suspect build population, the suspect line(s) will be replaced.

Alternate Transportation

Dealers should attempt to minimize customer inconvenience by placing the owner in a loaner vehicle if inspection determines that fuel tube replacement is required and the vehicle must be held overnight.

Parts Information

<u>Do NOT</u> place an order, parts will be manually allocated by MOPAR.

Parts Return

No parts return required for this campaign.

Special Tools

The following special tools are required to perform this repair:

- ▹ NPN wiTECH micro pod II
- NPN Laptop Computer
- ➢ NPN wiTECH Software

Service Procedure

<u>Do NOT perform any of these service procedures without prior</u> <u>authorization</u>. A Cummins representative will be dispatched to your dealership to inspect the fuel tube date codes. If any of the fuel tube date codes are found to be within the suspect build population, the Cummins representative will identify which suspect tubes(s) must be replaced. <u>Replacement of any fuel tube without prior authorization will result in</u> <u>forfeit of warranty reimbursement</u>.

A. Tube Removal Preparation Procedures

CAUTION: Cleanliness cannot be over emphasized when handling or replacing diesel fuel system components. This especially includes the fuel injectors, high-pressure fuel tubes and fuel injection pump. Very tight tolerances are used with these parts. Dirt contamination could cause rapid part wear and possible plugging of fuel injector nozzle tip holes. This in turn could lead to possible engine misfire. Always wash/clean any fuel system component thoroughly before disassembly and then air dry. Cap or cover any open part after disassembly. Before assembly, examine each part for dirt, grease or other contaminants and clean if necessary.

1. Disconnect the Intelligent Battery Sensor (IBS) wire harness connector (1) (Figure 1).

NOTE: Failure to disconnect the IBS wire harness connector can lead to damage of the IBS wire harness connector.

2. Loosen the ground terminal nut (2) and remove the negative battery cable with IBS from the battery and isolate it (Figure 1).



Figure 1 – Primary Battery

NOTE: If the vehicle is equipped with an auxiliary battery, when disconnecting and isolating the negative battery cable for the 12volt system, both batteries will need to be disconnected to power down the vehicle.

If the vehicle is equipped with an auxiliary battery, Loosen the clamp (1) and remove the clamp from the battery and isolate (Figure 2).



Figure 2 – Auxiliary Battery

4. Remove the oil dip stick (3) (Figure 3).

5. Remove the bolts (1) and the engine cover (2) (Figure 3).



Figure 3 – Engine Cover

6. Cut the cable tie and position aside the bulk head connector (Figure 4).



Figure 4 – Bulk Head Connector

- 7. Replace only the fuel tubes identified by the Cummins representative which require replacement. Follow the appropriate service procedure depending on which tube(s) must be replaced:
 - Section B. Tube Replacement Fuel Injection Pump to Fuel Rail
 - Section C. Tube Replacement Fuel Rail to Fuel Injector

B. Tube Replacement - Fuel Injection Pump to Fuel Rail

NOTE: The short upper pump to fuel rail tube may be removed separately without disconnecting the long lower pump to fuel rail tube. However, the long lower pump to fuel rail tube also requires removal of the short upper pump to fuel rail tube.

- 1. Remove the nut (1) securing the high pressure pump to rail tubes (16 and 17) (Figure 5).
- 2. Only if removing the long lower pump to fuel rail tube: Remove the bolt (7) securing the high pressure pump to rail tube (17) (Figure 5).



Figure 5 – Fuel Tubes

3. Place a clean shop towels around fuel tubes being disconnected. If possible, do not allow fuel to drip down side of engine.

NOTE: If only replacing the short upper pump to fuel rail tube, it is not necessary to loosen the long lower pump to fuel rail tube. If replacing the long lower pump to fuel rail tube, both short upper and long lower pump to fuel rail tubes must be removed.

4. Loosen the union nuts and carefully remove the fuel tube(s) (16 and 17) from the engine. Note position of tube(s) while removing (Figure 5).

NOTE: Use care not to bend fuel tubes when removing or installing.

- 5. Carefully install the fuel tube(s) (16 and 17) to the engine. Tighten the highpressure fuel injection pump-to-fuel rail fuel tube(s) at the pump first and then at the rail. Tighten the union nuts to 40 N·m (30 ft. lbs.) (Figure 5).
- 6. Remove the shop towels from around fuel tubes that were disconnected.
- 7. **If previously removed:** Install the bolt (7) securing the high pressure pump to rail tube (17). Tighten the bolt to 24 N⋅m (18 ft. lbs.) (Figure 5).
- 8. Install the nut (1) securing the high pressure pump to rail tubes (16 and 17). Tighten the nut to 20 N⋅m (15 ft. lbs.) (Figure 5).
- 9. Proceed to Section **D. Reassembly and Fuel System Priming Procedures**.

<u>C. Tube Replacement - Fuel Rail to Fuel Injector</u>

- 1. Disconnect the exhaust pressure sensor wire harness connector (Figure 6).
- 2. Disconnect the EGR cooler bypass valve wire harness connector (Figure 6).
- 3. Disconnect the crankcase pressure sensor 2 wire harness connector (Figure 6).
- 4. Release the wire harness retainers (Figure 6).
- 5. Disconnect crankcase pressure sensor 1 wire harness connector (Figure 6).
- 6. Disconnect the three Crank Case Ventilation (CCV) hoses from the crank case breather cover and cylinder head cover (Figure 6).



Figure 6 – Electrical Connectors and CCV Hoses

7. Disconnect the fuel pressure sensor wire harness connector (1) (Figure 7).

8. Disconnect both fuel injector harness connectors (Figure 8).



Figure 7 – Fuel Pressure Sensor

9. Position the engine harness to the side to allow clear access to the fuel rail noise silencer.

10. Remove the fuel rail noise silencer (Figure 8).

11. Thoroughly clean any dirt from fuel tubes and fuel tube nuts to minimize exposure to dirt/debris.



Figure 8 – Fuel Injector Harness and Nose Silencer

12. Remove eight fasteners and the crank case breather cover (Figure 9).



Figure 9 – Crank Case Breather Cover

13. Remove the crank case breather element (Figure 10).



Figure 10 – Crank Case Breather Element

14. Remove six bolts and remove the cylinder head cover (Figure 11).



Figure 11 – Cylinder Head Cover

15. Loosen the fuel injector wire harness nuts on the cylinder head cover gasket. Remove the cylinder head cover gasket (Figure 12).



Figure 12 – Cylinder Head Cover Gasket

- 16. Remove the bolts and the rocker housing (Figure 13).
- 17. Place clean shop towels around any fuel tube fittings that will be disconnected. If possible, do not allow fuel to drip down side of engine.

NOTE: Rail-to-cylinder head fuel tubes are marked on the cylinder head side nut with cylinder number identification.

NOTE: Cylinder No. 3 fuel tube (12) is equipped with two vibration isolators (18). Do not remove or change the position of vibration isolators (18) (Figure 14).



Figure 13 – Rocker Housing

CAUTION: When loosening high-pressure tube fittings attached to a separate fitting (5), use a back-up wrench on fitting (5). Do not allow fittings (5) to rotate. Damage to both fuel tube and fitting will result (Figure 14).

18. Loosen the union nuts then carefully remove the suspect fuel tube from engine.

NOTE: Use care not to bend fuel tubes when removing or installing.

CAUTION: Anytime a high-pressure fuel tube is removed from the engine, its fuel connector retaining nut (5) at the cylinder head must first be retorqued to prevent a leak between the high pressure connector and fuel injector inside the cylinder head (Figure 14).

CAUTION: When tightening high-pressure tube fittings attached to a separate fitting (5), use a back-up wrench on fitting (5). Do not allow fittings (5) to rotate. Damage to both fuel tube and fitting will result (Figure 14).



Figure 14 – Fuel Tubes

- 19. Install the new fuel tube to the injector and fuel rail. Tighten the fittings hand tight at both ends of tube (Figure 14).
- 20. Tighten fuel tube nut at the cylinder head to 55 N·m (41 ft. lbs.) (Figure 14).
- 21. Tighten fuel tube nuts at the fuel rail to 45 N·m (33 ft. lbs.) (Figure 14).

NOTE: Ensure proper clearance between each fuel tube after torqueing both the fuel tube nut at the cylinder head and the fuel rail. The fuel tubes should have minimum clearance of 1.25mm between one another.

22. Remove the shop towels around any fuel tube that was replaced.

23. Clean all the gasket sealing surfaces and inspect the rocker housing gasket (3) for damage and replace if necessary (Figure 15).

> NOTE: If the rocker housing gasket (3) has been removed from the groove in the rocker housing (2), a NEW gasket must be installed (Figure 15).



Figure 15 – Rocker Housing Gasket

CAUTION: When installing rocker housing onto cylinder head, do not slide housing from side to side, the gasket could fall out or be damaged.

- 24. Install the rocker housing and tighten the bolts finger tight. Working from center out, tighten bolts to 24 N⋅m (18 ft. lbs.) (Figure 13).
- 25. Inspect the cylinder head cover gasket for tears, or splits. Replace if necessary (Figure 12).
- 26. Install the cylinder head cover gasket on the rocker housing. Tighten the fuel injector wire harness nuts to 1.5 N⋅m (13 in. lbs.) (Figure 12).
- 27. Install the cylinder head cover then install the six bolts fastening the cover. Tighten the bolts to 24 N⋅m (18 ft. lbs.) (Figure 11).
- 28. Install the crank case breather element (Figure 10).
- 29. Install the crank case breather cover and the eight fasteners securing the cover. Tighten the fasteners to 10 N·m (89 in. lbs.) (Figure 9).

- 30. Install the fuel rail noise silencer (Figure 8).
- 31. Connect both fuel injector harness connectors (Figure 8).
- 32. Connect the fuel pressure sensor wire harness connector (1) (Figure 7).
- 33. Connect the three CCV hoses to the cylinder head cover and crank case breather cover (Figure 6).
- 34. Connect crankcase pressure sensor 1 wire harness connector (Figure 6).
- 35. Attach the wire harness retainers (Figure 6).
- 36. Connect the crankcase pressure sensor 2 wire harness connector (Figure 6).
- 37. Connect the EGR cooler bypass valve wire harness connector (Figure 6).
- 38. Connect the exhaust pressure sensor wire harness connector (Figure 6).
- 39. Proceed to Section **D. Reassembly and Fuel System Priming Procedures**.

D. Reassembly and Fuel System Priming Procedures.

- 1. Attach the bulk head connector (Figure 4).
- 2. Install the engine cover (2) and the bolts (1) securing the cover. Tighten the bolts to 10 N⋅m (89 in. lbs.) (Figure 3).
- 3. Install the oil dip stick (3) (Figure 3).
- 4. If the vehicle is equipped with an auxiliary battery, install the clamp (1) to the negative post and tighten to $6 \text{ N} \cdot \text{m}$ (53 in. lbs.) (Figure 2).
- 4. Install the negative battery cable with IBS to the negative post and tighten to 6 N⋅m (53 in. lbs.) (Figure 1).
- 5. Connect the IBS wire harness connector (Figure 1).
- 6. Be sure there is fuel in the fuel tank.
- 7. Turn ignition switch to the RUN position. This will operate fuel transfer pump for a minimum of 30 seconds.
- 8. Turn the ignition switch to the OFF position, and leave it off for at least 5 seconds.

NOTE: A certain amount of air becomes trapped in the fuel system when fuel system components on the supply and/or high-pressure side are serviced or replaced. Fuel system priming is accomplished using the electric fuel transfer (lift) pump.

The fuel transfer (lift) pump is self-priming: When the ignition switch is turned to the run position (without cranking engine), the pump operates for a minimum of 30 second. In cold temperatures, the lift pump operates for up to 35 seconds. Two priming cycles (each with a duration of 30 seconds) must be performed any time the fuel system is serviced

- 9. Turn the ignition switch to the RUN position. This will complete an additional priming cycle and operate the fuel transfer pump for a minimum of 30 seconds.
- 10. Start the engine. If the engine does not start after 25 seconds, turn the ignition switch to the OFF position, and leave it off for at least 5 seconds. Repeat the previous step until the engine starts. When engine does start, allow the engine to idle for a minimum of 30 seconds. The engine may run erratically and be noisy for a few minutes. This is a normal condition.
- 11. Fuel system priming is now completed.

CAUTION: Do not engage the starter motor for more than 30 seconds at a time. Allow two minutes between cranking intervals.

WARNING: The fuel injection pump supplies extremely high fuel pressure to each individual injector through the high-pressure tubes. Fuel under this amount of pressure can penetrate the skin and cause personal injury. Wear safety goggles and adequate protective clothing. Do not loosen fuel fittings while engine is running.

WARNING: Engine may start while cranking starter motor

- 12. Start engine and check for leaks.
- 13. Validation Run Fuel System Leak Test for Diesel ECM Controller Modules (Fuel Pressure Override Test)
- 14. Install a battery charger and verify that the charging rate provides 13.2 to 13.5 volts. Do not allow the charger to time out during the flash process. Set the battery charger timer (if so equipped) to continuous charge.

NOTE: Use an accurate stand-alone voltmeter. The battery charger volt meter may not be sufficiently accurate. If voltage reading is too high, apply an electrical load by activating the park or headlamps and/or HVAC blower motor to lower the voltage.

- 15. Connect the wiTECH MicroPod II to the vehicle Data Link Connector (DLC).
- 16. Place the ignition in the "**RUN**" position.
- 17. Open the wiTECH 2.0 website.
- 18. Enter your "User id" and "Password" and your "Dealer Code", then select "Sign In" at the bottom of the screen. Click "Accept".
- 19. From the "Vehicle Selection" screen, select the appropriate vehicle.
- 20. From the vehicle "**Topology**" screen, select the "**PCM**" icon.
- 21. From the "PCM" screen select the "System Tests" tab.
- 22. From the "System Tests" tab perform the "Fuel Pressure Overide" test.
- 23. Place the ignition in the "**OFF**" position the remove the wiTECH MicroPod II from the vehicle DLC.
- 24. Remove the battery changer.
- 25. Close the hood.
- 26. Complete the Proof of Correction form for California residents.
- 27. Return the vehicle to customer or vehicle inventory.

Complete Proof of Correction Form for California Residents

This recall is subject to the <u>State of California Registration Renewal/Emissions</u> <u>Recall Enforcement Program</u>. Complete a Vehicle Emission Recall Proof of Correction Form (<u>Form No. 81-016-1053</u>) and supply it to vehicle owners residing in the state of California for proof that this recall has been performed when they renew the vehicle registration.

Process Steps to obtain the California Proof of Correction form:

- a. Access the "DealerCONNECT" website.
- b. Select the "Service" tab.
- c. Under the "Publications" heading, select the "ePublishing" link.
- d. Sign in using your **Dealer Code** and **Password**.
- e. Select the "Proof of Correction form".

Completion Reporting and Reimbursement

Claims for vehicles that have been serviced must be submitted on the DealerCONNECT Claim Entry Screen located on the Service tab. Claims paid will be used by FCA to record recall service completions and provide dealer payments.

Use the following labor operation numbers and time allowances:

	Labor Operation <u>Number</u>	Time <u>Allowance</u>
Rocker Housing Removal to Access Fuel Injector Supply Tubes (Related below)	14-V7-61-82	1.7 hours
Fuel Supply Tube, Pump to Rail (Upper Pumping Chamber)	14-V7-61-83	0.8 hours
Fuel Supply Tube, Pump to Rail (Lower Pumping Chamber)	14-V7-61-84	1.0 hours
Related		
Cylinder #1 Fuel Injector Supply Tube	14-V7-61-51	0.1 hours
Cylinder #2 Fuel Injector Supply Tube	14-V7-61-52	0.1 hours
Cylinder #3 Fuel Injector Supply Tube	14-V7-61-53	0.1 hours
Cylinder #4 Fuel Injector Supply Tube	14-V7-61-54	0.1 hours
Cylinder #5 Fuel Injector Supply Tube	14-V7-61-55	0.2 hours
Cylinder #6 Fuel Injector Supply Tube	14-V7-61-56	0.2 hours
Floor Plan Reimbursement	95-95-95-97	Calculate See Below

Floor Plan Reimbursement represents the vehicle's average daily allowance (see table below) multiplied by the number of days the vehicle was in dealer inventory and not available for sale. This reimbursement is limited to the number of days from the date of the stop sale to the date that the remedy was made available. Note: If the vehicle was received by your dealership (KZX date) AFTER the stop sale date, you will use the KZX date instead of the stop sale date. For this Recall, the stop sale was initiated on 07/05/2019 and the remedy was made available on 07/09/2019, therefore, the number of days cannot exceed 4 days.

Completion Reporting and Reimbursement [Continued]

Vehicle	Average Daily Allowance
2019 (DJ) RAM 2500 Pickup	
2019 (D2) RAM 3500 Pickup	
2019 (DD) RAM 3500 Cab Chassis	
2019 (DP) RAM 4500/5500 Cab Chassis	

Add the cost of the recall parts package plus applicable dealer allowance to your claim.

NOTE: See the Warranty Administration Manual, Recall Claim Processing Section, for complete recall claim processing instructions.

Dealer Notification

To view this notification on DealerCONNECT, select "Global Recall System" on the Service tab, then click on the description of this notification.

Owner Notification and Service Scheduling

All involved vehicle owners known to FCA are being notified of the service requirement by first class mail. They are requested to schedule appointments for this service with their dealers. A generic copy of the owner letter is attached.

Vehicle Lists, Global Recall System, VIP and Dealer Follow Up

All involved vehicles have been entered into the DealerCONNECT Global Recall System (GRS) and Vehicle Information Plus (VIP) for dealer inquiry as needed.

GRS provides involved dealers with an <u>updated</u> VIN list of <u>their incomplete</u> vehicles. The owner's name, address and phone number are listed if known. Completed vehicles are removed from GRS within several days of repair claim submission.

To use this system, click on the "Service" tab and then click on "Global Recall System." Your dealer's VIN list for each recall displayed can be sorted by: those vehicles that were unsold at recall launch, those with a phone number, city, zip code, or VIN sequence.

Dealers <u>must</u> perform this repair on all unsold vehicles <u>before</u> retail delivery. Dealers should also use the VIN list to follow up with all owners to schedule appointments for this repair.

Recall VIN lists may contain confidential, restricted owner name and address information that was obtained from the Department of Motor Vehicles of various states. Use of this information is permitted for this recall only and is strictly prohibited from all other use.

Additional Information

If you have any questions or need assistance in completing this action, please contact your Service and Parts District Manager.

Customer Services / Field Operations FCA US LLC