

- Print and install updated I-Sheet into conversion kit. Refer to:

Updated I-Sheet J05807

- Insert reflector kit into each conversion kit.
- Change early part no. to current part no. Refer to Detachables Tour-Pak Luggage Conversion Kits.
- Add back into inventory using current part no.

Required Dealer Action

NOTE

Login to SIP (Service information portal) through Google Chrome to view.

- Retrieve and print recall notice poster from SIP. Click link.

Recall 0629 Notice Poster

- Verify that all early conversion kits have been addressed as per this service bulletin. Refer to Dealer Inventory Instruction.

NOTE

- Apply reflectors in ambient temperatures between 21–38 °C (70–100 °F).
- Reflectors cannot be repositioned after initial installation. Do not remove protective film from adhesive until ready to apply.
- Allow at least 24 h after application before exposing the area to vigorous washing, strong water spray or extreme weather.
- The adhesive bond will increase to maximum strength after about 72 h at normal room temperature.

- See Figure 2. Mark reflector location.
 - Clean the reflector mounting surface with a 50:50 mixture of isopropyl alcohol and water. Allow to dry completely.
 - See Figure 2. Place reflector (2) on rear of saddlebag centered and Distance: 13 mm (0.5 in) below auxiliary tail lamp (1).
 - Mark location with a grease pencil.

NOTE

Once applied, do not shift reflectors.

- Install reflector.
 - Remove the adhesive backing from reflector.
 - Place reflector in marked location.
 - After placing reflector, apply even pressure across entire surface for 15 s.
 - Wait 20 min before touching reflectors.




Figure 2. Reflector Placement

Credit Procedure

Credit procedure: H-Dnet and Talon Warranty Claim System Users

For each vehicle involved in this recall (involvement of the VIN (Vehicle identification number) has been verified on H-Dnet.com), submit a recall claim per Table 2.

Table 2.

ITEM	DATA
Claim Type	SRC
Problem Part Number	53000291A
Quantity	Leave blank
Labor Code ⁽¹⁾	2747
Labor Hours	0.2 h
Customer Concern Code	0629
Condition Code	9981
Replacement Part Number	91500105
Quantity	1

(1) Download may be required

Submit a warranty claim per Table 3 for all kits in dealer stock or kits that have been retailed to a customer but are not registered to the SWR.

NOTE

Do not enter a VIN in the claim.

Table 3.

ITEM	DATA
Claim Type	SNV
Problem Part Number	53000291A
Quantity	Leave blank
Primary Labor Code	Leave blank
Detail Labor Code	8888
Time	0.2 h
Customer Concern Code	0629
Condition Code	9982
Replacement Part Number	91500105
Quantity	1

Credit Procedure: GDP/SAP System Users

For each vehicle involved in this recall (involvement of the VIN has been verified on H-Dnet.com), submit a recall claim per Table 4.

Table 4.

ITEM	DATA
Claim Type	Recall Claim
Fix ID-Found in Recall Number	C
Problem Part Number	53000291A
Customer Concern Code	0629
Condition Code	9981

Submit a warranty claim per Table 5 for all kits in dealer stock or kits that have been retailed to a customer but are not registered to the SWR.

NOTE

VIN is not involved in the recall per H-Dnet.com.

Table 5.

ITEM	DATA
Claim Type	PAM - sold or PAM - stock
Problem Part Number	53000291A
Customer Concern Code	0629
Condition Code	9982
Labor Code	8888
Time	0.2 h
Replacement Part Number	91500105
Quantity	1