

SIB 65 23 19

2021-02-12

#### RECALL 19V-851: DRIVER'S FRONT AIR BAG (NADI) INFLATOR

This Service Information Bulletin (Revision 10) replaces SI B65 23 19 dated October 2020.

What's New (Specific text highlighted):

- Correction & Parts- Standard airbag unit without multifunction controls is now available
- Warranty

Please perform the procedure outlined in this Service Information on all affected vehicles before customer delivery. In the event the customer has already taken delivery of the vehicle, please perform the procedure the next time the vehicle is in the shop.

#### **MODEL**

E-Series	Model Description	Production Date
E46	3 Series Sedan	July 2, 1998 – January 5, 1999

## **AFFECTED VEHICLES**

Vehicles which require this Recall Campaign to be completed will show it as "Open" when checked either in AIR, the "Service Menu" of DCSnet (Dealer Communication System), ISPA Next or Warranty Vehicle Inquiry.

#### **SITUATION**

BMW AG is conducting a Voluntary Safety Recall (effective December 4, 2019) on certain Model Year 1999 BMW 3 Series vehicles that were produced between July 1998 and January 1999. Please see attached Recall Notice and Q&A for further information.

This recall campaign involves vehicles equipped with the single-stage Takata Non Azide (NADI) Driver gas generator/Inflator. There are three separate recalls involving the NADI units.

Recall ID	SIB No.	Recall Description
19V-851	B65 23 19	Driver's Front Air Bag (NADI) Inflator -STOP DRIVE
19V-852	B65 24 19	Driver's Front Air Bag (NADI) Inflator
19V-853	B65 25 19	Driver's Front Air Bag (NADI) Inflator -Spare Parts

Customers potentially affected by the STOP DRIVE recall will be instructed not to drive the vehicle until the repair is completed. The stop drive only pertains to the vehicles identified in this bulletin.

If a customer calls in to schedule a repair, please redirect them to 1-800-805-9230 (9:30 – 6:00 CST Central Standard Time, Monday through Friday) to arrange for towing and to set up an appointment.

The vehicles that are affected by the STOP DRIVE will be towed to BMW centers for repair.

#### OTHER AIR BAG-RELATED FAULTS AND REPAIRS

This Recall applies to an operational driver's front air bag. The issue addressed will not cause an air bag (SRS) malfunction light to illuminate. It will also not prevent the system from deploying in a front-end collision.

However, a recalled vehicle can arrive at your center with an air bag malfunction light illuminated.

It is important to notify the customer that diagnosing other air bag-related system issues may be required and this diagnosis and corresponding repair work, **if needed, is not covered by this Recall.** 

In this case, replacing the driver's front air bag gas generator will not correct the other fault code(s).

#### **CAUSE**

The single-stage Takata Non-Azide (NADI) Driver gas generator, also known as an air bag inflator, may have been produced with an insufficient seal that could allow moisture to enter the gas generator. The gas generator is a separately replaceable part of the air bag module.

#### CORRECTION

The current installed air bag gas generator must be inspected.

The serial number on the installed air bag gas generator must be compared to the serial number list in the procedure section to determine if the gas generator needs to be replaced.


If the vehicle has a Category 1 or Category 2 air bag gas generator installed, then proceed with air bag gas generator replacement.

In the following cases, the gas generator replacement should not be performed. Instead, the complete air bag assembly must be replaced:

- Threaded bolts are damaged
- · Threaded bolts are bent or corroded
- The generator cannot be removed from the air bag without excess force
- If the target tightening torque of the nuts cannot be achieved (5 Nm in a star pattern sequence)
- If there is a gap between the generator & air bag that is not closed up when tightening the nuts
- If there is damage to the air bag cover that may impede deployment of the air bag

If a complete air bag assembly(Sport steering wheel and standard air bag **WITH** multifunction switches) is required but parts are not available, please contact BMW Customer Relations at 1-800-525-7417 for further support.

## **PROCEDURE**




Follow all safety precautions when handling air bags.

Remove Basic Drivers air bag as per


REP 32 34 020 "Removing and installing/replacing airbag unit"

OR

Remove Sports Drivers air bag as per



**REP 32 34 020** "Removing and installing/replacing the airbag unit (sports steering wheel, inserted airbag unit)"



Once the air bag is removed and the wiring is disconnected, turn the air bag over to read the parts label(s) on the gas generator on the back.

**Basic Driver's air bag,** showing the location of the parts label.



**Sport Driver's air bag,** showing the location of the parts label.

Changes start here:

#### Gas generator serial number decoding:

Digits 1-2 = Type of gas generator

Digit 3 = Production Line

Digit 4 = Production year

Digit 5-11\* = Serial #

Copyright ©2021 BMW of North America, Inc.

\*NOTE: The serial number can have 10 or 11 characters. Only the first 10 characters counted from the left are relevant for the check. The 11th digit can be disregarded for the repair covered by this SIB



**EXAMPLE 1:** Gas Generator Parts Label

All BK1H are Category 2



**EXAMPLE 2:** Gas Generator Parts Label

**BKCJ** may fall under two categories:

<b>Up to</b> 059642	Category 1 – Drivers air bag gas generator must be replaced; the vehicle cannot be driven until repaired.
From 059659	Category 2 – Drivers air bag gas generator must be replaced

This example is **105965**2 which is a higher serial number than 059659 so this is **Category 2** 

\*NOTE: The serial number can have 10 or 11 characters. Only the first 10 characters counted from the left are relevant for the check. The 11th digit can be disregarded for the repair covered by this SIB, so ignore the last digit 2



**EXAMPLE 3:** Gas Generator Parts Label

**BK1K** may fall under two categories:

<b>Up to</b> 088984	Category 2 – Drivers air bag gas generator must be replaced
From 088992	Category 3 – Drivers air bag gas generator is OK

This example is 11 digits and **386101**S is above 088992 so this is **Category 3** 

\*NOTE: The serial number can have 10 or 11 characters. Only the first 10 characters counted from the left are relevant for the check. The 11th digit can be disregarded for the repair covered by this SIB, so ignore the letter S



If the serial number is not legible or the driver airbag gas-generator (not type BK) cannot be identified, submit a TSARA case for support. Title the TSARA case **NADI TAKATA RECALL 19V-851**.

#### To see the repair category of your air bag gas generator, refer to the table below.

Descriptions of each category are shown below the table.

Digits 1-3	Digit 4	Digit 5-10	Repair Category
ВКС	Н	ALL	Category 1 – Drivers air bag gas generator must be replaced; the vehicle cannot be driven until repaired.
BKC	J	<b>Up to</b> 059642	Category 1 – Drivers air bag gas generator must be replaced; the vehicle cannot be driven until repaired.
		<b>From</b> 059659	Category 2 – Drivers air bag gas generator must be replaced
BK1	Н	ALL	Category 2 – Drivers air bag gas generator must be replaced
BK1	J	ALL	Category 2 – Drivers air bag gas generator must be replaced
BK1	К	<b>Up to</b> 088984	Category 2 – Drivers air bag gas generator must be replaced
DKI	N.	From 088992	Category 3 – Drivers air bag gas generator is OK
BK1	LMNPQRUV	ALL	Category 3 – Drivers air bag gas generator is OK
BK5	-	ALL	Category 3 – Drivers air bag gas generator is OK
BKV	-	ALL	Category 3 – Drivers air bag gas generator is OK

Category	Part	Defect Code*	Steps
1	Air Bag Gas Generator	Final Repair: 00 32 97 02 00	<ul> <li>The serial number of the checked gas-generator AND the new gas-generator must both be stated on the repair order and in the comments section of the warranty claim.</li> <li>Refer to SI B65 03 20 for details on how to replace a gas generator.</li> <li>See the attached Checklist for gas generator replacement.</li> </ul>
	Complete Air Bag Assembly Needed	Temporary: 32 34 90 03 00	<ul> <li>Parts are not available</li> <li>The serial number of the checked gas-generator must be stated on the repair order and in the comments section of the warranty claim.</li> <li>Contact BMW Customer Relations at 1-800-525-7417 for further support</li> </ul>
Category	Part	Defect Code	Steps

Copyright ©2021 BMW of North America, Inc.

2	Air Bag Gas Generator	Final Repair: 00 32 97 02 00	<ul> <li>The serial number of the checked gas-generator AND the new gas-generator must both be stated on the repair order and in the comments section of the warranty claim.</li> <li>Refer to SI B65 03 20 for details on how to replace a gas generator.</li> <li>See the attached Checklist for gas generator replacement.</li> </ul>
	Complete Air Bag Assembly Needed	Temporary: 32 34 90 03 00	<ul> <li>Parts are not available</li> <li>The serial number of the checked gas-generator must be stated on the repair order and in the comments section of the warranty claim.</li> <li>Contact BMW Customer Relations at 1-800-525-7417 for further support</li> </ul>
Category	Part	Defect Code	Steps
3	No part needed	Final Repair: 00 32 97 02 00	<ul> <li>The air bag is OK and it can be reinstalled.</li> <li>The serial number of the checked gas-generator must be stated on the repair order and in the comments section of the warranty claim.</li> </ul>

Changes end here.

## **PARTS INFORMATION**

Please monitor the Parts Matrix for ordering procedure.

Only use and invoice the part numbers below that apply.

Performing a part number look-up in ETK (EPC) by VIN or model in place of using/invoicing the following part numbers may result with the wrong part numbers being invoiced and installed. This could delay the payment of claim.

Part Number	Description	Quantity
32 30 5 A1B D99	Gas Generator repair kit	1
32 34 5 A1B DB4	Standard air bag unit <b>WITHOUT</b> multifunction switches	1 (if required)
32 34 5 A1B DB5	Standard air bag unit <b>WITH</b> multifunction switches	1 (if required)
32 34 5 A1B DB3 ETA is April	Airbag unit, sports steering wheel. Not available until April	1 (if required)

## **PARTS RETENTION AND RETURN**

Recalled parts that are removed from BMW vehicles cannot be used for resale!

The parts replaced to perform and submit for this Recall repair procedure are the property of BMW NA.

Your center is responsible for the proper identification, storage and documentation of these parts. They must be held in a secure retention area until notification of claim payment is made by BMW NA through DCSnet.

<sup>\*</sup> It is very important to claim on the correct defect code so we know which vehicles still need a part when parts become available.

Upon claim payment and based on the replacement front air bag component part number claimed, a corresponding DCSnet part return tag will be generated with special handling instructions.

 Please DO NOT return these recalled air bag components to the Warranty Parts Return Center (WPRC).

Inflatable air bags are classified as dangerous goods by the Department of Transportation (DOT) and require special preparation, packing and labeling for transport.

Your center is responsible for following all rules and regulations that apply to shipping dangerous goods as described in the attachment.

A shipping procedure has been created for returning the replaced air bag modules directly to Takata. There is also a procedure available for Bulk Shipping 15 or more air bag modules at one time to Takata.

These procedures are contained in the Part Return Program Instructions and Bulk Ship PDF attachments to this bulletin; please read both of them. Effective immediately, please use the following email address when scheduling bulk shipment returns to Takata:

#### Scfieldaction.14305@xpo.com

The parts are to be packaged in the same packaging that the new part arrived in for shipment back to Takata.

The returns pickup schedule has been changed from weekly to every two weeks (bi-weekly).

#### WARRANTY INFORMATION

Reimbursement for this Service Action will be via normal claim entry utilizing the applicable work package information below, and when applicable, the part number listed above that applies.

Plus work	Vehicle is already in the workshop for another repair
Main	The vehicle arrives at your center and this Recall Campaign shows open (No other Main
work	work will be performed/claimed during this workshop visit)

## Category 1 and 2 vehicles - Inspect the air bag and the gas generator is replaced (Recall is CLOSED)-

<b>Defect Code:</b>	0032970200	E46 Driver's air bag (NADI - part I)		
:				
Work Pkg	Labor Operation	Description (Plus work)	Labor Allowance	
# 1	00 68 976	Checking the driver's air bag and replacing the gas generator (category 1 and 2) (Plus work)	7 FRU	
Or:				
# 2	00 68 358	Checking the driver's air bag and replacing the gas generator (category 1 and 2) (Main work)	8 FRU	

Category 3 vehicles - Inspection the air bag ONLY, no replacement is required (Recall is CLOSED)-

Defect Code: 0	032970200	E46 Driver's air bag (NADI - part I)	
:			
		Description (Plus work)	
1	0	wight @2024 DNAN of North Arcoring Inc	ı

Work Pkg	Labor Operation		Labor Allowance
#3	00 68 812	Only checking the driver's air bag, air bag is OK (category 3), no replacement is necessary (Plus work)	3 FRU
Or:			
# 4	00 68 228	Only checking the driver's air bag, air bag is OK (category 3), no replacement is necessary (Main work)	5 FRU

# Category 1 and 2 vehicles – The gas generator repair cannot be performed, future air bag module replacement is required (Recall remains OPEN)-

Defect Code:	3234900300	E46 Driver's airbag NADI - test result	
: Work Pkg	Labor Operation	Description	Labor Allowance
# 5	00 68 810	Check, the necessary gas generator repair cannot be performed, future driver's air bag module replacement required (category 1) (Plus work)	3 FRU
Or:			
# 6	00 68 811	Check, the necessary gas generator repair cannot be performed, replace the driver's air bag module (category 2) (Plus work)	3 FRU
Or:			
#7	00 68 226	Check, the necessary gas generator repair cannot be performed, future driver's air bag module replacement required (category 1) (Main work)	5 FRU
Or:			
#8	00 68 227	Check, the necessary gas generator repair cannot be performed, replace the driver's air bag module (category 2) (Main work)	5 FRU

## Category 1 and 2 vehicles - As applicable below, the air bag module complete is replaced (Recall is CLOSED)-

Defect Code:	0032970200	E46 Driver's air bag (NADI - part I)	
Work Pkg	Labor Operation	Description	Labor Allowance
#9	00 69 559	Replace the driver air bag (module complete, replacement part is available) after abandoning the replacement of the gas generator (category 1 and 2) (Plus work)	3 or 4 FRU, please confirm in AIR
Or:			
# 10	00 69 055	Replace the driver air bag (module complete, replacement part is	5 FRU
	Con	 vright ©2021 BMW of North America Inc	

		available) after abandoning the replacement of the gas generator (category 1 and 2) (Main work)	
Or:			
# 11	00 70 637	Replacing the driver's air bag module (complete, replacement part is available) (category 1 and 2) (Follow-up work after WP # 3 or # 4 was performed and claimed prior/DC 32 34 90 03 00) (Plus work)	
Or:			
# 12	00 70 120	Replacing the driver's air bag module (complete, replacement part is available) (category 1 and 2) (Follow-up work after WP # 3 or # 4 was performed and claimed prior/DC 32 34 90 03 00) (Main work)	

Only one of the flat rate labor operation codes listed above can be used for claim submission/reimbursement purposes. Also, only one Main work flat rate labor operation code can be claimed per workshop visit.

#### **Claim Repair Comments**

Only reference the SIB number and the work package (Pkg) number performed in the RO technician notes and the claim comments (For example: B65 23 19 WP 1), unless otherwise required by State law.

#### Reimbursement of Prior Customer-Pay Repairs (TREAD Act)

With this Technical Campaign, a prior repair reimbursement is not likely. Typically, a customer would have their driver's front air bag module replaced as a result of an accident. In such a case, either an insurance company or the customer themselves paid for the replacement of the above mentioned air bag module in conjunction with the accident repairs. Such cases are not covered by this campaign and are not entitled to reimbursement.

## **QUESTIONS REGARDING THIS BULLETIN**

Technical inquiries	Submit feedback at the top of this bulletin
Warranty inquiries	Submit an IDS ticket to the Warranty Department or use
Warranty inquiries	the chat available in the Warranty Documentation Portal
Parts inquiries	Submit an IDS ticket to the Parts Department

#### **Supporting Materials**

picture as pdf B65 23 19 19V-851 E46 DAB QA 17Apr2020.pdf picture as pdf B652319 Parts Return Program Instructions.pdf picture as pdf B652319 Parts Bulk Ship Return.pdf picture as pdf B652319 REP.pdf picture as pdf B652319 Recall Notice.pdf

Attachment to B652319 October 2020

## **SAFETY RECALL NOTICE**

To: All Center Operators, Sales Managers, Service Manager, Parts Manager and Warranty Processor

RE: Recall 19V-851: Driver's Front Air Bag (NADI) Inflator - B65 23 19

BMW of North America, LLC is conducting a Voluntary Safety Recall (effective December 4, 2019) on certain Model Year 1999 BMW 3 Series vehicles that were produced between July 1998 and January 1999.

Customers potentially affected by this recall will be instructed not to drive the vehicle until the repair is completed. The stop drive only pertains to the vehicles identified in bulletin B65 23 19.

Please be reminded that it is a violation of federal law (The Safety Act) for you to sell, lease or deliver any new motor vehicle covered by this notification until the recall repair has been performed. This means that centers may not legally deliver new motor vehicles to consumers until they are fixed or use/sell replacement equipment/parts subject to this recall. Note also that substantial civil penalties apply to violations of the Safety Act.

Also, you should not sell, lease or deliver any Certified Pre-Owned or used vehicles subject to a safety recall until the repair is completed.

Please follow any special instructions that we provide to you for the return or disposition of recall parts.

We appreciate all your assistance with this Recall.

Attachment B65 23 19 October 2020

Replacing the gas generator for the driver's airbag »

#### WARNING

Pyrotechnic components.

Danger! Immobilization period-threatening injuries!

- All work on pyrotechnic parts may be carried out by technically experienced and appropriately trained personnel only.
- Replace any damaged part or ones that have been dropped.
- For additional information see: 72 00 Safety regulations on handling components with gas generators.

## RISK OF DAMAGE



Electrostatic discharge.

Damage to or destruction of electrical components.

- Leave electrical components in original packaging until just before they are installed. Use the original packaging only for any return shipments. Always package removed components straight away.
- Read and comply with user information on using the associated special tool 12 7 060.
- Only tap the housings of electrical components. Do not tap pins or multi-pin connectors directly.
- Wear electrically conductive clothing and antistatic shoes (with ESD symbol).
- For additional information see: 61 35 ... Notes on ESD (electrostatic discharge) protection
  - 61 35 ... Notes on ESD protection (Electro Static Discharge)

## i TECHNICAL INFORMATION

The work surface must be clean, even, skid-proof and tilt-proof.

## □ NOTE

Only one vehicle may be processed at a time.

Execute repair without interruption.

Interruptions of any kind are not permitted (such as by telephone calls).

The person performing the procedure must not be distracted.

## □ NOTE

The person performing the repair must have a second person available for the entire duration of the repair.

The second person has the following tasks:

Fill in the checklist.


Attach the component(s).

Inspection of work performed.

## Preliminary work

## Preparing the workplace

Workplace for replacement of the gas generator (E46)



- 1 Collection container for disposal of the nuts
- 2 Tools required for the exchange
- 3 Antistatic mat
- 4 New, packaged gas generator
- 5 Scratch-resistant cotton underlay

• Print out the checklist.

## 3234

- Prepare the antistatic mat and cotton pad:
- Have the following tools ready:

Felt pen

Adhesive tape (width min. 25 mm)

Wedge 0 490 539 (00 9 322)

1/4" reversible ratchet
1/4" reversible ratchet



1/4" reversible ratchet with Extension 1/4 inch Extension 1/4 inch



Extension 1/4 inch and Socket wrench for hexagon Socket wrench for hexagon



Socket wrench for hexagon 8 mm

Torque wrench with Socket wrench for hexagon Socket wrench for hexagon



Socket wrench for hexagon 8 mm

## Tightening torques

Gas generator to airbag unit

Nut

Renew nut.


Tightening torque

5Nm

## Main Works


## Replacing the gas generator of airbag unit (standard steering wheel) Prerequisite


Airbag unit is removed.




- Place the airbag unit (1) turned around as shown.
- Note the serial number (2) of the airbag unit (1) on the work order.

• Glue the connector (1) from the previous gas generator of the airbag unit (2) with the adhesive tape so that the contacts cannot be touched.






- Mark a cross (1) with the felt pen to avoid a mix-up with the new gas generator.
- Mark all the four nuts (2) with the felt pen to avoid a mix-up with the new nuts.



• Release both the connectors (1) on the airbag unit (2).

- Auxiliary person: Hold the airbag unit (1).
- Unscrew all the nuts (2) in any order and dispose of immediately in the collection container provided (3).
- Do not reuse the nuts (2).




► Preparing the new gas generator

## RISK OF DAMAGE

Damage to the gas generator.

A damaged gas generator due to, for example, a fall, can lead to malfunctions and must be replaced.

- Handle gas generator carefully.
- Do not use the gas generator after a fall, but replace it.




- Unpack the new nuts (1), reinforcement plate (2), new gas generator (3), cable (4) and sticker (5) and place it as shown.
- Make sure that the groove (arrow) of the reinforcement plate (2) is positioned correctly.
- USA only:

Dispose of the hazard sticker (6).

 Clip in the cable (1) as shown in the new gas generator (2).


The cable (1) and the groove (arrow) of the new gas generator (2) point upwards.

The connector is encoded against incorrect assembly.






RB32 01044



 Remove the previous gas generator (1) and subsequently directly place the new gas generator (2).


The cable and the groove of the new gas generator (2) point upwards.




 Insert the previous gas generator (1) in the packaging (2).

- Position the reinforcement plate (1) over the new gas generator (2).
- Make sure that the groove (arrow) of the reinforcement plate (1) is positioned correctly.

The groove (arrow) points downwards to the left.





## • Auxiliary person:

Hold the airbag unit (6).

Check whether the nuts have been tightened correctly by the executing person.

The noise must be audible while retorquing.

#### • Executing person:

Lightly screw on the new gas generator (5) with the new nuts in the screwing sequence (1) to (4).

Tighten the nuts in the screwing sequence (1) to (4).

Retorque the nuts in screwing sequence (1) to (4).

## Tightening torques

## Gas generator to airbag unit

Nut

Renew nut.

Tightening torque

5Nm




Visually inspect the gap (3) between the new gas generator (1), reinforcement plate (2) and airbag unit (4) on all four sides (5).

#### Auxiliary person:

Visually inspect the gap (3) between the new gas generator (1), reinforcement plate (2) and airbag unit (4) on all four sides (5).


• If the gap (3) is not OK:




#### AIR - Technical documents

Release the screw connection and tighten again as described in the previous step. If the gap is still not OK, then cancel the repair. Install the new airbag unit in this case.

• Connect both the connectors (1) with the airbag unit (2).



- Glue on the first sticker on the airbag unit (1) with the new number on the position (2).
- Glue on the second sticker on the work order.



 Install the airbag unit and horn switch and if necessary, check the multifunction button for operability.

## 3234020

• All except USA:

Affix the hazard sticker (1) externally on the packaging (2).

USA:

Do not affix any hazard sticker (3) externally on the packaging (2).

Attachment to B652319 October 2020

#### Driver's Front Air Bag Inflator (NADI) Model Year 1999 BMW 3 Series Safety Recall 19V-851 Date Issued: 4/17/2019

#### Q1. Which models are included in this Safety Recall Campaign?

Certain Model Year 1999 BMW 3 Series Sedans (323i, 328i) (E46), produced from July 1998 through January 1999 are potentially affected.

#### Q2. Which inflator is affected?

This recall campaign involves vehicles equipped with the single-stage Takata Non Azide Driver Inflator (NADI).

#### Q3. What is the specific concern?

A population of NADI inflators manufactured prior to March 15, 1999 may have been produced with an insufficient seal which could allow moisture to enter the inflator.

#### Q4. What can happen as a result of this issue?

In a crash where the driver air bag deploys, it may not deploy with sufficient restraint capability which could increase the risk of injury. It is also possible that the air bag housing may explode and could cause metal fragments to pass through the air bag cushion material, which may result in injury or death to the driver and/or other vehicle occupants.

#### Q5. Can I continue to drive my vehicle?

No. Potentially affected vehicles are not to be driven. If you are not the only driver of this vehicle, please advise all other drivers of this important information. Please call 1-800-805-9230 so we can help arrange for the vehicle to be repaired.

#### Q6. Why are other BMW models not included?

Other vehicles have driver front air bags that were produced with different inflators.

#### Q7. What is the fix?

The inflator will be inspected and if necessary, replaced.

#### Q8. How will I be notified of this recall?

Initial letters were sent out in December 2019 via First Class mail, advising customers of this recall. Follow-up letters asking vehicle owners to schedule their vehicle for repair will start to be mailed in May 2020. To ensure BMW of North America, LLC has your most recent contact and vehicle information, please register your vehicle at <a href="http://www.bmwusa.com/myBMW">http://www.bmwusa.com/myBMW</a>. Registration is free, and will give you access to factory initiated campaigns and other information specific to your BMW vehicle.

#### Q9. Do I have to wait for my letter in order to have my vehicle repaired?

No. Please call 1-800-805-9230 so we can help arrange for the vehicle to be repaired.

#### Q10. Is it possible to find out whether the problem exists in my car?

No. There is no way to detect if your BMW might have an air bag inflator potentially at risk of rupturing upon deployment in an accident.

#### Q11. How did BMW become aware of this issue?

BMW became aware of this issue through its quality control procedures.

Attachment to B652319 October 2020

## Driver's Front Air Bag Inflator (NADI) Model Year 1999 BMW 3 Series Safety Recall 19V-851

Date Issued: 4/17/2019

#### Q12. I did not receive a letter from BMW regarding my vehicle. How can I find out if my BMW is included in this

You can enter your vehicle identification number (VIN) at <a href="https://www.bmwusa.com/recall">www.bmwusa.com/recall</a> and download a sample owner notification letter and Q&A if your VIN is affected. Make sure to update your contact information by registering at http://www.bmwusa.com/myBMW.

#### Q13. What if I am not the current owner of this vehicle?

If you changed your address or sold the vehicle, you can let us know by visiting http://www.bmwusa.com/mybmw or by contacting BMW Customer Relations.

#### Q14. Am I eligible for reimbursement under the TREAD Act if I previously replaced my driver's front air bag module?

In this particular recall, reimbursement is likely not applicable, as you would typically have replaced your driver front air bag module as a result of an accident. In that situation, most likely your insurance company paid for the repair. However, in the very unusual (unlikely) scenario that you previously paid to replace the front air bag module "out-ofpocket" upon learning of this possible defect, you may be eligible for reimbursement. Additional information is provided when BMW mails the letter asking you to make an appointment with an authorized BMW center.

## **BMW / MINI BULK SHIPMENT PACKAGE REFERENCE GUIDE**

NOTE: The information outlined in this document pertains to dealers within the Contiguous 48 States.

Dealers in Puerto Rico, the Hawaiian Islands, and Alaska **CANNOT** follow the shipping instructions outlined in this document; they **MUST** contact the following Takata USA representative(s) directly, **once a week**, for shipping instructions:

- Dealers in Puerto Rico, please contact: <u>Juan.Armstrong@craneww.com</u>
- Dealers in the Hawaiian Islands, please contact: Becky.Argyropoulos@craneww.com
  - Please make sure to include the required completed Hawaiian Hazardous Materials Shipping Certificate.
- Dealers in Alaska, please contact: SCTakataRestraints\_International@xpo.com
  - Important: please be aware that there is an underscore (\_) in the above Alaska email address, between the words "Restraints" and "International".
  - Or call the Alaskan Representative; Armando Gonzales at 210-250-5039.

#### 1. Contact Takata:

- Dealers must contact Takata/XPO Every Other week to schedule BULK and SINGLE recall airbag component shipments.
  - o **Email:** <u>SCFieldAction.14305@xpo.com</u>
  - o Phone: 210-250-5079
- Takata/XPO will select the return type (bulk or single) based on the shipping quantities (LTL or FedEx PRP), and will supply the dealer with the proper shipping documentation.
  - o If Takata instructs you to return the recall airbag components as a **BULK SHIPMENT**, please follow the instructions outlined below.
  - o If Takata instructs you to return the recall airbag components as a **SINGLE SHIPMENT**, please follow the instructions provided by Takata.

#### 2. Stacking:

Place the recall airbag components neatly on a pallet, and securely shrink-wrap them to the pallet.

**Note:** The total height of the pallet and boxes cannot exceed 60 inches.



#### 3. Labeling:

Securely attach the following labels on each side of the shrink-wrapped pallet.

- o Class 9 Label
- UN3268 Safety Device \*
- OVERPACK USED \*

\*You can print these labels on letter size white paper, using Microsoft Word.



#### 4. Questions/Concerns:

For any other questions or concerns, please contact the WPRC: AirbagReturns@bmwna.com

**Defect Code:** 00 32 97 02 00

Safety Device Return Procedure for Airbag Recall

# \*\*ATTENTION\*\*

**DO NOT** USE THE "1.4 LABEL" **AND DO NOT** FOLLOW ANY INSTRUCTIONS FOUND INSIDE THE REPLACEMENT AIRBAG MODULE'S BOX.

DISREGARD THOSE INSTRUCTIONS AND DO NOT RELABEL THE ORIGINAL BOX THAT WILL NOW BE USED FOR RETURNING THE RECALLED AIRBAG.

#### **IMPORTANT**

- As the shipper, your center is responsible for proper packaging and documentation completion.
- The person packaging the airbag(s) must have received the Hazardous Material training per 49CFR 172.702. Those training records must be on file at your center.
- The U.S. Department of Transportation ("DOT") will impose substantial fines and/or penalties on the shipper if the packaging, labeling, or documentation is not properly prepared and the customer's (center) copy of the OP 900PRP form is not kept on file for a minimum of two (2) years.

#### CAMPAIGN DOF - CONTIGUOUS 48 STATE FEDEX GROUND SHIPMENT PREPARATION

As the shipper, you are responsible for proper packing and document completion. The person packaging the module must have received hazardous material training per 49CFR 172.702, and the training records must be on file at your dealership. The U.S. Department of Transportation will impose substantial fines and/or penalties on the shipper if the packaging, labeling, or documentation is not properly prepared and Customer Copy of OP 900PRP form is not kept on file for a minimum of 2 years.

**IMPORTANT:** Do not deploy the safety device. The person packing the used safety device must read and follow the provided instructions.

 Dealers must contact Takata/XPO Every Other Week to schedule BULK and SINGLE recall airbag component shipments. Takata/XPO will select the return type (bulk or single) based on the shipping quantities (LTL or FedEx PRP), and will supply the dealer with the proper shipping documentation.

Email: scfieldaction.14305@xpo.com

Phone: 210-250-5079

**NOTE:** Dealers in Puerto Rico, the Hawaiian Islands, and Alaska **CANNOT** follow the shipping instructions outlined in this document; they **MUST** contact the following Takata USA representative(s) directly, **Every Other Week**, for shipping instructions:

- Dealers in Puerto Rico, please contact: <u>Juan.Armstrong@craneww.com</u>
- Dealers in the Hawaiian Islands, please contact: Becky.Argyropoulos@craneww.com
  - Please make sure to include the required completed Hawaiian Hazardous Materials Shipping Certificate.
- Dealers in Alaska, please contact: SCTakataRestraints\_International@xpo.com
  - Important: please be aware that there is an underscore (\_) in the above Alaska email address, between the words "Restraints" and "International".
  - Or call the Alaskan Representative; Armando Gonzales at 210-250-5039

For any other questions or concerns, please contact the WPRC: AirbagReturns@bmwna.com